

# Volkswagen VEHICLE DIAGNOSTIC REPORT

## Vehicle Information

--/Volkswagen/AW/C1 - T-Cross 2019 >/--  
VIN: AAVZZZAWZKU102006

Odometer Reading: 124854km  
License Plate: JF35SXGP

## Customer Information

Name: MFC Dekra Nedbank Auction House

Tel: 0861033572

## Device information

Scanner: MaxiSys MS906 BT  
Version: V19.50

Serial Number: VB8GJCC01509  
Repair Order Number: --

## System Scanned( 9 )

System	Status/DTC
01 - Engine Control Module 1	21
03 - Brakes 1	3
08 - Air Conditioning	2
09 - Electronic central electric	8
15 - Airbag	2
17 - Instrument cluster	3
19 - Gateway	2
44 - Power Steering	3
5F - Information electronics 1	4

## DTC ( 48 )

### 01 - Engine Control Module 1 ( 21 DTCs )

DTC	Description	Status
P227900	Intake air system leakage	Passive/Sporadic
P051200	Starter Request Circuit	Passive/Sporadic
P06E900	Engine Starter Performance	Active/static
P06EF00	Engine Restart Performance	Passive/Sporadic
P253200	Ignition Switch Run Position Circuit High	Passive/Sporadic
U041500	Invalid data received from ABS control unit	Passive/Sporadic
P105700	Bank 1, camshaft adjustment, exhaust Open circuit	Passive/Sporadic

P142900	Brake vacuum pump activation Open circuit	Passive/Sporadic
P001000	'A' Camshaft Position Actuator Circuit/Open (Bank1)	Passive/Sporadic
P008700	Fuel rail/system pressure - too low	Passive/Sporadic
P030000	Random/multiple cylinder Misfire detected	Passive/Sporadic
P030100	Cylinder 1 Misfire detected	Passive/Sporadic
P030200	Cylinder 2 Misfire detected	Passive/Sporadic
P030300	Cylinder 3 Misfire detected	Passive/Sporadic
P130A00	Cylinder suppression	Passive/Sporadic
P068A00	ECM/PCM Power Relay De-Energized Performance - Too Early	Passive/Sporadic
P109300	Incorrect Fuel Composition	Passive/Sporadic
P023800	Turbocharger boost sensor (A) circuit High input	Passive/Sporadic
P125000	Fuel level too low	Passive/Sporadic
P011300	Intake air temperature sensor 1 (bank 1) Circuit high	Passive/Sporadic
P044400	Evaporative Emission (EVAP) system purge control valve A circuit open	Passive/Sporadic

### 03 - Brakes 1 ( 3 DTCs )

DTC	Description	Status
C1146F2	TPMS EEPROM fault	Active/static
B13BCF2	Multiple collision brake No function	Passive/Sporadic
C106A16	ABS valves voltage supply Voltage too low	Passive/Sporadic

### 08 - Air Conditioning ( 2 DTCs )

DTC	Description	Status
B109211	Recirculation flap motor Circuit short to ground	Passive/Sporadic
B10F000	Function restriction caused by compressor shut-off by engine	Passive/Sporadic

### 09 - Electronic central electric ( 8 DTCs )

DTC	Description	Status
B11E815	Left front turn signal bulb Open circuit/short circuit to B+	Passive/Sporadic
B11EA15	Right front turn signal bulb Open circuit/short circuit to B+	Passive/Sporadic
B121715	Left low beam headlamp bulb Circuit open or short to positive	Passive/Sporadic
B121815	Right low beam headlamp bulb Circuit open or short to positive	Passive/Sporadic
U101100	Supply voltage Voltage too low	Passive/Sporadic
B133029	Anti-theft alarm system sensor Range/performance	Passive/Sporadic
B131DF5	Sirens/alarm horn for anti-theft warning system Voltage supply below lower limit	Passive/Sporadic
U112100	Data bus message missing	Passive/Sporadic

**15 - Airbag ( 2 DTCs )**

DTC	Description	Status
B13BCF2	Multiple collision brake No function	Passive/Sporadic
U101100	Supply voltage Voltage too low	Passive/Sporadic

**17 - Instrument cluster ( 3 DTCs )**

DTC	Description	Status
U101100	Supply voltage Voltage too low	Passive/Sporadic
B104B31	Key No signal	Passive/Sporadic
B104C29	Key Range/performance	Passive/Sporadic

**19 - Gateway ( 2 DTCs )**

DTC	Description	Status
U101100	Supply voltage Voltage too low	Passive/Sporadic
B1802F1	NV-Energy management Alarm triggered	Passive/Sporadic

**44 - Power Steering ( 3 DTCs )**

DTC	Description	Status
U140000	Function restriction Caused by low voltage	Passive/Sporadic

C113E00	Software error detected	Passive/Sporadic
B200FF0	Internal malfunction	Passive/Sporadic

5F - Information electronics 1 ( 4 DTCs )

DTC	Description	Status
U140000	Function restriction Caused by low voltage	Passive/Sporadic
B2008F0	Function restriction Caused by overtemperature protection	Passive/Sporadic
U111100	Function restriction caused by missing message	Passive/Sporadic
U11B800	Interface for external media No communication	Passive/Sporadic

Technician Notes  
2016379379

Customer name: \_\_\_\_\_

Technician: \_\_\_\_\_

Date: \_\_\_\_\_

Note:Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.