



Shop Name: Dekra MFC Auction House  
Tel: --  
Email: --  
Address: MFC AUCTION HOUSE  
M57 PRETORIA ROAD  
KEMPTON PARK

Report ID: MAXIA20250611122206  
Test Time: 2025-06-11 12:22:06  
Technician: Andrick

# GreatWall VEHICLE DIAGNOSTIC REPORT

## Vehicle Information

--/GreatWall/Poer/P-Series/Cannon/Ute/Poer Ruman and  
Sucan/2019-2022/--  
VIN: LGWCBF198NJ630882

Odometer Reading: 93785  
  
License Plate: KY40KMGP

## Customer Information

Name: Dekra MFC AUCTION HOUSE


















Tel: 0861033572

## Device information

Scanner: MaxiSys MS906 BT  
Version: V11.00

Serial Number: VB8GJCC01514  
Repair Order Number: --

## System Scanned( 16 )

System	Status/DTC
ECM (Engine Control Module)-ECM (Engine Control Module) - 4D20M	 1
A/T (Automatic Transmission)	 1
ESP (Electronic Stability Program)	 1
SRS (Supplemental Restraint System)	 0
BCM (Body Control Module)	 0
ICM/IP (Instrument Cluster Module/Instrument Pannel)-Yazaki instrument (3.5)	 2
TPMS (Tire Pressure Monitoring System)	 12
A/C (Air Conditioning)	 0
CSA (Combination Switch Assembly) - with Steering Angle Sensor Calibration Function	 2
PEPS (Passive Start System)	 4
SBWM (Shift-By-Wire Module)	 0
HUT (Multimedia Player Assembly)	  5
GW (Gateway)	 1
EPS (Electric Power Steering)	 0
ESCL (Electronic Steering Column Lock)	 1
IMMO (Immobilizer)	 4



## DTC ( 34 )

### ECM (Engine Control Module)-ECM (Engine Control Module) - 4D20M ( 1 DTC )

DTC	Description	Status
P012400	Accelerator Pedal Position (APP) sensor signal 1 and 2 inconsistent	History DTC

### A/T (Automatic Transmission) ( 1 DTC )

DTC	Description	Status
U016487	Lost communication with A/C	History DTC

### ESP (Electronic Stability Program) ( 1 DTC )

DTC	Description	Status
U016487	A/C signal timeout	History DTC

### ICM/IP (Instrument Cluster Module/Instrument Pannel)-Yazaki instrument (3.5) ( 2 DTCs )

DTC	Description	Status
U014087	Lost communication with BCM	History DTC
U012787	Lost communication with TPMS	History DTC

### TPMS (Tire Pressure Monitoring System) ( 12 DTCs )

DTC	Description	Status
C008304	Left rear sensor lost	Current DTC
C007702	Right front tire low pressure warning	Current DTC
C007703	Right rear tire low pressure warning	Current DTC
U000188	CAN Bus off Failure	Current DTC
U016487	Lost communication with AC (AC-FCP)	History DTC
C008351	Left front sensor ID not configured	History DTC
C008352	Right front sensor ID not configured	History DTC
C008353	Right rear sensor ID not configured	History DTC
C008354	Left rear sensor ID not configured	History DTC
C008302	Right front sensor lost	History DTC
C007701	Left front tire low pressure warning	History DTC
C007704	Left rear tire low pressure warning	History DTC

### CSA (Combination Switch Assembly) - with Steering Angle Sensor Calibration Function ( 2 DTCs )

DTC	Description	Status
U168287	BCM missing message	History DTC
U100287	Passive Entry Passive Start (PEPS) node lost	History DTC

### PEPS (Passive Start System) ( 4 DTCs )

DTC	Description	Status
-----	-------------	--------

B185100	Ignition key battery low	Current DTC
U014087	Lost communication with BCM unit	History DTC
U025487	Lost communication with ESCL	History DTC
B182700	Immobilizer system authentication failed	History DTC

#### HUT (Multimedia Player Assembly) ( 5 DTCs )

DTC	Description	Status
U110116	Communication voltage too low	History DTC
U015587	Lost communication with instrument panel	History DTC
U014687	Lost communication with GW	History DTC
U024387	Lost communication with PAS(APA)	History DTC
U016487	Lost communication with AC (AC-FCP)	History DTC

#### GW (Gateway) ( 1 DTC )

DTC	Description	Status
U016487	Lost communication with AC (AC-FCP)	History DTC

#### ESCL (Electronic Steering Column Lock) ( 1 DTC )

DTC	Description	Status
U100287	Lost communication with Passive Entry Passive Start (PEPS)	History DTC

#### IMMO (Immobilizer) ( 4 DTCs )

DTC	Description	Status
B185100	Ignition key battery low	Current DTC
U014087	Lost communication with BCM unit	History DTC
U025487	Lost communication with electronic steering column lock	History DTC
B182700	Immobilizer system authentication failed	History DTC

#### Technician Notes

2016909727

Customer name: \_\_\_\_\_

Technician: \_\_\_\_\_

Date: \_\_\_\_\_

Note: Please save a copy of this report for your records.