Nedbook MFC **Auction House**A division of **15 MEDBANK**

Shop Name: Dekra MFC Auction House

Tel: --Email: --

Address: MFC AUCTION HOUSE

M57 PRETORIA ROAD KEMPTON PARK Report ID: MAXIA20250523120454 Test Time: 2025-05-23 12:04:54

Technician: Werner

Mercedes-Benz VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Mercedes-Benz/205.076 - C 180 Sedan / C 200 Sedan/--

VIN: WDD2050762R533972

Odometer Reading: 132170 License Plate: FRM352L

Customer Information

Name: Dekra MFC AUCTION HOUSE

Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT

Version: V19.09

Serial Number: VB8GJCC01514

Repair Order Number: --

🔀 System Scanned(39) System Status/DTC ECM(Engine Control Unit) 8 TCM(Transmission Control Unit) **2** 0 ESP(Electronically controlled vehicle stability braking **Q** 3 system control unit) SRS(Supplemental Restraint System Control Unit) **O 0** KI(Instrument Cluster) TPM(Tire Pressure Monitor Control Unit) **APAS** PTS(Parking System) **3** 1 SAMF(Front SAM signal acquisition control unit) LIN:BSN(Battery Sensor) **2** 0 LIN:FSW(Wiper Motor) LIN:VCS(Rain/sunlight sensor) **2** 0 SAMR(Rear SAM signal acquisition control unit) **2** 0 EZS(Electronic Ignition Lock Control Unit) **Q** 2 ES(Electric Power Steering) KLA(Air Conditioner Control Unit) **2** 0 PTCU(Drivetrain Control Unit) **2** 0 **HU(Head Unit Control Unit) 3** KG(Keyless Go Control Unit) **2** 0

MaxiSys MS906 BT

/Mercedes-Benz/205.076 - C 180 Sedan / C 200 Sedan	Test Time: 2025-05-23 12:04:54	Report ID: MAXIA20250523120454
SW-SW-R(Right Headlamp Control Unit)	ADAS	② 0
SW-SW-L(Left Headlamp Control Unit)	ADAS	Q 1
LRE(Steering Wheel Electronics)		② 0
ABA(Collision Prevention Assist)	ADAS	Q 1
DMFL(Left Front Door Control Unit)		3
DMFR(Right Front Door Control Unit)		Q 2
DMRR(Right Rear Door Control Unit)		Q 2
DMRL(Left Rear Door Control Unit)		Q 2
ZBE(Head Unit Display)		Q 1
LIN:OBF(Upper Control Panel)		② 0
LIN:UBF(Lower Control Panel)		② 0
LIN:UBF-S(Head Unit Audio Operation Swit	ch)	Q 1
LIN:UBFR(Head Unit Controller Right Button	۱)	② 0
ZAN(Center Display Control Unit)		② 0
MRM(Steering Column Control Unit)		② 0
MFK(Multifunction Camera)	APAS	② 0
FSCU(Fuel Pump Control Unit)		② 0
DTA(Telematics Service Control Unit)		Q 1
DBE(Sunroof Control Unit)		② 0
LIN:AISP_2(Interior mirror)		② 0
LIN:AS_2(Alarm Siren)		② 0

TO (36)

ECM(Engine Control Unit) (8 DTCs)

DTC	Description	Status
P012B28	The pressure sensor upstream of the turbocharger has a malfunction. The signal offset is outside the permissible range.	Stored
P012D12	The pressure sensor upstream of the turbocharger has a short circuit to positive. There is a short circuit to positive.	Stored

www.autel.com MaxiSys MS906 BT Page 2

/Mercedes-Benz, 200 Sedan	/205.076 - C 180 Sedan / C Test Time: 2025-05-23 12:04:54	Report ID: MAXIA20250523120454
P012D22	The pressure sensor upstream of the turbocharger has a short circuit to positive. The signal amplitude is greater than the maximum amplitude.	Stored
P056200	The on-board power supply voltage is too low.	Stored
P029921	The boost pressure of turbocharger 1 is too low. The signal amplitude is less than the minimum amplitude.	Stored
P26CE7A	The rpm of the coolant pump is too high. Leakage or a defective seal was detected.	Active
P2B8500	The rpm of the coolant pump is too low.	Active and stored
P021700	The coolant temperature of the engine is too high.	Active
ESP(Electronic	eally controlled vehicle stability braking system control unit) (3 DTC	s)
DTC	Description	Status
B23D1E3	The brake calipers have a malfunction.	Stored(Event codes)
B23D1E2	The brake calipers have a malfunction.	Stored(Event codes)
U11C300	There is a communication fault due to a short-term undervoltage.	Stored(Event codes)
PTS(Parking S	ystem) (1 DTC)	
DTC	Description	Status
B223209	Component fault - PARKTRONIC fault	Active and stored
SAMF(Front SA	AM signal acquisition control unit) (4 DTCs)	
DTC	Description	Status
P060A05	The monitoring function in the control unit has a malfunction. There is a programming fault.	Stored
P25567B	The sensor 'Coolant level' has an electrical fault. The fluid level is too low.	Active and stored(Event codes)
B181E64	The sensor for the engine hood has a malfunction. There is an implausible signal.	Stored
B1F4500	The starter battery has excessive resistance.	Stored
EZS(Electronic	Ignition Lock Control Unit) (2 DTCs)	
DTC	Description	Status
B210D00	The power supply is too low.	Stored(Event codes)
B21DC01	The buffer battery of the electronic ignition lock has a malfunction. There is a general electrical fault.	Stored
ES(Electric Pov	wer Steering) (1 DTC)	
DTC	Description	Status
B210F00	Input 'Circuit 30' has a malfunction.	Stored(Event codes)

Page 3 www.autel.com MaxiSys MS906 BT

/Margadas Da	/20E 076	Deport ID. MAVIAGOSSOS 00100
/Mercedes-Benz/ 200 Sedan	/205.076 - C 180 Sedan / C Test Time: 2025-05-23 12:04:54	Report ID: MAXIA202505231204
HU(Head Unit	Control Unit) (3 DTCs)	
DTC	Description	Status
B15A100	Login to the server has failed.	Stored(Event codes)
B21A100	An internal control unit reset was performed.	Stored(Event codes)
B159F00	The Internet connection could not be established due to a problem with the network provider.	Stored(Event codes)
SW-SW-L(Left	Headlamp Control Unit) (1 DTC)	
DTC	Description	Status
U014100	Communication with the front signal acquisition and actuation module has a malfunction.	Stored(Event codes)
ABA(Collision I	Prevention Assist) (1 DTC)	
DTC	Description	Status
B210A00	The power supply in the system is too low.	Stored(Event codes)
DMFL(Left Fro	nt Door Control Unit) (3 DTCs)	
DTC	Description	Status
B173D15	The output for the turn signal lamp in the outside mirror has a malfunction. There is a short circuit to positive or an open circuit.	Active and stored
B210A00	The power supply in the system is too low.	Stored(Event codes)
B210C16	The power supply is outside the valid range. The limit value for electrical voltage has not been attained.	Stored(Event codes)
DMFR(Right Fr	ont Door Control Unit) (2 DTCs)	
DTC	Description	Status
B210A00	The power supply in the system is too low.	Stored(Event codes)
B210C16	The power supply is outside the valid range. The limit value for electrical voltage has not been attained.	Stored(Event codes)
DMRR(Right Re	ear Door Control Unit) (2 DTCs)	
DTC	Description	Status
B210A00	The power supply in the system is too low.	Stored(Event codes)
B210C16	The power supply is outside the valid range. The limit value for electrical voltage has not been attained.	Stored(Event codes)
DMRL(Left Rea	ar Door Control Unit) (2 DTCs)	
DTC	Description	Status
B210A00	The power supply in the system is too low.	Stored(Event codes)
B210C16	The power supply is outside the valid range. The limit value for electrical voltage has not been attained.	Stored(Event codes)

ZBE(Head Unit Display) (1 DTC)

Page 4 www.autel.com MaxiSys MS906 BT

/Mercedes-Benz 200 Sedan	/205.076 - C 180 Sedan / C Test Time: 2025-05-23 12:04:54	Report ID: MAXIA20250523120454
DTC	Description	Status
B15062A	The Audio/COMAND controller has a malfunction. There is no signal change.	Stored
LIN:UBF-S(Hea	ad Unit Audio Operation Switch) (1 DTC)	
DTC	Description	Status
B15062A	The Audio/COMAND controller has a malfunction. There is no signal change.	Stored
DTA(Telematic	cs Service Control Unit) (1 DTC)	
DTC	Description	Status
B129C00	The control unit for telematics services has a malfunction.	Stored
Technician N 2016888439	otes	
	Customer name:	
	Technician:	

Note:Please save a copy of this report for your records.

Date: _____

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.



vw.autel.com MaxiSys MS906 BT Page 5