

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572



Assignment

Client	MFC Auction House	Inspection Location	MFC
Requested Date	07/04/2025		M57 Pretoria Road - 1619
Inspection Date	07/04/2025		Kempton Park - GT

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	
Manufacturer	RENAULT	Registration Number	FX17TCGP
Model	SANDERO	Register Number	
VIN	VF15SRAAC56972120	Date Of First Licensing	
Engine Number		Last COR	
Doors	5	License Expiry Date	
Color	WHITE	Power / Displacement	
Year Model		Paint Finish	TWO COAT UNI
Km Reading	188,820 KM	Fuel	PETROL
Cab / Body Type	HATCHBACK	Transmission	MANUAL

Vehicle Options & Accessories

Items

VEHICLE INSPECTION

	Damage	Repair Way
	Engine Oil Leak	Repair
	Air Conditioner Insufficient	Replace
	Tail Light Left Scratched	Replace
	Seat Front Left Dirty	Repair
	Seat Front Right Damaged	Repair
	Hood Lining Dirty	Repair
	Door Sealing Rubber Front Right Damaged	Replace
	Steering Wheel Trim Defective	Repair
	Side Mirror Left Damaged	Replace
	Side Mirror Right Damaged	Replace
	Front Bumper Damaged	Repair
	Bonnet Damaged	Repair
	Front Fender Left Damaged	Repair
	Front Fender Right Paintwork • Scratched	Repair
	Rear Fender Left Paintwork • Scratched	Repair
	Rear Fender Right Paintwork • Scratched	Repair
	Rear Fender Left / Inner Tray Damaged	Repair
	Door Front Left Damaged	Repair
	Door Front Right Paintwork • Scratched	Repair
	Door Rear Left Paintwork • Scratched	Repair

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: VF15SRAAC56972120

Damage	Repair Way
Door Rear Right Paintwork • Scratched	Repair
Boot Lid / Hatch door Dented	Repair
Boot Lid / Hatch Door Rubbers Damaged	Replace
Rear bumper Damaged	Repair
Inner Boot Floor Pan and Spare Wheel Well Damaged	Repair
Sill Panel Left Paintwork • Scratched	Repair
Roof Damaged	Repair
Windscreen Cracked	Replace
Parking Brake Performance Left / Right Difference out of legal range	Repair
Brake fluid level Insufficient	Replace
Spare Tyre Damaged	Replace
Rim Front Right Dented	Repair
Rim Spare Wheel Dented	Repair
Engine	Foreign substance on oil cap
Engine	Signs of rodent in engine bay.
Warning lights illuminated on dashboard	Repair
Tyres and rims	Front left hubcap damaged
Body and Exterior	Dents and scratches on some body panels
Interior	Vehicle interior dirty and some panels scratched
Undercarriage	Bottom of engine and gearbox fully covered.
Body and Exterior	Stone chips and spray work on some body panels
Tyres and rims	Front and rear hubcaps scratched.

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s ²]
Front	2.8	2.76	-	
Rear	2.06	1.54	-	
Emergency / Parking	1.24	0.39	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	205/55 R16	91H	Kumho	Ecowing	V	0617	3 mm
Front Right	205/55 R16	91H	Kumho	Ecowing	V	0617	2 mm
Rear Left	205/55 R16	91H	Continental	ContiEco	V	0217	2 mm
Rear Right	205/55 R16	91H	Continental	ContiEco	V	2115	2 mm
Spare	205/55 R16	91H	Continental	Contipremuim	V	2115	2 mm

* Tyre Legend: V=Virgin, R=Recap

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	INJECTION	DTC030166	MISFIRE ON CYLINDER 1 DESTRUCTIVE MISFIRING	

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO AGE AND MILEAGE OF

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Sibusiso Mokase

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.



Oil cap and dipstick



Manual transmission

Name		Date		Page	
1. Name		1. Name		1. Name	
2. Address		2. Address		2. Address	
3. City		3. City		3. City	
4. State		4. State		4. State	
5. Zip		5. Zip		5. Zip	
6. Phone		6. Phone		6. Phone	
7. Email		7. Email		7. Email	
8. Notes		8. Notes		8. Notes	
9. Signature		9. Signature		9. Signature	
10. Date		10. Date		10. Date	

Brake and shock absorber report

Renault Vehicle Diagnostic Software

Vehicle Information

VIN:

Year:

Make:

Model:

Mileage:

Engine Information

Engine Type:

Displacement:

Fuel System:

Diagnosis

Diagnostic Codes:

- P0120: Throttle Position Sensor (TPS) Voltage Not at Idle
- P0121: Throttle Position Sensor (TPS) Voltage Not at Full Load
- P0122: Throttle Position Sensor (TPS) Voltage Not at Full Load
- P0123: Throttle Position Sensor (TPS) Voltage Not at Full Load
- P0124: Throttle Position Sensor (TPS) Voltage Not at Full Load
- P0125: Throttle Position Sensor (TPS) Voltage Not at Full Load
- P0126: Throttle Position Sensor (TPS) Voltage Not at Full Load
- P0127: Throttle Position Sensor (TPS) Voltage Not at Full Load
- P0128: Throttle Position Sensor (TPS) Voltage Not at Full Load
- P0129: Throttle Position Sensor (TPS) Voltage Not at Full Load
- P0130: Oxygen Sensor (O2) Circuit Voltage Not at Full Load
- P0131: Oxygen Sensor (O2) Circuit Voltage Not at Full Load
- P0132: Oxygen Sensor (O2) Circuit Voltage Not at Full Load
- P0133: Oxygen Sensor (O2) Circuit Voltage Not at Full Load
- P0134: Oxygen Sensor (O2) Circuit Voltage Not at Full Load
- P0135: Oxygen Sensor (O2) Circuit Voltage Not at Full Load
- P0136: Oxygen Sensor (O2) Circuit Voltage Not at Full Load
- P0137: Oxygen Sensor (O2) Circuit Voltage Not at Full Load
- P0138: Oxygen Sensor (O2) Circuit Voltage Not at Full Load
- P0139: Oxygen Sensor (O2) Circuit Voltage Not at Full Load

Help

Diagnostic report page 1

[illegible]

Diagnostic report page 2

1. What is the purpose of the study?
 2. What are the research objectives?
 3. What is the research methodology?
 4. What are the results of the study?
 5. What are the conclusions of the study?
 6. What are the limitations of the study?
 7. What are the implications of the study?
 8. What are the future research directions?
 9. What are the contributions of the study?
 10. What are the key findings of the study?

Diagnostic report page 3



Spare wheel and Accessories



Front left hubcap



Front chassis



Rear chassis



FRONT RIGHT CORNER



REAR LEFT CORNER



INTERIOR (FRONT DRIVER DOOR)



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



90 DEGREE FRONT



90 DEGREE RIGHT



90 DEGREE REAR



90 DEGREE LEFT



LF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD



RF TYRE TREAD



LICENSE DISC



VIN PLATE OR STICKER



ENGINE 1



Front Bumper



Front Bumper



Bonnet



Windscreen



Front Fender Left



Water level



Brake fluid level



Hood Lining



Steering Wheel Trim



Seat Front Right



Door Sealing Rubber Front Right



Rear Fender Right



Door Rear Right



Door Front Right



Front Fender Right



Side Mirror Right



Side Mirror Left



Door Front Left



Door Rear Left



Rear Fender Left



Seat Front Left



Sill Panel Left



Rear bumper




Rear bumper



Boot Lid / Hatch door



Roof



Parking Brake Performance



Boot Lid / Hatch Door Rubbers



Rim Spare Wheel



Spare Tyre



Inner Boot Floor Pan and Spare Wheel Well



Tail Light Left



Rim Front Right



Engine



Rear Fender Left / Inner Tray



Air Conditioner

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: VF15SRAAC56972120