



CONDITION REPORT

Report No: 2016255640

DATE
05/02/2024

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572

**Assignment**


Client	MFC Auction House	Inspection Location	MFC
Requested Date	05/02/2024		M57 Pretoria Road - 1619
Inspection Date	05/02/2024		Kempton Park - GT

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	MFC AUCTION HOUSE
Manufacturer	VOLKSWAGEN	Registration Number	FMG705L
Model	POLO VIVO	Register Number	
VIN	AAVZZZ6RZMU001395	Date Of First Licensing	
Engine Number		Last COR	
Doors	5	License Expiry Date	31/07/2024
Color	WHITE	Power / Displacement	
Year Model		Paint Finish	TWO COAT UNI
Km Reading	102,879 KM	Fuel	PETROL
Cab / Body Type	HATCHBACK	Transmission	MANUAL

Vehicle Options & Accessories**Items**

VEHICLE INSPECTION



Damage	Repair Way
Engine Oil Sweat	Repair
Headlight Right Scratched	Repair
Seat Front Left Dirty	Repair
Seat Front Right Damaged	Repair
Seat Rear Dirty	Repair
Interior Mirror Loose / Excessive Play	Replace
Hood Lining Defective	Repair
Door Handle Rear Right Defective	Repair
Door Sealing Rubber Front Right Damaged	Replace
Parcel Tray Damaged	Replace
Steering Wheel Trim Defective	Repair
Number Plate Rear Dented	Repair
Front Bumper Damaged	Repair
Bonnet Paintwork • Chipmarks	Repair
Front Fender Left Paintwork • Scratched	Repair
Front Fender Right Dented	Repair
Rear Fender Left Paintwork • Scratched	Repair
Rear Fender Right Damaged	Repair
Door Front Left Damaged	Repair
Door Front Right Dented	Repair
Door Rear Left Damaged	Repair
Door Rear Right Damaged	Repair
Boot Lid / Hatch door Paintwork • Scratched	Repair
Rear bumper Paintwork • Scratched	Repair
Inner Boot Floor Pan and Spare Wheel Well Paintwork • Scratched	Repair
Sill Panel Left Paintwork • Scratched	Repair
Rocker Panel Left Damaged	Repair
Rocker Panel Right Damaged	Repair

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksdorp, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6RZMU001395

1 / 16



CONDITION REPORT

Report No: 2016255640

DATE
05/02/2024

Damage	Repair Way
Windscreen Cracked	Replace
Brake disc 1. Axle right Defective	Replace
Service Brake Performance Rear Axle Left / Right	Repair
Difference out of legal range	Repair
Parking Brake Performance Left / Right Difference out of legal range	Repair
Stabilizer Mounting Front Left Defective	Replace
Control Arm Bush(es) Front Axle Left Cracked	Replace
Control Arm Bush(es) Front Axle Right Cracked	Replace
Tyre Rear Left Worn	Replace
Tyre Rear Right Damaged	Replace
Chassis Scratched	Repair
Sub Frame Dented	Repair
Engine to silencer pipe Defective	Repair
Belly plates Defective	Repair
Gearbox Oil Leak	Repair
CV Joint(s) Front Right (inner/outer) Defective	Repair
Radiator Cradle Damaged	Replace

Brakes**Brake Test Results**

	Left	Right	Axle Weight [KG]	Deceleration [m/s ²]
	Braking Force [kN]	Braking Force [kN]		
Front	2.1	2.42	-	
Rear	0.14	0.67	-	
Emergency / Parking	0.53	1.19	-	

Tyres and Rims**Tyre Specification & Measurement**

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	185/65 R15	88H	Bridgestone	B250	V	3419	1 mm
Front Right	185/65 R15	88H	Bridgestone	B250	V	3319	2 mm
Rear Left	185/65 R15	88H	Bridgestone	B250	V	3419	0 mm
Rear Right	185/60 R15	88H	Firestone	Touring	V	4222	0 mm

* Tyre Legend: V=Virgin, R=Recap

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	01-ENGINE CONTROL MODULE	P1603:00/05635:000	CTRL.MODULE FAULTY-	

Inspection Conditions

- No Test Drive
- Rain at time of inspection
- Battery Flat
- Engine number – not possible to verify engine number (not visible without dismantling)
- Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS. Engine Compartment: Engine bay dirty. Brake fluid level ok. Radiator and Aircon condenser loose. Aircon co

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

DEKRA Automotive (PTY) Ltd.
 97 Willem Cruywagen Ave
 Klerksdorp, Pretoria, 0200
 Phone: 012 542 4867
www.dekraauto.co.za

**CONDITION REPORT**VIN: AAUVT776R21001300
Report No: 2016235640

2 / 16

DATE

05/02/2024

Sibusiso Mokase

This document was created electronically and is valid without signature.

General Remarks:

The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.




CONDITION REPORT

Report No: 2016255640

VIN: AAVZZZ6RZMU001395

DATE

05/02/2024



Brake and shock absorber report



Diagnostic report page 1



Diagnostic report page 2



FRONT RIGHT CORNER



REAR LEFT CORNER



INTERIOR (FRONT DRIVER DOOR)



CONDITION REPORT

Report No: 2016255640

DATE

VIN: AAVZZZ6RZ491002024

09/02/2024

4 / 16

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016255640

DATE
05/02/2024

VIN: AAVZZZ6RZMU001395

5 / 16



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



90 DEGREE FRONT



90 DEGREE RIGHT



90 DEGREE REAR



90 DEGREE LEFT



CONDITION REPORT

Report No: 2016255640

DATE
05/02/2024

VIN: AAVZZZ6RZMU001395

6 / 16

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016255640

DATE
05/02/2024

LF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD



RF TYRE TREAD



Spare wheel Accessories



LICENSE DISC



CONDITION REPORT

Report No: 2016255640

DATE
05/02/2024

VIN: AAVZZZ6RZMU001395

8 / 16

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016255640

DATE
05/02/2024

VIN PLATE OR STICKER



ENGINE 1



Front chassis



Rear chassis



Oil cap and dipstick



Manual Transmission



CONDITION REPORT

Report No: 2016255640

DATE
05/02/2024

VIN: AAVZZZ6RZMU001395

10 / 16



CONDITION REPORT

Report No: 2016255640

DATE
05/02/2024

Seat Front Right



Door Sealing Rubber Front Right



Door Front Right



Front Fender Right



Door Rear Right



Rear Fender Right



CONDITION REPORT

Report No: 2016255640

DATE
05/02/2024

VIN: AAVZZZ6RZMU001395

12 / 16



CONDITION REPORT

Report No: 2016255640

DATE
05/02/2024

Seat Rear



Rear bumper

VIN: AAVZZZ00ZMU001395
13 / 16

Rear bumper



Boot Lid / Hatch door



Parcel Tray



Inner Boot Floor Pan and Spare Wheel Well



CONDITION REPORT

Report No: 2016255640

DATE
05/02/2024

VIN: AAVZZZ6RZMU001395

14 / 16



CONDITION REPORT

Report No: 2016255640

DATE
05/02/2024

Rear Fender Left



Door Rear Left



Door Front Left



Front Fender Left



Windscreen



Seat Front Left



CONDITION REPORT

Report No: 2016255640

DATE
05/02/2024

VIN: AAVZZZ6RZMU001395

16 / 16



CONDITION REPORT

Report No: 2016255640

DATE
05/02/2024

Seat Rear



Sill Panel Left



Sill Panel Left



Front Bumper



Front Bumper



Bonnet



CONDITION REPORT

Report No: 2016255640

DATE
05/02/2024

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016255640

DATE
05/02/2024

Headlight Right



Interior Mirror




Steering Wheel Trim



Hood Lining



Engine



Parking Brake Performance



CONDITION REPORT

Report No: 2016255640


DATE
05/02/2024

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016255640

DATE
05/02/2024

Service Brake Performance Rear Axle



Brake disc 1. Axle right



Control Arm Bush(es) Front Axle Right



Rocker Panel Right



Rocker Panel Left



Control Arm Bush(es) Front Axle Left



CONDITION REPORT

Report No: 2016255640

DATE
05/02/2024

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016255640

DATE
05/02/2024

Gearbox



CV Joint(s) Front Right (inner/outer)



Radiator Cradle



Sub Frame



Chassis



Belly plates



CONDITION REPORT

Report No: 2016255640

DATE
05/02/2024

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za




CONDITION REPORT

Report No: 2016255640

DATE
05/02/2024

Tyre Rear Left



Tyre Rear Right



Tyre Rear Right



Stabilizer Mounting Front Left



Engine to silencer pipe



Number Plate Rear



CONDITION REPORT

Report No: 2016255640

DATE
05/02/2024

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016255640

DATE
05/02/2024

Door Handle Rear Right

**CONDITION REPORT**

Report No: 2016255640

DATE
05/02/2024

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za