



CONDITION REPORT



Report No:

2016961534

DATE

29/07/2025

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572



Assignment

Client	MFC Auction House	Inspection Location	MFC
Requested Date	29/07/2025		M57 Pretoria Road - 1619
Inspection Date	29/07/2025		Kempton Park -

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	MFC
Manufacturer	VOLKSWAGEN	Registration Number	LF03GKGP
Model	POLO VIVO SEDAN GP 1.4 TRENDLINE [2014-2017]	Register Number	
		Date Of First Licensing	
VIN	AAVZZZ6SZGU019215	Last COR	
Engine Number		License Expiry Date	31/01/2026
Doors	4	Power / Displacement	
Color	WHITE	Paint Finish	C - COMMON
Year Model	2016	Fuel	PETROL
Km Reading	155,293 KM	Transmission	MANUAL
Cab / Body Type	SEDAN		

Vehicle Options & Accessories

Items

VEHICLE INSPECTION

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6SZGU019215



CONDITION REPORT



Report No:

2016961534

DATE

29/07/2025

Damage

Repair Way

Engine Oil Leak	Repair
Switch Electrical Window Winder front right Damaged	Repair
Tail Light Right Cracked	Repair
Hood Lining Excessive Wear & Tear	Repair
Parcel Tray Damaged	Repair
Front Bumper Residual Traces of Repair	Repair
C • Pillar Left Residual Traces of Repair	Repair
Front Fender Left Residual Traces of Repair	Repair
Rear Fender Left Residual Traces of Repair	Repair
Rear Fender Right Residual Traces of Repair	Repair
Door Front Left Residual Traces of Repair	Repair
Door Rear Left Residual Traces of Repair	Repair
Door Rear Right Residual Traces of Repair	Repair
Boot Lid / Hatch door Residual Traces of Repair	Repair
Rear bumper Residual Traces of Repair	Repair
Roof Residual Traces of Repair	Repair
Tie Rod End left Cracked	Replace
Tie Rod End right Cracked	Replace
Control Arm Bush(es) Front Axle Left Cracked	Repair
Control Arm Bush(es) Front Axle Right Cracked	Replace
Tyre Front Left Damaged	Replace
Tyre Front Right Smooth	Replace
Tyre Rear Left Smooth	Replace
Tyre Rear Right Smooth	Replace
Gearbox Oil Sweat	Repair
Body exterior	Residual traces of poor repair on most body panels
Axle and suspension	CV joints excessive noise
Body exterior	Signs of spray work done on some body panels
Electronics malfunction	Wiper blades faulty
Bootlid does not open	Repair
Driver electric window not working	Repair

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s ²]
Front	2.6	2.5	-	
Rear	1.4	1.3	-	
Emergency / Parking	1.1	0.6	-	

DEKRA Automotive (PTY) Ltd.
 97 Willem Cruywagen Ave
 Klerksoord, Pretoria, 0200
 Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6SZGU019215



CONDITION REPORT



Report No:
2016961534
DATE
29/07/2025

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	185/60R14	82H	Aplus	A609	V	0824	2 mm
Front Right	185/65R14	86T	Bridgestone	B250	V	1219	0 mm
Rear Left	175/65R14	82T	Cachland	CH	V	0000	0 mm
Rear Right	185/65R14	86H	Bridgestone	Touring	V	0000	0 mm

* Tyre Legend: V=Virgin, R=Recap

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	ENGINE CONTROL MODULE	P1355:00//4949:000	IGNITION ACTIVATION CYLINDER 1	

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Trevino Julius

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6SZGU019215



CONDITION REPORT




Report No:
2016961534
DATE
29/07/2025



Shock and brake report



Diagnostic test



Diagnostic test



FRONT RIGHT CORNER



REAR LEFT CORNER



INTERIOR (FRONT DRIVER DOOR)

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6SZGU019215



CONDITION REPORT



Report No:
2016961534
DATE
29/07/2025



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



Manual



90 DEGREE FRONT



90 DEGREE RIGHT



90 DEGREE REAR

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6SZGU019215



CONDITION REPORT



Report No:
2016961534
DATE
29/07/2025



90 DEGREE LEFT



LF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD



RF TYRE TREAD



LICENSE DISC

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6SZGU019215



CONDITION REPORT



Report No:
2016961534
DATE
29/07/2025



VIN PLATE OR STICKER



ENGINE 1



ENGINE 2



CHASSIS



Rear end



Expansion bottle

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6SZGU019215



CONDITION REPORT



Report No:
2016961534
DATE
29/07/2025



Oil cap and dipstick



Water level



Door Rear Right



Rear Fender Right



Hood Lining



Hood Lining

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6SZGU019215



CONDITION REPORT



Report No:
2016961534
DATE
29/07/2025




Hood Lining



Boot Lid / Hatch door



Tail Light Right



C • Pillar Left



Rear Fender Left



Roof

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6SZGU019215



CONDITION REPORT



Report No:
2016961534
DATE
29/07/2025



Hood Lining



Door Front Left



Front Fender Left



Parcel Tray



Parcel Tray



Control Arm Bush(es) Front Axle Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6SZGU019215



CONDITION REPORT



Report No:
2016961534
DATE
29/07/2025



Tyre Front Right



Front Bumper



Front Bumper



Front Bumper



Tyre Front Left



Tyre Front Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6SZGU019215




CONDITION REPORT




Report No:
2016961534
DATE
29/07/2025



Control Arm Bush(es) Front Axle Left



Door Rear Left



Tyre Rear Left



Rear bumper



Rear bumper



Rear bumper

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6SZGU019215



CONDITION REPORT



Report No:
2016961534
DATE
29/07/2025



Tyre Rear Right



Tie Rod End left



Gearbox



Tie Rod End right



Engine



Roof

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6SZGU019215



CONDITION REPORT



Report No:
2016961534
DATE
29/07/2025



Switch Electrical Window Winder front right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6SZGU019215