



CONDITION REPORT



Report No:

2017304204

DATE

28/09/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572



Assignment

Client	MFC Auction House	Inspection Location	MFC
Requested Date	28/09/2026		M57 Pretoria Road - 1619
Inspection Date	28/09/2026		Kempton Park - GT

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	MFC
Manufacturer	VOLKSWAGEN	Registration Number	HC33GRGP
Model	POLO VIVO GP 1.4 55KW CONCEPTLINE 5-DR [2016-2018]	Register Number	
		Date Of First Licensing	
VIN	AAVZZZ6SZHU029355	Last COR	
Engine Number		License Expiry Date	31/03/2027
Doors	5	Power / Displacement	
Color	SILVER	Paint Finish	M - METALLIC
Year Model	2017	Fuel	PETROL
Km Reading	204,302 KM	Transmission	MANUAL
Cab / Body Type	HATCHBACK		

Vehicle Options & Accessories

Items

VEHICLE INSPECTION

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6SZHU029355



CONDITION REPORT



Report No:

2017304204

DATE

28/09/2026

Damage

Repair Way

Engine Oil Leak	Repair
Tail Light Left Cracked	Replace
Tail Light Right Cracked	Replace
Dim Light Right Malfunction	Repair
Headlight Right Damaged	Repair
Parcel Tray Missing	Replace
Side Mirror Left Damaged	Repair
Side Mirror Right Paintwork • Scratched	Repair
Front Bumper Paintwork • Scratched	Repair
Bonnet Paintwork • Scratched	Repair
Front Fender Left Residual Traces of Repair	Repair
Front Fender Right Residual Traces of Repair	Repair
Rear Fender Left Residual Traces of Repair	Repair
Rear Fender Right Paintwork • Scratched	Repair
Door Front Left Residual Traces of Repair	Repair
Door Front Right Dented	Repair
Door Rear Left Residual Traces of Repair	Repair
Door Rear Right Paintwork • Scratched	Repair
Boot Lid / Hatch door Dented	Repair
Rear bumper Damaged	Repair
Inner Boot Floor Pan and Spare Wheel Well Dented	Repair
Windscreen Cracked	Replace
Bolt(s) / Nut(s) Front Wheel Right Missing	Replace
Silencer Defective	Repair
Radiator Cradle Missing	Replace
EPC light on	Repair
Boot not opening can not see spare wheel	Repair
All four hup caps missing	Replace
Battery loose	Repair
Rear and Front tyres size differs	Replace

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s ²]
Front	2.6	2.7	-	
Rear	1.3	1.3	-	
Emergency / Parking	0.6	0.4	-	

DEKRA Automotive (PTY) Ltd.
 97 Willem Cruywagen Ave
 Klerksoord, Pretoria, 0200
 Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6SZHU029355



CONDITION REPORT



Report No:
2017304204
DATE
28/09/2026

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	185/60R14	82H	Goodyear	Efficient gr	V	0424	3 mm
Front Right	165/70R14	81T	Hankook	Kinergy	V	3423	3 mm
Rear Left	175/65R14	82H	Continental	Contact	V	0811	2 mm
Rear Right	165/70R14	82H	Hankook	Kinergy	V	3423	3 mm

* Tyre Legend: V=Virgin, R=Recap

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	PASSIVE SPORADIC	00532:007	SUPPLY VOLTAGE - SIGNAL TOO LOW	

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS. Body • Exterior: Signs of spray work done on some body panels.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Andrick Wymers

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6SZHU029355



CONDITION REPORT



Report No:

2017304204

DATE


28/09/2026

SHOCK AND BRAKE REPORT			
Item	Condition	Remarks	Result
1. Front Suspension	Good		Pass
2. Rear Suspension	Good		Pass
3. Front Brakes	Good		Pass
4. Rear Brakes	Good		Pass
5. Steering	Good		Pass
6. Tyres	Good		Pass
7. Wheel Alignment	Good		Pass
8. Chassis	Good		Pass
9. Exhaust	Good		Pass
10. Fuel System	Good		Pass
11. Ignition System	Good		Pass
12. Electrical System	Good		Pass
13. Bodywork	Good		Pass
14. Paintwork	Good		Pass
15. Interior	Good		Pass
16. Exterior	Good		Pass
17. Overall Condition	Good		Pass

Shock and brake report

VEHICLE DIAGNOSTIC REPORT			
Item	Condition	Remarks	Result
1. Engine	Good		Pass
2. Transmission	Good		Pass
3. Clutch	Good		Pass
4. Gearbox	Good		Pass
5. Driveshafts	Good		Pass
6. Axles	Good		Pass
7. Suspension	Good		Pass
8. Steering	Good		Pass
9. Tyres	Good		Pass
10. Wheel Alignment	Good		Pass
11. Chassis	Good		Pass
12. Exhaust	Good		Pass
13. Fuel System	Good		Pass
14. Ignition System	Good		Pass
15. Electrical System	Good		Pass
16. Bodywork	Good		Pass
17. Paintwork	Good		Pass
18. Interior	Good		Pass
19. Exterior	Good		Pass
20. Overall Condition	Good		Pass

Diagnostic report



Diagnostic report



FRONT RIGHT CORNER



REAR LEFT CORNER



INTERIOR (FRONT DRIVER DOOR)

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6SZHU029355



CONDITION REPORT



Report No:

2017304204

DATE

28/09/2026



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



Manual



90 DEGREE FRONT



90 DEGREE RIGHT



90 DEGREE REAR

DEKRA Automotive (PTY) Ltd.
 97 Willem Cruywagen Ave
 Klerksoord, Pretoria, 0200
 Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6SZHU029355




CONDITION REPORT



Report No:
2017304204
DATE
28/09/2026



90 DEGREE LEFT



LF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD



RF TYRE TREAD



LICENSE DISC

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za


VIN: AAVZZZ6SZHU029355



CONDITION REPORT



Report No:
2017304204
DATE
28/09/2026



VIN PLATE OR STICKER



ENGINE 1



ENGINE 2



CHASSIS



Expection bottle



Oil cap and dipstick

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6SZHU029355



CONDITION REPORT



Report No:
2017304204
DATE
28/09/2026



Battery loose



Parcel Tray



Windscreen



Dim Light Right



Headlight Right



Tail Light Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6SZHU029355



CONDITION REPORT



Report No:
2017304204
DATE
28/09/2026



Tail Light Right



Water level



Bonnet



Rear Fender Right



Door Rear Right



Door Front Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6SZHU029355



CONDITION REPORT



Report No:
2017304204
DATE
28/09/2026



Front Fender Right



Side Mirror Right



Front Bumper



Front Bumper



Front Fender Left



Side Mirror Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6SZHU029355



CONDITION REPORT



Report No:

2017304204

DATE

28/09/2026



Door Front Left



Door Rear Left



Rear Fender Left



Boot Lid / Hatch door



Rear bumper



Rear bumper

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6SZHU029355



CONDITION REPORT



Report No:
2017304204
DATE
28/09/2026



Inner Boot Floor Pan and Spare Wheel Well



Silencer



Engine



Radiator Cradle



Bolt(s) / Nut(s) Front Wheel Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6SZHU029355