



CONDITION REPORT

Report No: 2016843982

DATE
15/04/2025

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572



Assignment

Client	MFC Auction House	Inspection Location	MFC
Requested Date	15/04/2025		M57 Pretoria Road - 1619
Inspection Date	15/04/2025		Kempton Park - GT

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	
Manufacturer	VOLKSWAGEN	Registration Number	FVZ841L
Model	POLO VIVO GP 1.4 55KW CONCEPTLINE 5-DR [2016-2018]	Register Number	
VIN	AAVZZZ6SZHU033170	Date Of First Licensing	
Engine Number		Last COR	
Doors	5	License Expiry Date	31/07/2025
Color	WHITE	Power / Displacement	
Year Model	2017	Paint Finish	TWO COAT UNI
Km Reading	155,967 KM	Fuel	PETROL
Cab / Body Type	HATCHBACK	Transmission	MANUAL

Vehicle Options & Accessories

Items

VEHICLE INSPECTION

Damage	Repair Way
Engine Oil Sweat	Repair
Radiator Damaged	Replace
Air conditioner pipes Damaged	Repair
Windscreen Wiper Damaged	Replace
Air Conditioner Insufficient	Replace
Headlight Right Defective	Repair
Seat Front Right Damaged	Repair
Seat Rear Dirty	Repair
Door Handle Front Left Defective	Replace
Steering Wheel Trim Defective	Repair
Side Mirror Left Residual Traces of Repair	Replace
Side Mirror Right Paintwork • Scratched	Repair
Front Bumper Damaged	Repair
Bonnet Paintwork • Scratched	Repair
Front Fender Left Damaged	Repair
Front Fender Right Damaged	Repair
Rear Fender Left Dented	Repair
Rear Fender Right Paintwork • Scratched	Repair
Rear Fender Right / Inner Tray Dented	Repair

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6SZHU033170



CONDITION REPORT

Report No: 2016843982

DATE
15/04/2025

Damage	Repair Way
Door Front Left Paintwork • Scratched	Repair
Door Front Right Paintwork • Scratched	Repair
Door Rear Left Paintwork • Scratched	Repair
Door Rear Right Paintwork • Scratched	Repair
Boot Lid / Hatch door Paintwork • Scratched	Repair
Rear bumper Paintwork • Scratched	Repair
Inner Boot Floor Pan and Spare Wheel Well Damaged	Repair
Sill Panel Left Dented	Repair
Sill Panel Right Dented	Repair
Windscreen Cracked	Replace
Control Arm Bush(es) Front Axle Left Cracked	Replace
Control Arm Bush(es) Front Axle Right Cracked	Replace
Tyre Rear Left Worn	Replace
Spare Tyre Worn	Replace
Rim Front Left Scratched	Repair
Rim Front Right Scratched	Repair
Rim Rear Left Scratched	Repair
Rim Rear Right Scratched	Repair
Chassis Damaged	Repair
Cross Member Rear Right Dented	Repair
Sub Frame Damaged	Replace
Engine to silencer pipe Welded	Replace
Silencer Damaged	Replace
Belly plates Damaged	Repair
Gearbox Oil Sweat	Repair
Fuel Tank Defective	Repair
Radiator Cradle Damaged	Replace
Interior	Vehicle interior dirty and some panels scratched
Engine	Engine bay dirty.
Engine	Computer box strapped with cable ties
Engine	Aircon condenser dented
Engine	Engine oil sump dented
Undercarriage	Vehicle undercarriage dirty
Body and Exterior	Dents and scratches on some body panels
Body and Exterior	Signs of impact damage to front of vehicle.
Tyres and rims	Rear left and right tyre sizes different

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s ²]
Front	2.52	2.4	-	
Rear	1.59	1.58	-	
Emergency / Parking	1.04	1.07	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	175/65 R14	82H	Apollo	Acelere	V	5011	1 mm
Front Right	175/65 R14	82H	Apollo	Acelere	V	4711	1 mm
Rear Left	175/70 R14	84T	Firestone	Touring	V	3421	0 mm
Rear Right	175/65 R14	82H	Goodyear	Efficient	V	1722	3 mm
Spare	185/60 R14	82H	Goodride	Radial	V		0 mm

* Tyre Legend: V=Virgin, R=Recap

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6SZHU033170



CONDITION REPORT

Report No: 2016843982

DATE
15/04/2025**Diagnostic**

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	09-ELECTRONIC CENTRAL ELECTRIC	01598:007	DRIVE BATTERY VOLTAGE-SIGNAL TOO LOW	

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Sibusiso Mokase

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6SZHU033170



CONDITION REPORT

Report No: 2016843982

DATE
15/04/2025

Vehicle Information			
Client:	Mr. M. M. M.	Vehicle:	VW Polo 1.4
Model:	VW Polo	Year:	2015
Registration:	1234567	Engine:	1.4 1600
Owner:	Mr. M. M. M.	Transmission:	Manual
Insurer:	SAFARI	Color:	White
Inspection Results			
Item	Result	Item	Result
Engine	OK	Brakes	OK
Transmission	OK	Steering	OK
Chassis	OK	Wheels	OK
Electrics	OK	Lighting	OK
Interior	OK	Exterior	OK
Overall	OK	Notes	

Brake and shock absorber report

Vehicle Information			
Client:	Mr. M. M. M.	Vehicle:	VW Polo 1.4
Model:	VW Polo	Year:	2015
Registration:	1234567	Engine:	1.4 1600
Owner:	Mr. M. M. M.	Transmission:	Manual
Insurer:	SAFARI	Color:	White
Inspection Results			
Item	Result	Item	Result
Engine	OK	Brakes	OK
Transmission	OK	Steering	OK
Chassis	OK	Wheels	OK
Electrics	OK	Lighting	OK
Interior	OK	Exterior	OK
Overall	OK	Notes	

Diagnostic report page 1

Vehicle Information			
Client:	Mr. M. M. M.	Vehicle:	VW Polo 1.4
Model:	VW Polo	Year:	2015
Registration:	1234567	Engine:	1.4 1600
Owner:	Mr. M. M. M.	Transmission:	Manual
Insurer:	SAFARI	Color:	White
Inspection Results			
Item	Result	Item	Result
Engine	OK	Brakes	OK
Transmission	OK	Steering	OK
Chassis	OK	Wheels	OK
Electrics	OK	Lighting	OK
Interior	OK	Exterior	OK
Overall	OK	Notes	

Diagnostic report page 2



FRONT RIGHT CORNER



REAR LEFT CORNER



DRIVER SIDE

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6SZHU033170



CONDITION REPORT

Report No: 2016843982

DATE
15/04/2025

INTERIOR (FRONT DRIVER DOOR)



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



Manual transmission



90 DEGREE FRONT



90 DEGREE RIGHT

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6SZHU033170



CONDITION REPORT

Report No: 2016843982

DATE
15/04/2025

90 DEGREE REAR



90 DEGREE LEFT



LF TYRE TREAD



RF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6SZHU033170



CONDITION REPORT

Report No: 2016843982

DATE
15/04/2025

Spare wheel and Accessories



LICENSE DISC



VIN PLATE OR STICKER



ENGINE 1



Front chassis



Rear Chassis

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6SZHU033170



CONDITION REPORT

Report No: 2016843982

DATE
15/04/2025

Engine oil sump



Aircon condenser



Oil cap and dipstick



Steering Wheel Trim



Seat Front Right



Seat Rear

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6SZHU033170



CONDITION REPORT

Report No: 2016843982

DATE
15/04/2025

Rear Fender Right



Door Rear Right



Door Front Right



Front Fender Right



Side Mirror Right



Front Bumper

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6SZHU033170



CONDITION REPORT

Report No: 2016843982

DATE
15/04/2025

Front Bumper



Bonnet



Windscreen



Front Fender Left



Door Front Left



Door Rear Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6SZHU033170



CONDITION REPORT

Report No: 2016843982

DATE
15/04/2025

Rear Fender Left



Side Mirror Left



Door Handle Front Left



Air Conditioner



Inner Boot Floor Pan and Spare Wheel Well



Spare Tyre

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6SZHU033170



CONDITION REPORT

Report No: 2016843982

DATE
15/04/2025

Windscreen Wiper



Boot Lid / Hatch door



Rear bumper



Rear bumper



Engine



Water level

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6SZHU033170



CONDITION REPORT

Report No: 2016843982

DATE
15/04/2025

Headlight Right



Rim Front Right



Control Arm Bush(es) Front Axle Right



Rim Rear Right



Rim Rear Left



Sill Panel Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6SZHU033170



CONDITION REPORT

Report No: 2016843982

DATE
15/04/2025

Rim Front Left



Control Arm Bush(es) Front Axle Left



Radiator



Sill Panel Right



Engine to silencer pipe



Silencer


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6SZHU033170



CONDITION REPORT


Report No: 2016843982

DATE
15/04/2025


Sub Frame



Gearbox



Air conditioner pipes



Radiator Cradle



Engine to silencer pipe



Chassis


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6SZHU033170



CONDITION REPORT

Report No: 2016843982

DATE
15/04/2025

Belly plates



Cross Member Rear Right



Silencer



Belly plates



Belly plates



Tyre Rear Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6SZHU033170



CONDITION REPORT


Report No: 2016843982

DATE
15/04/2025

Fuel Tank



Rear Fender Right / Inner Tray



Chassis



Water level

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6SZHU033170