



CONDITION REPORT



Report No:
2017305036
DATE
30/09/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572



Assignment

Client	MFC Auction House	Inspection Location	MFC
Requested Date	30/09/2026		M57 Pretoria Road - 1619
Inspection Date	30/09/2026		Kempton Park -

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	MFC
Manufacturer	VOLKSWAGEN	Registration Number	KB38RTGP
Model	POLO 1.0 TSI 70KW COMFORTLINE 5-DR [2018-2020]	Register Number	
		Date Of First Licensing	
VIN	AAVZZZAWZJU067233	Last COR	
Engine Number		License Expiry Date	30/06/2027
Doors	5	Power / Displacement	
Color	GREY	Paint Finish	TWO COAT UNI
Year Model	2018	Fuel	PETROL
Km Reading	26,622 KM	Transmission	MANUAL
Cab / Body Type	HATCHBACK		

Vehicle Options & Accessories

Items

VEHICLE INSPECTION

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZAWZJU067233



CONDITION REPORT



Report No:

2017305036

DATE

30/09/2026

Damage

Repair Way

Engine Oil Leak	Repair
Radiator Deformed	Replace
Engine Management Lights Set	Repair
Sun Roof Defective	Repair
Side Mirror Right Damaged	Replace
Front Bumper Damaged	Repair
Bonnet Residual Traces of Repair	Repair
A • Pillar Left Damaged	Repair
A • Pillar Right Residual Traces of Repair	Repair
B • Pillar Left Residual Traces of Repair	Repair
B • Pillar Right Residual Traces of Repair	Repair
C • Pillar Left Residual Traces of Repair	Repair
C • Pillar Right Residual Traces of Repair	Repair
Front Fender Left Residual Traces of Repair	Repair
Front Fender Right Residual Traces of Repair	Repair
Rear Fender Left Damaged	Repair
Rear Fender Right Residual Traces of Repair	Repair
Door Front Left Residual Traces of Repair	Repair
Door Front Right Residual Traces of Repair	Repair
Door Rear Left Residual Traces of Repair	Repair
Door Rear Right Residual Traces of Repair	Repair
Boot Lid / Hatch door Damaged	Repair
Rear bumper Residual Traces of Repair	Repair
Fuel Flap Damaged	Replace
Roof Residual Traces of Repair	Repair
Tyre Front Left Worn	Replace

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s ²]
Front	2.91	3.02	-	
Rear	2.18	2.09	-	
Emergency / Parking	1.02	0.89	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	215/45R17	91W	Ovation	Radial	V	1921	0 mm
Front Right	215/45R17	91W	Sailwin	Radial	V	4121	2 mm
Rear Left	215/45R17	91W	Bridgestone	Radial	V	2119	1 mm
Rear Right	215/45R17	91V	Continental	Contisport	V	2118	1 mm

* Tyre Legend: V=Virgin, R=Recap

DEKRA Automotive (PTY) Ltd.
 97 Willem Cruywagen Ave
 Klerksoord, Pretoria, 0200
 Phone: 012 542 4867
 www.dekraauto.co.za

VIN: AAVZZAWZJU067233



CONDITION REPORT



Report No:

2017305036

DATE

30/09/2026

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	ENGINE CONTROL MODULE 1	P019700	OIL TEMPERATURE SENSOR SHORT CIRCUIT TO GROUND	

Inspection Conditions

No Test Drive

Rain at time of inspection

Battery Flat

Engine number – not possible to verify engine number (not visible without dismantling)

Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS. 62 DTC'S AT TIME OF TESTING SEE DTC REPORT. VEHICLE MIGHT BE A POSSIBLE CUT AND JOIN ON THE ROOF SECTION OF THE VEHICLE. Engine Compartment: Battery loose.

Electrical Components and Instruments: vehicle electronics malfunctioning.

Interior: sunroof sunshader damaged.

Body • Exterior: Minor dents and scratches and stone chips to body panels. Signs of repair work done to body panels. Poor alignment to somebody panels. Repair work done to vehicle below standard.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Werner Laubscher

This document was created electronically and is valid without signature.

General Remarks:

The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za


VIN: AAVZZAWZJU067233




CONDITION REPORT




Report No:
2017305036
DATE
30/09/2026




Brake and shock absorber




Diagnostic report




Diagnostic report



Diagnostic report



Diagnostic report



Diagnostic report

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZAWZJU067233



CONDITION REPORT



Report No:
2017305036
DATE
30/09/2026



FRONT RIGHT CORNER



REAR LEFT CORNER



INTERIOR (FRONT DRIVER DOOR)



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



90 DEGREE FRONT

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZAWZJU067233



CONDITION REPORT



Report No:

2017305036

DATE

30/09/2026



90 DEGREE RIGHT



90 DEGREE REAR



90 DEGREE LEFT



LF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZAWZJU067233



CONDITION REPORT



Report No:
2017305036
DATE
30/09/2026



RF TYRE TREAD



LICENSE DISC



VIN PLATE OR STICKER



ENGINE 1



ADDITIONAL 1



ADDITIONAL 2

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZAWZJU067233



CONDITION REPORT



Report No:

2017305036

DATE

30/09/2026



ADDITIONAL 10



Front Bumper



Front Bumper



Bonnet



Front Fender Left



Rear Fender Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZAWZJU067233



CONDITION REPORT



Report No:
2017305036
DATE
30/09/2026



Door Front Left



Door Rear Left



Boot Lid / Hatch door



Rear bumper



Door Rear Right



Door Front Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZAWZJU067233



CONDITION REPORT



Report No:
2017305036
DATE
30/09/2026



Rear Fender Right



Front Fender Right



A • Pillar Right



B • Pillar Right



C • Pillar Right



A • Pillar Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZAWZJU067233



CONDITION REPORT



Report No:

2017305036

DATE

30/09/2026



B • Pillar Left



C • Pillar Left



Roof



Sun Roof



Water level



Side Mirror Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZAWZJU067233



CONDITION REPORT



Report No:
2017305036
DATE
30/09/2026



A • Pillar Left



A • Pillar Left



Tyre Front Left



Engine



Radiator



Fuel Flap

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZAWZJU067233



CONDITION REPORT



Report No:
2017305036
DATE
30/09/2026



Engine Management Lights

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZAWZJU067233