



CONDITION REPORT



Report No:
2017302310
DATE
22/09/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572



Assignment

Client	MFC Auction House	Inspection Location	MFC
Requested Date	22/09/2026		M57 Pretoria Road - 1619
Inspection Date	22/09/2026		Kempton Park -

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	
Manufacturer	VOLKSWAGEN	Registration Number	JY31DZGP
Model	POLO 1.0 TSI 70KW COMFORTLINE 5-DR DSG [2020-2022]	Register Number	
		Date Of First Licensing	
VIN	AAVZZZAWZMU060202	Last COR	
Engine Number		License Expiry Date	30/04/2026
Doors	5	Power / Displacement	
Color	RED	Paint Finish	C - COMMON
Year Model	2021	Fuel	PETROL
Km Reading	216,250 KM	Transmission	AUTOMATIC
Cab / Body Type	HATCHBACK		

Vehicle Options & Accessories

Items

VEHICLE INSPECTION

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZAWZMU060202



CONDITION REPORT



Report No:

2017302310

DATE

22/09/2026

Damage

Repair Way

Switch Electrical Window Winder front left Malfunction	Repair
Switch Electrical Window Winder front right Malfunction	Repair
Number Plate Rear Missing	Replace
Side Mirror Left Paintwork • Scratched	Repair
Front Bumper Paintwork • Scratched	Repair
Bonnet Paintwork • Chipmarks	Repair
A • Pillar Right Paintwork • Scratched	Repair
Front Fender Left Paintwork • Scratched	Repair
Front Fender Right Paintwork • Chipmarks	Repair
Rear Fender Left Dented	Repair
Rear Fender Right Paintwork • Scratched	Repair
Door Front Left Paintwork • Chipmarks	Repair
Door Front Right Paintwork • Scratched	Repair
Door Rear Left Paintwork • Scratched	Repair
Door Rear Right Paintwork • Chipmarks	Repair
Boot Lid / Hatch door Paintwork • Scratched	Repair
Rear bumper Paintwork • Scratched	Repair
Windscreen Damaged	Replace
Engine management lights illuminated	Repair
Boot not opening can not see spare wheel	Repair
R/R tire deferred name brand	Repair

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s ²]
Front	3.2	3.0	-	
Rear	2.5	2.7	-	
Emergency / Parking	1.4	1.9	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	215/45R17	91W	Continental	Contact	V	3725	3 mm
Front Right	215/45R17	91W	Continental	Contact	V	1724	3 mm
Rear Left	215/45R17	91W	Continental	Contact	V	3625	3 mm
Rear Right	215/45R17	91W	Annaite	An606	V	4323	4 mm

* Tyre Legend: V=Virgin, R=Recap

DEKRA Automotive (PTY) Ltd.
 97 Willem Cruywagen Ave
 Klerksoord, Pretoria, 0200
 Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZAWZMU060202



CONDITION REPORT



Report No:
2017302310
DATE
22/09/2026

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	ACTIVE STATIC	P256400	TURBOCHARGER BOOST CONTROL POSITION SENSOR CIRC LO	

Inspection Conditions

No Test Drive

Battery Flat

Engine number – not possible to verify engine number (not visible without dismantling)

Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Andrick Wymers

This document was created electronically and is valid without signature.

General Remarks:

The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZAWZMU060202



CONDITION REPORT



Report No:
2017302310
DATE
22/09/2026

Shock and brake report form with fields for vehicle details, inspection results, and technician information. The form includes a table for 'Shock & brake test' results.

Shock and brake report

Diagnostic report form with fields for vehicle details, inspection results, and technician information. The form includes a table for 'Diagnostic test' results.


Diagnostic report

Diagnostic report form with fields for vehicle details, inspection results, and technician information. The form includes a table for 'Diagnostic test' results.


Diagnostic report

Diagnostic report form with fields for vehicle details, inspection results, and technician information. The form includes a table for 'Diagnostic test' results.

Diagnostic report



FRONT RIGHT CORNER



REAR LEFT CORNER

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZAWZMU060202



CONDITION REPORT



Report No:
2017302310
DATE
22/09/2026



INTERIOR (FRONT DRIVER DOOR)



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



Automatic



90 DEGREE FRONT



90 DEGREE RIGHT

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZAWZMU060202



CONDITION REPORT




Report No:

2017302310

DATE

22/09/2026



90 DEGREE REAR



90 DEGREE LEFT




LF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD



RF TYRE TREAD

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZAWZMU060202



CONDITION REPORT



Report No:

2017302310

DATE

22/09/2026



LICENSE DISC



VIN PLATE OR STICKER



ENGINE 1



ENGINE 2



CHASSIS



Oil cap and dipstick

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZAWZMU060202



CONDITION REPORT



Report No:
2017302310
DATE
22/09/2026



Expection bottle



Water level



Switch Electrical Window Winder front left



Switch Electrical Window Winder front right



Windscreen



Number Plate Rear

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za


VIN: AAVZZAWZMU060202




CONDITION REPORT



Report No:
2017302310
DATE
22/09/2026



Rear Fender Right



Door Rear Right



Door Front Right



Front Fender Right



Bonnet



Front Bumper

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZAWZMU060202



CONDITION REPORT



Report No:

2017302310

DATE

22/09/2026



Front Bumper



Front Fender Left




Side Mirror Left



Door Front Left



Door Rear Left



Rear Fender Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZAWZMU060202



CONDITION REPORT




Report No:

2017302310

DATE

22/09/2026



Rear bumper



Rear bumper



Boot Lid / Hatch door



A • Pillar Right

DEKRA Automotive (PTY) Ltd.

97 Willem Cruywagen Ave

Klerksoord, Pretoria, 0200

Phone: 012 542 4867

www.dekraauto.co.za

VIN: AAVZZAWZMU060202