



CONDITION REPORT



Report No:
2017302498
DATE
23/09/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572



Assignment

Client	MFC Auction House	Inspection Location	MFC
Requested Date	23/09/2026		M57 Pretoria Road - 1619
Inspection Date	23/09/2026		Kempton Park - GT

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	MFC
Manufacturer	VOLKSWAGEN	Registration Number	HBZ487L
Model	POLO 1.0 TSI 70KW LIFE 5-DR [2021-2023]	Register Number	
VIN	AAVZZAWZNU028131	Date Of First Licensing	
Engine Number		Last COR	
Doors	5	License Expiry Date	31/01/2027
Color	SILVER	Power / Displacement	
Year Model	2022	Paint Finish	TWO COAT UNI
Km Reading	196,687 KM	Fuel	PETROL
Cab / Body Type	HATCHBACK	Transmission	MANUAL

Vehicle Options & Accessories

Items

VEHICLE INSPECTION

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za


VIN: AAVZZAWZNU028131



CONDITION REPORT



Report No:
2017302498
DATE
23/09/2026



Damage	Repair Way
Engine Oil Sweat	Repair
Switch Electrical Window Winder rear left Damaged	Replace
Tail Light Left Cracked	Replace
Headlight Right Defective	Repair
Seat Front Left Dirty	Repair
Seat Front Right Damaged	Repair
Seat Rear Dirty	Repair
Hood Lining Dirty	Repair
Parcel Tray Missing	Replace
Side Mirror Right Paintwork • Scratched	Repair
Front Bumper Damaged	Replace
Bonnet Residual Traces of Repair	Replace
Bonnet slam plate (Shock tower/ Inner tray) Damaged	Replace
Front Fender Left Residual Traces of Repair	Repair
Front Fender Right Residual Traces of Repair	Repair
Rear Fender Left Dented	Repair
Rear Fender Right Dented	Repair
Door Front Left Residual Traces of Repair	Repair
Door Front Right Damaged	Repair
Door Rear Right Damaged	Repair
Boot Lid / Hatch Door Rubbers Damaged	Replace
Rear bumper Paintwork • Scratched	Repair
Sill Panel Right Damaged	Repair
Roof Dented	Repair
Back Window Residual Traces of Repair	Repair
Control Arm Bush(es) Front Axle Left Cracked	Replace
Control Arm Bush(es) Front Axle Right Cracked	Replace
Tyre Front Left Damaged	Replace
Tyre Front Right Damaged	Replace
Tyre Rear Left Damaged	Replace
Tyre Rear Right Damaged	Replace
Cross Member Rear Right Damaged	Repair
Sub Frame Damaged	Repair
Belly plates Damaged	Replace
Fuel Tank Damaged	Repair
Jack Missing	Replace
Wheel Spanner Missing	Replace
Spare Wheel missing	Replace
Front and rear tyres regrooved	Replace
Engine light illuminated	Repair

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZAWZNU028131



CONDITION REPORT



Report No:
2017302498
DATE
23/09/2026

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s ²]
Front	3.05	3.26	-	
Rear	1.51	1.17	-	
Emergency / Parking	1.45	1.07	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	185/65 R15	92T	Sumitomo	Radial	V	3825	0 mm
Front Right	185/60 R15	84H	Continental	Contipremuim	V	4422	0 mm
Rear Left	185/65 R15	88H	Autogrip	P308	V	0125	0 mm
Rear Right	185/65 R15	88H	Autogrip	P308	V	0125	0 mm

* Tyre Legend: V=Virgin, R=Recap

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	01-ENGINE CONTROL MODULE 1	P051200	STARTER REQUEST CIRCUIT	

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS. Interior: Vehicle interior dirty and panels scratched.
Body • Exterior: Poor residual traces of repair on body panels. Body panels misaligned. Stone chips and spray work on body panels. Dents and scratches on body panels.
Undercarriage: Vehicle undercarriage dirty

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Sibusiso Mokase

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZAWZNU028131

**CONDITION REPORT**

Report No:
2017302498
DATE
23/09/2026

strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZAWZNU028131



CONDITION REPORT



Report No:
2017302498
DATE
23/09/2026

VEHICLE INFORMATION					
Make/Model	Volkswagen Polo	Year	2017	Engine	1.6 TSI
Registration	2017302498	Chassis No.	WVGZZZAWZNU028131	Color	White
TEST RESULTS					
Item	Value	Unit	Limit	Result	
Engine oil level	40	mm	40-60	Pass	
Shock absorber test	100	mm	100-120	Pass	
Brake test	100	mm	100-120	Pass	
Steering wheel	100	mm	100-120	Pass	
Brake pedal	100	mm	100-120	Pass	
Brake fluid	100	mm	100-120	Pass	
Brake disc	100	mm	100-120	Pass	
Brake pads	100	mm	100-120	Pass	
Brake lines	100	mm	100-120	Pass	
Brake master cylinder	100	mm	100-120	Pass	
Brake booster	100	mm	100-120	Pass	
Brake reservoir	100	mm	100-120	Pass	
Brake caliper	100	mm	100-120	Pass	

Brake and shock absorber report

VEHICLE INFORMATION	
Make/Model	Volkswagen Polo
Year	2017
Registration	2017302498
Chassis No.	WVGZZZAWZNU028131
Color	White
TEST RESULTS	
Item	Value
Engine oil level	40
Shock absorber test	100
Brake test	100
Steering wheel	100
Brake pedal	100
Brake fluid	100
Brake disc	100
Brake pads	100
Brake lines	100
Brake master cylinder	100
Brake booster	100
Brake reservoir	100
Brake caliper	100

Diagnostic report page 1

VEHICLE INFORMATION					
Make/Model	Volkswagen Polo	Year	2017	Engine	1.6 TSI
Registration	2017302498	Chassis No.	WVGZZZAWZNU028131	Color	White
TEST RESULTS					
Item	Value	Unit	Limit	Result	
Engine oil level	40	mm	40-60	Pass	
Shock absorber test	100	mm	100-120	Pass	
Brake test	100	mm	100-120	Pass	
Steering wheel	100	mm	100-120	Pass	
Brake pedal	100	mm	100-120	Pass	
Brake fluid	100	mm	100-120	Pass	
Brake disc	100	mm	100-120	Pass	
Brake pads	100	mm	100-120	Pass	
Brake lines	100	mm	100-120	Pass	
Brake master cylinder	100	mm	100-120	Pass	
Brake booster	100	mm	100-120	Pass	
Brake reservoir	100	mm	100-120	Pass	
Brake caliper	100	mm	100-120	Pass	

Diagnostic report page 2

VEHICLE INFORMATION	
Make/Model	Volkswagen Polo
Year	2017
Engine	1.6 TSI
Registration	2017302498
Chassis No.	WVGZZZAWZNU028131
Color	White
TEST RESULTS	
Item	Value
Engine oil level	40 mm
Shock absorber test	100 mm
Brake test	100 mm
Steering wheel	100 mm
Brake pedal	100 mm
Brake fluid	100 mm
Brake disc	100 mm
Brake pads	100 mm
Brake lines	100 mm
Brake master cylinder	100 mm
Brake booster	100 mm
Brake reservoir	100 mm
Brake caliper	100 mm

Diagnostic report page 3

/volkswagen/16/16V - Poler 2017 - call engine		Test Time: 2024/09/17 08:45:02	Report ID: 86639A3000012304662
130808			
2017302498			
Customer name:			
Technician:			
Date:			
Here Please sign a copy of this report for your records.			

Diagnostic report page 4



FRONT RIGHT CORNER

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZAWZNU028131



CONDITION REPORT



Report No:
2017302498
DATE
23/09/2026



REAR LEFT CORNER



INTERIOR (FRONT DRIVER DOOR)



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



Manual Transmission



90 DEGREE FRONT

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZAWZNU028131



CONDITION REPORT



Report No:

2017302498

DATE


23/09/2026



90 DEGREE RIGHT



90 DEGREE REAR



90 DEGREE LEFT



LF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZAWZNU028131



CONDITION REPORT



Report No:
2017302498
DATE
23/09/2026



RF TYRE TREAD



LICENSE DISC



VIN PLATE OR STICKER



ENGINE 1



Front chassis



Rear chassis

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZAWZNU028131



CONDITION REPORT



Report No:
2017302498
DATE
23/09/2026



Triangle



Oil cap and dipstick



Bonnet



Bonnet



Water level



Bonnet slam plate (Shock tower/ Inner tray)

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZAWZNU028131



CONDITION REPORT



Report No:
2017302498
DATE
23/09/2026



Headlight Right



Water level



Seat Front Right



Seat Rear



Switch Electrical Window Winder rear left



Seat Rear

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZAWZNU028131



CONDITION REPORT



Report No:
2017302498
DATE
23/09/2026



Seat Front Left



Front Fender Left



Hood Lining



Front Fender Right



Door Front Right



Door Rear Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZAWZNU028131



CONDITION REPORT



Report No:
2017302498
DATE
23/09/2026



Door Rear Right



Rear Fender Right



Rear Fender Left



Door Front Left



Side Mirror Right



Rear bumper

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZAWZNU028131



CONDITION REPORT



Report No:
2017302498
DATE
23/09/2026



Rear bumper



Rear bumper



Rear bumper



Back Window



Parcel Tray



Boot Lid / Hatch Door Rubbers

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZAWZNU028131



CONDITION REPORT



Report No:
2017302498
DATE
23/09/2026



Tail Light Left



Sill Panel Right



Control Arm Bush(es) Front Axle Right



Control Arm Bush(es) Front Axle Left



Front Bumper



Front Bumper

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZAWZNU028131




CONDITION REPORT



Report No:
2017302498
DATE
23/09/2026



Front Bumper




Belly plates




Belly plates



Belly plates



Tyre Front Left



Tyre Front Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZAWZNU028131



CONDITION REPORT



Report No:
2017302498
DATE
23/09/2026



Sub Frame



Sub Frame



Engine



Cross Member Rear Right



Fuel Tank



Tyre Rear Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZAWZNU028131




CONDITION REPORT



Report No:
2017302498
DATE
23/09/2026



Tyre Rear Left



Roof

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZAWZNU028131