



## CONDITION REPORT



Report No:  
2017295710  
DATE  
08/09/2026

MFC Auction House  
M57 Pretoria Rd, Glenmarais, KEMPTON PARK  
Gauteng

DEKRA MFC  
M57 Pretoria Rd - 1619  
KEMPTON PARK - GT  
08610 33572



## Assignment

|                 |                   |                     |                          |
|-----------------|-------------------|---------------------|--------------------------|
| Client          | MFC Auction House | Inspection Location | MFC                      |
| Requested Date  | 08/09/2026        |                     | M57 Pretoria Road - 1619 |
| Inspection Date | 08/09/2026        |                     | Kempton Park - GT        |

## Vehicle Data

|                 |                   |                         |              |
|-----------------|-------------------|-------------------------|--------------|
| Vehicle Type    | PASSENGER VEHICLE | Registered Owner        | MFC          |
| Manufacturer    | VOLKSWAGEN        | Registration Number     | HCL866L      |
| Model           | POLO TSI          | Register Number         |              |
| VIN             | AAVZZZAWZPU109927 | Date Of First Licensing |              |
| Engine Number   |                   | Last COR                |              |
| Doors           | 5                 | License Expiry Date     |              |
| Color           | GREY              | Power / Displacement    |              |
| Year Model      |                   | Paint Finish            | M - METALLIC |
| Km Reading      | 110,745 KM        | Fuel                    | PETROL       |
| Cab / Body Type | HATCHBACK         | Transmission            | AUTOMATIC    |

## Vehicle Options &amp; Accessories

## Items

## VEHICLE INSPECTION

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za

VIN: AAVZZZAWZPU109927



## CONDITION REPORT



Report No:

2017295710


DATE

08/09/2026

## Damage

## Repair Way

|                                             |                                                    |
|---------------------------------------------|----------------------------------------------------|
| Front Bumper Paintwork • Scratched          | Repair                                             |
| Bonnet Paintwork • Chipmarks                | Repair                                             |
| Rear Fender Left Paintwork • Scratched      | Repair                                             |
| Rear Fender Right Dented                    | Repair                                             |
| Door Front Left Paintwork • Scratched       | Repair                                             |
| Door Front Right Paintwork • Scratched      | Repair                                             |
| Door Rear Left Dented                       | Repair                                             |
| Door Rear Right Paintwork • Scratched       | Repair                                             |
| Boot Lid / Hatch door Paintwork • Scratched | Repair                                             |
| Rear bumper Paintwork • Scratched           | Repair                                             |
| Windscreen Chipped                          | Repair                                             |
| Body exterior                               | Vehicle got minor scratches, stone chips and dents |



## Brakes

## Brake Test Results

|                     | Left               | Right              |                  |                                  |
|---------------------|--------------------|--------------------|------------------|----------------------------------|
|                     | Braking Force [KN] | Braking Force [KN] | Axle Weight [KG] | Deceleration [m/s <sup>2</sup> ] |
| Front               | 3.1                | 3.1                | -                |                                  |
| Rear                | 2.6                | 2.9                | -                |                                  |
| Emergency / Parking | 1.2                | 1.6                | -                |                                  |

## Tyres and Rims

## Tyre Specification &amp; Measurement

|             | Size      | Load/Speed Index | Manufacture | Model        | Type* | Production Date | Tread Depth (mm) |
|-------------|-----------|------------------|-------------|--------------|-------|-----------------|------------------|
| Front Left  | 215/45R17 | 91W              | Dunlop      | Sp sport     | V     | 2624            | 3 mm             |
| Front Right | 215/45R17 | 91W              | Fronway     | Eurus 08     | V     | 1426            | 3 mm             |
| Rear Left   | 215/45R17 | 91W              | Continental | Contact      | V     | 3523            | 3 mm             |
| Rear Right  | 215/45R17 | 91W              | Continental | Contact      | V     | 3123            | 3 mm             |
| Spare       | 195/65R15 | 88H              | Goodyear    | Efficient gr | V     | 0000            | 3 mm             |

\* Tyre Legend: V=Virgin, R=Recap

DEKRA Automotive (PTY) Ltd.  
 97 Willem Cruywagen Ave  
 Klerksoord, Pretoria, 0200  
 Phone: 012 542 4867  
[www.dekraauto.co.za](http://www.dekraauto.co.za)

VIN: AAVZZAWZPU109927



## CONDITION REPORT



Report No:  
2017295710  
DATE  
08/09/2026

### Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

| No | System           | Code    | Description                             | Status |
|----|------------------|---------|-----------------------------------------|--------|
| 1  | PASSIVE SPORADIC | U140000 | FUNCTION RESTRICTION DUE TO LOW VOLTAGE |        |

### Inspection Conditions

No Test Drive

Battery Flat

Engine number – not possible to verify engine number (not visible without dismantling)

Inspection conditions for the vehicle inspection were sufficient

### Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE EXTERIOR AND INTERIOR ELECTRICAL AND MECHANICAL PARTS.

### Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

### Technician

Andrick Wymers

This document was created electronically and is valid without signature.

#### General Remarks:

The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za

VIN: AAVZZZAWZPU109927



## CONDITION REPORT



Report No:


2017295710

DATE

08/09/2026



LICENSE DISC



VIN PLATE OR STICKER



FRONT RIGHT CORNER



90 DEGREE FRONT



90 DEGREE LEFT



REAR LEFT CORNER

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za

VIN: AAVZZZAWZPU109927



## CONDITION REPORT



**Report No:**  
**2017295710**  
**DATE**  
**08/09/2026**



90 DEGREE REAR



90 DEGREE RIGHT

[illegible]

## Shock and brake report

[illegible]

## Diagnostic report

[illegible]

## Diagnostic report

This is a photograph of a blank, lined page from a notebook. The page is white with horizontal ruling lines and a vertical margin line on the left side. The notebook's binding is visible on the left edge. The page is slightly aged and has some faint smudges.

## Diagnostic report

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
[www.dekraauto.co.za](http://www.dekraauto.co.za)

VIN: AAVZZZAWZPU109927



## CONDITION REPORT



Report No:  
2017295710  
DATE  
08/09/2026



Spare wheel



Expection bottle



Oil cap and dipstick



Automatic



INTERIOR (FRONT DRIVER DOOR)



DASHBOARD (W/ ENGINE RUNNING)

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
[www.dekraauto.co.za](http://www.dekraauto.co.za)

VIN: AAVZZZAWZPU109927



## CONDITION REPORT



Report No:

2017295710

DATE

08/09/2026



ODOMETER




LF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD



RF TYRE TREAD



ENGINE 1

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
[www.dekraauto.co.za](http://www.dekraauto.co.za)

VIN: AAVZZAWZPU109927



## CONDITION REPORT



Report No:  
2017295710  
DATE  
08/09/2026



ENGINE 2



CHASSIS



Windscreen



Water level



Rear Fender Right



Door Rear Right

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksord, Pretoria, 0200  
Phone: 012 542 4867  
[www.dekraauto.co.za](http://www.dekraauto.co.za)

VIN: AAVZZAWZPU109927



## CONDITION REPORT



Report No:

2017295710

DATE

08/09/2026



Door Front Right



Bonnet



Front Bumper



Front Bumper



Door Front Left



Door Rear Left

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksord, Pretoria, 0200  
Phone: 012 542 4867  
[www.dekraauto.co.za](http://www.dekraauto.co.za)

VIN: AAVZZAWZPU109927



## CONDITION REPORT




Report No:  
2017295710  
DATE  
08/09/2026



Rear Fender Left



Boot Lid / Hatch door



Rear bumper



Rear bumper

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za

VIN: AAVZZZAWZPU109927