



CONDITION REPORT



Report No:
2016993104
DATE
27/08/2025

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572

**Assignment**

Client	MFC Auction House	Inspection Location	MFC
Requested Date	29/08/2025		M57 Pretoria Road - 1619
Inspection Date	27/08/2025		Kempton Park - GT

Vehicle Data

Vehicle Type	LIGHT LOAD VEHICLE	Registered Owner	MFC
Manufacturer	CHEVROLET	Registration Number	FY78MDGP
Model	UTILITY 1.4 UTEFORCE EDITION PU [2014-2017]	Register Number	
VIN	ADMCF4MR0J4813797	Date Of First Licensing	
Engine Number		Last COR	
Doors	2	License Expiry Date	31/07/2025
Color	SILVER	Power / Displacement	
Year Model	2017	Paint Finish	TWO COAT METALLIC
Km Reading	43,400 KM	Fuel	PETROL
Cab / Body Type	SINGLE CAB	Transmission	MANUAL

Vehicle Options & Accessories**Items**

VEHICLE INSPECTION

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za


VIN: ADMCF4MR0J4813797



CONDITION REPORT



Report No:
2016993104
DATE
27/08/2025



Damage	Repair Way
Engine Wiring Damaged	Repair
Hoses Damaged	Replace
Radio/CD/USB Damaged	Replace
Center Console / Cubbyhole + Lid Damaged	Replace
Engine Management Lights Set	Repair
Tail Light Left Damaged	Replace
Tail Light Right Damaged	Replace
Headlight Left Damaged	Repair
Headlight Right Damaged	Replace
Front Bumper Damaged	Repair
Bonnet Damaged	Repair
Bonnet slam plate (Shock tower/ Inner tray) Damaged	Repair
A • Pillar Left Damaged	Repair
A • Pillar Right Damaged	Repair
B • Pillar Left Damaged	Replace
B • Pillar Right Damaged	Replace
Front Fender Left Damaged	Repair
Front Fender Right Damaged	Repair
Rear Fender Left Damaged	Repair
Rear Fender Right Damaged	Repair
Front Fender Left / Inner Tray Damaged	Repair
Front Fender Right / Inner Tray Damaged	Repair
Door Front Left Damaged	Repair
Door Front Right Damaged	Repair
Sealing / Rubber Front Door Right Damaged	Repair
Tailgate Damaged	Repair
Rear bumper Damaged	Repair
Sill Panel Right Damaged	Repair
Roof Damaged	Repair
Chassis Welded	Repair

Brakes**Brake Test Results**

	Left	Right	Axle Weight [KG]	Deceleration [m/s ²]
	Braking Force [KN]	Braking Force [KN]		
Front	2.23	2.72	-	
Rear	1.29	1.23	-	
Emergency / Parking	0.93	0.49	-	

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksdorp, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ADMCF4MR0J4813797



CONDITION REPORT



Report No:
2016993104
DATE
27/08/2025

Tyres and Rims**Tyre Specification & Measurement**

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	185/65R14	86H	Goodyear	Duragrip	V	0713	2 mm
Front Right	185/65R14	86H	Goodyear	Duragrip	V	0713	1 mm
Rear Left	185/60R14	82H	Continental	Contieco	V	4206	3 mm
Rear Right	185/60R14	82H	Continental	Contieco	V	0921	3 mm

* Tyre Legend: V=Virgin, R=Recap

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	ENGINE CONTROL MODULE	P0335:00	CAMSHAFT POSITION SENSOR CIRCUIT	

Inspection Conditions

No Test Drive

Battery Flat

Engine number – not possible to verify engine number (not visible without dismantling)

Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS. 8 DTC'S AT TIME OF TESTING SEE DTC REPORT.

Body • Exterior: Minor dents and scratches and stone chips to some body panels. Signs of repair work done to somebody panels. Poor alignment to somebody panels. Repair work done to vehicle below standard. Vehicle body in poor condition. Vehicle is a cut and join.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Werner Laubscher

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksdorp, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za


VIN: ADMCF4MR0J4813797




CONDITION REPORT




Report No:
2016993104
DATE
27/08/2025




Brake test.



Diagnostic.



Diagnostic.



Diagnostic.



FRONT RIGHT CORNER



REAR LEFT CORNER

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksdorp, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ADMCF4MR0J4813797



CONDITION REPORT



Report No:
2016993104
DATE
27/08/2025



INTERIOR (FRONT DRIVER DOOR)



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



Manual.



90 DEGREE FRONT



90 DEGREE RIGHT

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksdorp, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ADMCF4MR0J4813797



CONDITION REPORT



Report No:
2016993104
DATE
27/08/2025



90 DEGREE REAR



90 DEGREE LEFT



LR TYRE TREAD



RR TYRE TREAD



LF TYRE TREAD



RF TYRE TREAD

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ADMCF4MR0J4813797



CONDITION REPORT



Report No:
2016993104
DATE
27/08/2025



LICENSE DISC



VIN PLATE OR STICKER



ENGINE 1



Undercarriage front.



Undercarriage rear.



Oil cap and dipstick.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksdorp, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ADMCF4MR0J4813797




CONDITION REPORT




Report No:
2016993104
DATE
27/08/2025



Water level



Hoses



Hoses



Engine Wiring



Front Bumper



Front Bumper

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksdorp, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ADMCF4MR0J4813797



CONDITION REPORT



Report No:
2016993104
DATE
27/08/2025



Bonnet slam plate (Shock tower/ Inner tray)



Front Fender Right / Inner Tray



Front Fender Left / Inner Tray



Bonnet



Front Fender Left



Door Front Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksdorp, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ADMCF4MR0J4813797



CONDITION REPORT



Report No:
2016993104
DATE
27/08/2025



Rear bumper



Rear bumper



Tailgate



Rear Fender Right



Rear Fender Left



Door Front Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksdorp, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ADMCF4MR0J4813797



CONDITION REPORT



Report No:
2016993104
DATE
27/08/2025



Front Fender Right



A • Pillar Left



A • Pillar Right



B • Pillar Right



B • Pillar Left



Sealing / Rubber Front Door Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksdorp, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ADMCF4MR0J4813797



CONDITION REPORT



Report No:
2016993104
DATE
27/08/2025



A • Pillar Right



Roof



Headlight Right



Headlight Left



Tail Light Left



Tail Light Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ADMCF4MR0J4813797



CONDITION REPORT



Report No:
2016993104
DATE
27/08/2025



Sill Panel Right



Chassis



Chassis



Chassis



Engine Wiring



Center Console / Cubbyhole + Lid

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksdorp, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ADMCF4MR0J4813797



CONDITION REPORT



Report No:
2016993104
DATE
27/08/2025



Radio/CD/USB



Engine Management Lights

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ADMCF4MR0J4813797