



CONDITION REPORT



Report No:
2016927175
DATE
27/06/2025

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572



Assignment

Client	MFC Auction House	Inspection Location	MFC
Requested Date	27/06/2025		M57 Pretoria Road - 1619
Inspection Date	27/06/2025		Kempton Park - GT

Vehicle Data

Vehicle Type	LIGHT LOAD VEHICLE	Registered Owner	MFC
Manufacturer	CHEVROLET	Registration Number	NO REG
Model	UTILITY 1.8 SPORT PU [2011-2017]	Register Number	
VIN	ADMCF80HEC4589523	Date Of First Licensing	
Engine Number		Last COR	
Doors	2	License Expiry Date	30/11/2024
Color	GREY	Power / Displacement	
Year Model	2012	Paint Finish	M - METALLIC
Km Reading	169,420 KM	Fuel	PETROL
Cab / Body Type	SINGLE CAB	Transmission	MANUAL

Vehicle Options & Accessories

Items

VEHICLE INSPECTION

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za


VIN: ADMCF80HEC4589523



CONDITION REPORT



Report No:
2016927175
DATE
27/06/2025



Damage	Repair Way
Engine Oil Leak	Repair
Engine Wiring Damaged	Repair
Air conditioner pump Damaged	Replace
Air cleaner Damaged	Repair
Indicator Light Front Right Missing	Replace
Seat Front Left Torn / Cut	Repair
Seat Front Right Torn / Cut	Repair
Door Panel Front Left Damaged	Repair
Door Panel Front Right Damaged	Repair
Door Sealing Rubber Front Right Missing	Replace
Channel / Roof Gutter Right Damaged	Repair
Side Mirror Left Damaged	Repair
Front Bumper Damaged	Repair
Bonnet Residual Traces of Repair	Repair
A • Pillar Right Welded	Repair
Front Fender Left Residual Traces of Repair	Repair
Front Fender Right Residual Traces of Repair	Repair
Door Front Left Residual Traces of Repair	Repair
Door Front Right Residual Traces of Repair	Repair
Tailgate Damaged	Replace
Roof Residual Traces of Repair	Repair
Load Body Residual Traces of Repair	Repair
Windscreen Cracked	Replace
Shock Absorber Rear Left Leak	Replace
Tyre Front Right Smooth	Replace
Spare Tyre Smooth	Replace
Bolt(s) / Nut(s) Rear Wheel Left Missing	Replace
Main Beam Left Welded	Repair
Main Beam Right Welded	Repair
Cross Member Front Right Damaged	Replace
Engine to silencer pipe Welded	Replace
Gearbox Grease Leak	Repair
CV Joint(s) Boot(s) Front Left (inner/outer) Damaged	Replace
Radiator Cradle Welded	Repair
Gear Selections Insufficient	Repair
Vehicle struggling to start	Electronics malfunction
Body exterior	Residual traces of poor repair on most body panels
Body exterior	Signs of spray work done on most body panels
No battery	Replace
ABS warning lights illuminated	Repair
engine water leak.	Repair
No reverse gear	Repair

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ADMCF80HEC4589523



CONDITION REPORT



Report No:
2016927175
DATE
27/06/2025

Brakes

Brake Test Results

No Brake Test on a brake test machine has been performed.

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s ²]
Front	-	-	-	
Rear	-	-	-	
Emergency / Parking	-	-	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	195/65R15	91H	Goodyear	Excellence	V	4317	1 mm
Front Right	185/65R15	88H	Symmetry	SY101	V	0000	0 mm
Rear Left	195/50R15	82V	Sava	Intensta	V	0217	1 mm
Rear Right	195/65R15	91H	Hankook	Kinergy	V	4121	1 mm
Spare	185/60R15	84H	Bridgestone	Ecopia	V	0000	0 mm

* Tyre Legend: V=Virgin, R=Recap

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	ELECTRONIC BRAKE CONTROL MODULE	C0035:00	LEFT FRONT WHEEL SPEED SENSOR CIRCUIT	

Inspection Conditions

No Test Drive
Vehicle doesn't start
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Trevino Julius

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ADMCF80HEC4589523

**CONDITION REPORT**

Report No:
2016927175
DATE
27/06/2025

strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ADMCF80HEC4589523




CONDITION REPORT



Report No:
2016927175
DATE
27/06/2025



Diagnostic test



Diagnostic test



FRONT RIGHT CORNER



REAR LEFT CORNER



INTERIOR (FRONT DRIVER DOOR)



DASHBOARD (W/ ENGINE RUNNING)

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ADMCF80HEC4589523



CONDITION REPORT



Report No:
2016927175
DATE
27/06/2025



ODOMETER



Manual



90 DEGREE FRONT



90 DEGREE RIGHT



90 DEGREE REAR



90 DEGREE LEFT

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za


VIN: ADMCF80HEC4589523



CONDITION REPORT




Report No:
2016927175
DATE
27/06/2025




LF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD



RF TYRE TREAD



Sparewheel



LICENSE DISC

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ADMCF80HEC4589523



CONDITION REPORT



Report No:
2016927175
DATE
27/06/2025



VIN PLATE OR STICKER



ENGINE 1



ENGINE 2



CHASSIS



Rear



No battery

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ADMCF80HEC4589523



CONDITION REPORT



Report No:
2016927175
DATE
27/06/2025



Expansion bottle



timing belt cover machine



Oil cap and dipstick



ABS warning lights



Seat Front Right



Door Sealing Rubber Front Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ADMCF80HEC4589523



CONDITION REPORT



Report No:
2016927175
DATE
27/06/2025



Door Sealing Rubber Front Right



Door Sealing Rubber Front Right



A • Pillar Right



A • Pillar Right



Seat Front Left



Door Panel Front Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ADMCF80HEC4589523



CONDITION REPORT




Report No:
2016927175
DATE
27/06/2025



Door Panel Front Right



Indicator Light Front Right



Front Fender Right



Door Front Right



Channel / Roof Gutter Right



Roof

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ADMCF80HEC4589523



CONDITION REPORT



Report No:
2016927175
DATE
27/06/2025



Load Body



Load Body



Tailgate



Load Body



Load Body



Windscreen

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ADMCF80HEC4589523



CONDITION REPORT



Report No:
2016927175
DATE
27/06/2025



Door Front Left



Side Mirror Left



Front Fender Left



Bonnet



Spare Tyre



Tyre Front Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ADMCF80HEC4589523



CONDITION REPORT



Report No:
2016927175
DATE
27/06/2025



Tyre Front Right



Main Beam Right



Main Beam Right



Main Beam Right



Front Bumper



Front Bumper

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ADMCF80HEC4589523



CONDITION REPORT



Report No:
2016927175
DATE
27/06/2025



Main Beam Left



Bolt(s) / Nut(s) Rear Wheel Left



Engine



Engine



Engine



Engine

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za


VIN: ADMCF80HEC4589523



CONDITION REPORT



Report No:
2016927175
DATE
27/06/2025



Engine Wiring



Engine Wiring



Engine Wiring



Engine Wiring



Air conditioner pump



Main Beam Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ADMCF80HEC4589523



CONDITION REPORT



Report No:
2016927175
DATE
27/06/2025



Main Beam Right



Radiator Cradle



Radiator Cradle



Radiator Cradle



Radiator Cradle



Radiator Cradle

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ADMCF80HEC4589523



CONDITION REPORT



Report No:
2016927175
DATE
27/06/2025



Gearbox



Gearbox



CV Joint(s) Boot(s) Front Left (inner/outer)



Cross Member Front Right



Engine to silencer pipe



Engine to silencer pipe

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ADMCF80HEC4589523



CONDITION REPORT



Report No:
2016927175
DATE
27/06/2025



Engine to silencer pipe



Shock Absorber Rear Left



Water level



Engine Wiring



Main Beam Left



Air cleaner

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ADMCF80HEC4589523



CONDITION REPORT



Report No:
2016927175
DATE
27/06/2025



Air cleaner



Engine Wiring

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ADMCF80HEC4589523