



CONDITION REPORT



Report No:

2017305034

DATE

29/09/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572



Assignment

Client	MFC Auction House	Inspection Location	MFC
Requested Date	29/09/2026		M57 Pretoria Road - 1619
Inspection Date	29/09/2026		Kempton Park -

Vehicle Data

Vehicle Type	LIGHT LOAD VEHICLE	Registered Owner	MFC
Manufacturer	NISSAN	Registration Number	LLV585MP
Model	NP200 1.6 8V BASE +AC PU [2011-2019]	Register Number	
VIN	ADNUSN1D5U0145117	Date Of First Licensing	
Engine Number		Last COR	
Doors	2	License Expiry Date	31/12/2026
Color	WHITE	Power / Displacement	
Year Model	2018	Paint Finish	TWO COAT UNI
Km Reading	232,591 KM	Fuel	PETROL
Cab / Body Type	SINGLE CAB	Transmission	MANUAL

Vehicle Options & Accessories

Items

VEHICLE INSPECTION

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za


VIN: ADNUSN1D5U0145117



CONDITION REPORT



Report No:
2017305034
DATE
29/09/2026



Damage	Repair Way
Engine Oil Sweat	Repair
Engine Wiring Defective	Repair
Radiator Water Leak	Replace
Ref Counter Damaged	Replace
Heater control Damaged	Replace
Tail Light Left Defective	Repair
Tail Light Right Defective	Repair
Number Plate Light Left Damaged	Replace
Number Plate Light Right Damaged	Replace
Seat Front Left Damaged	Repair
Seat Front Right Damaged	Repair
Hood Lining Dirty	Repair
Door Sealing Rubber Front Left Damaged	Replace
Door Lock Front Right Damaged	Replace
Carpet Front Damaged	Repair
Mirror Adjusters Missing	Replace
Steering Wheel Trim Excessive Wear & Tear	Repair
Side Mirror Right Damaged	Replace
Front Bumper Damaged	Replace
Grill Paintwork • Scratched	Repair
Bonnet Paintwork • Scratched	Repair
A • Pillar Left Damaged	Repair
Front Fender Left Damaged	Repair
Rear Fender Left Residual Traces of Repair	Repair
Rear Fender Right Paintwork • Scratched	Repair
Front Fender Left / Inner Tray Damaged	Replace
Front Fender Right / Inner Tray Damaged	Replace
Door Front Left Residual Traces of Repair	Repair
Door Front Right Damaged	Repair
Tailgate Damaged	Repair
Rear bumper Damaged	Repair
Load Body Damaged	Repair
Windscreen Cracked	Replace
Brake Drum 2. Axle left Damaged	Replace
Service Brake Performance Rear Axle Left / Right	Repair
Difference out of legal range	Repair
Tie Rod End left Damaged	Replace
Steering Rack Boot Left Sweat	Replace
Stabilizer Mounting Front Left Damaged	Replace
Stabilizer Mounting Front Right Damaged	Replace
Mounting Rubber(s) Rear Axle Left Cracked	Replace
Mounting Rubber(s) Rear Axle Right Cracked	Replace
Tyre Rear Left Damaged	Replace
Tyre Rear Right Worn	Replace
Spare Tyre Damaged	Replace
Rim Front Right Dented	Repair
Rim Rear Left Dented	Repair
Rim Rear Right Dented	Repair
Rim Spare Wheel Dented	Repair
Main Beam Left Damaged	Repair
Chassis Damaged	Repair
Engine to silencer pipe Welded	Repair
Catalytic converter Damaged	Replace
Belly plates Damaged	Repair
Gearbox Oil Leak	Repair
CV Joint(s) Boot(s) Front Left (inner/outer) Damaged	Replace

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ADNUSN1D5U0145117



CONDITION REPORT



Report No:
2017305034
DATE
29/09/2026

Damage

Repair Way

Radiator Cradle Dented
Engine Performance Insufficient
Engine Noise Idling / Hunting
Gearbox Noise Excessive
Jack Missing
Wheel Spanner Missing
Triangle Missing
Foreign substance on oil cap
Aircon condenser dented
Front bumper stiffener damaged

Repair
Repair
Repair
Repair
Replace
Replace
Replace
Repair
Repair
Repair

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s ²]
Front	2.93	2.27	-	
Rear	1.06	3.12	-	
Emergency / Parking	1.39	1.18	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	185/65 R15	88H	Powertrac	Eco Comfort	V	0623	2 mm
Front Right	185/65 R15	88H	Powertrac	Eco Comfort	V	0626	2 mm
Rear Left	185/65 R15	88H	Annaite	Anchee	V	3125	0 mm
Rear Right	185/65 R15	88T	Annaite	Anchee	V	3125	0 mm
Spare	185/65 R15	88H	Rapid	ECO809	V	3424	0 mm

* Tyre Legend: V=Virgin, R=Recap

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	BCM	040000	PLEASE REFER TO VEHICLE SERVICE MANUAL.	

Inspection Conditions

No Test Drive
Rain at time of inspection
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ADNUSN1D5U0145117



CONDITION REPORT



Report No:
2017305034
DATE
29/09/2026

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS. Interior: Vehicle interior dirty and panels scratched. Non standard sound fitted to vehicle.

Body • Exterior: Left tailgate stay cable missing. Poor residual traces of repair on body panels. Body panels misaligned. Stone chips and spray work on body panels. Dents and scratches on body panels. Signs of impact damage to front and rear of vehicle.

Undercarriage: Front catalytic converter missing. Engine splash plate missing.

Road Test: Vehicle struggles to start. Gearbox faulty.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Sibusiso Mokase

This document was created electronically and is valid without signature.

General Remarks:

The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ADNUSN1D5U0145117



CONDITION REPORT



Report No:

2017305034

DATE _____

29/09/2026

Car		Motorcycle		Car	
Name/No.		Name/No.		Name/No.	
Zip code, city		Zip code, city		Zip code, city	
Telephone		Telephone		Telephone	
E-mail		E-mail		E-mail	
1st vehicle	2002/2003	1st vehicle	2000/2001	1st vehicle	2000/2001
2nd vehicle	2003	2nd vehicle	2001	2nd vehicle	2000/2001
3rd vehicle		3rd vehicle		3rd vehicle	
4th vehicle		4th vehicle		4th vehicle	
5th vehicle		5th vehicle		5th vehicle	
6th vehicle		6th vehicle		6th vehicle	
7th vehicle		7th vehicle		7th vehicle	
8th vehicle		8th vehicle		8th vehicle	
9th vehicle		9th vehicle		9th vehicle	
10th vehicle		10th vehicle		10th vehicle	
11th vehicle		11th vehicle		11th vehicle	
12th vehicle		12th vehicle		12th vehicle	
13th vehicle		13th vehicle		13th vehicle	
14th vehicle		14th vehicle		14th vehicle	
15th vehicle		15th vehicle		15th vehicle	
16th vehicle		16th vehicle		16th vehicle	
17th vehicle		17th vehicle		17th vehicle	
18th vehicle		18th vehicle		18th vehicle	
19th vehicle		19th vehicle		19th vehicle	
20th vehicle		20th vehicle		20th vehicle	
21st vehicle		21st vehicle		21st vehicle	
22nd vehicle		22nd vehicle		22nd vehicle	
23rd vehicle		23rd vehicle		23rd vehicle	
24th vehicle		24th vehicle		24th vehicle	
25th vehicle		25th vehicle		25th vehicle	
26th vehicle		26th vehicle		26th vehicle	
27th vehicle		27th vehicle		27th vehicle	
28th vehicle		28th vehicle		28th vehicle	
29th vehicle		29th vehicle		29th vehicle	
30th vehicle		30th vehicle		30th vehicle	
31st vehicle		31st vehicle		31st vehicle	
32nd vehicle		32nd vehicle		32nd vehicle	
33rd vehicle		33rd vehicle		33rd vehicle	
34th vehicle		34th vehicle		34th vehicle	
35th vehicle		35th vehicle		35th vehicle	
36th vehicle		36th vehicle		36th vehicle	
37th vehicle		37th vehicle		37th vehicle	
38th vehicle		38th vehicle		38th vehicle	
39th vehicle		39th vehicle		39th vehicle	
40th vehicle		40th vehicle		40th vehicle	
41st vehicle		41st vehicle		41st vehicle	
42nd vehicle		42nd vehicle		42nd vehicle	
43rd vehicle		43rd vehicle		43rd vehicle	
44th vehicle		44th vehicle		44th vehicle	
45th vehicle		45th vehicle		45th vehicle	
46th vehicle		46th vehicle		46th vehicle	
47th vehicle		47th vehicle		47th vehicle	
48th vehicle		48th vehicle		48th vehicle	
49th vehicle		49th vehicle		49th vehicle	
50th vehicle		50th vehicle		50th vehicle	
51st vehicle		51st vehicle		51st vehicle	
52nd vehicle		52nd vehicle		52nd vehicle	
53rd vehicle		53rd vehicle		53rd vehicle	
54th vehicle		54th vehicle		54th vehicle	
55th vehicle		55th vehicle		55th vehicle	
56th vehicle		56th vehicle		56th vehicle	
57th vehicle		57th vehicle		57th vehicle	
58th vehicle		58th vehicle		58th vehicle	
59th vehicle		59th vehicle		59th vehicle	
60th vehicle		60th vehicle		60th vehicle	
61st vehicle		61st vehicle		61st vehicle	
62nd vehicle		62nd vehicle		62nd vehicle	
63rd vehicle		63rd vehicle		63rd vehicle	
64th vehicle		64th vehicle		64th vehicle	
65th vehicle		65th vehicle		65th vehicle	
66th vehicle		66th vehicle		66th vehicle	
67th vehicle		67th vehicle		67th vehicle	
68th vehicle		68th vehicle		68th vehicle	
69th vehicle		69th vehicle		69th vehicle	
70th vehicle		70th vehicle		70th vehicle	
71st vehicle		71st vehicle		71st vehicle	
72nd vehicle		72nd vehicle		72nd vehicle	
73rd vehicle		73rd vehicle		73rd vehicle	
74th vehicle		74th vehicle		74th vehicle	
75th vehicle		75th vehicle		75th vehicle	
76th vehicle		76th vehicle		76th vehicle	
77th vehicle		77th vehicle		77th vehicle	
78th vehicle		78th vehicle		78th vehicle	
79th vehicle		79th vehicle		79th vehicle	
80th vehicle		80th vehicle		80th vehicle	
81st vehicle		81st vehicle		81st vehicle	
82nd vehicle		82nd vehicle		82nd vehicle	
83rd vehicle		83rd vehicle		83rd vehicle	
84th vehicle		84th vehicle		84th vehicle	
85th vehicle		85th vehicle		85th vehicle	
86th vehicle		86th vehicle		86th vehicle	
87th vehicle		87th vehicle		87th vehicle	
88th vehicle		88th vehicle		88th vehicle	
89th vehicle		89th vehicle		89th vehicle	
90th vehicle		90th vehicle		90th vehicle	
91st vehicle		91st vehicle		91st vehicle	
92nd vehicle		92nd vehicle		92nd vehicle	
93rd vehicle		93rd vehicle		93rd vehicle	
94th vehicle		94th vehicle		94th vehicle	
95th vehicle		95th vehicle		95th vehicle	
96th vehicle		96th vehicle		96th vehicle	
97th vehicle		97th vehicle		97th vehicle	
98th vehicle		98th vehicle		98th vehicle	
99th vehicle		99th vehicle		99th vehicle	
100th vehicle		100th vehicle		100th vehicle	

Brake and shock absorber report

[illegible]

Diagnostic report



FRONT RIGHT CORNER



REAR LEFT CORNER



INTERIOR (FRONT DRIVER DOOR)



DASHBOARD (W/ ENGINE RUNNING)

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ADNUSN1D5U0145117



CONDITION REPORT



Report No:

2017305034

DATE

29/09/2026



ODOMETER



Manual Transmission



90 DEGREE FRONT



90 DEGREE RIGHT



90 DEGREE REAR



90 DEGREE LEFT

DEKRA Automotive (PTY) Ltd.
 97 Willem Cruywagen Ave
 Klerksoord, Pretoria, 0200
 Phone: 012 542 4867
www.dekraauto.co.za

VIN: ADNUSN1D5U0145117



CONDITION REPORT



Report No:
2017305034
DATE
29/09/2026



LF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD



RF TYRE TREAD



Spare Wheel



LICENSE DISC

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ADNUSN1D5U0145117



CONDITION REPORT



Report No:

2017305034

DATE

29/09/2026



VIN PLATE OR STICKER



ENGINE 1



Front Chassis



Rear chassis



Oil cap and dipstick



Front bumper stiffener

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ADNUSN1D5U0145117



CONDITION REPORT



Report No:

2017305034

DATE

29/09/2026



Aircon condenser




Steering Wheel Trim



Ref Counter



Seat Front Right



Carpet Front



Rear Fender Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ADNUSN1D5U0145117



CONDITION REPORT



Report No:

2017305034

DATE

29/09/2026



Door Front Left



Front Fender Left



Door Front Left



Seat Front Left



Door Sealing Rubber Front Left



Windscreen

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ADNUSN1D5U0145117



CONDITION REPORT



Report No:

2017305034

DATE

29/09/2026



Rear Fender Right



Rear Fender Right



Door Front Right



Side Mirror Right



Rear bumper



Rear bumper

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ADNUSN1D5U0145117



CONDITION REPORT



Report No:


2017305034

DATE

29/09/2026



Tailgate



Tail Light Right



Tail Light Left



Rim Spare Wheel



Spare Tyre



Number Plate Light Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ADNUSN1D5U0145117



CONDITION REPORT



Report No:
2017305034
DATE
29/09/2026



Number Plate Light Right

Brake test					
	Brake force		Difference	Quality	
	left	right		left	right
Front axle	2,50 kN	2,27 kN	23 %	— %	— %
Parking brake	1,39 kN	1,15 kN	15 %	— %	— %
Rear axle	1,06 kN	1,12 kN	66 %	92 %	97 %
Final evaluation static					
Deceleration service brake		63 %			
Deceleration parking brake		17 %			
				Total weight	1507 kg

Service Brake Performance Rear Axle



Bonnet



Bonnet



Grill



Water level

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ADNUSN1D5U0145117



CONDITION REPORT



Report No:

2017305034

DATE

29/09/2026



Rim Front Right



Front Fender Right / Inner Tray



Front Bumper



Front Bumper



Front Bumper



A • Pillar Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ADNUSN1D5U0145117



CONDITION REPORT



Report No:

2017305034

DATE

29/09/2026



Front Fender Left / Inner Tray



Brake Drum 2. Axle left



Rim Rear Left



Rim Rear Right



Stabilizer Mounting Front Right



Stabilizer Mounting Front Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ADNUSN1D5U0145117



CONDITION REPORT



Report No:
2017305034
DATE
29/09/2026



Gearbox



CV Joint(s) Boot(s) Front Left (inner/outer)



Tie Rod End left



Catalytic converter



Engine to silencer pipe



Radiator

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ADNUSN1D5U0145117



CONDITION REPORT



Report No:
2017305034
DATE
29/09/2026



Engine



Chassis



Chassis



Belly plates



Engine Wiring



Mounting Rubber(s) Rear Axle Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ADNUSN1D5U0145117



CONDITION REPORT



Report No:

2017305034

DATE

29/09/2026



Mounting Rubber(s) Rear Axle Left



Tyre Rear Right



Tyre Rear Left



Load Body



Main Beam Left



Belly plates

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ADNUSN1D5U0145117



CONDITION REPORT



Report No:
2017305034
DATE
29/09/2026




Radiator Cradle



Steering Rack Boot Left



Door Lock Front Right



Water level



Mirror Adjusters



Heater control

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ADNUSN1D5U0145117



CONDITION REPORT



Report No:
2017305034
DATE
29/09/2026



Hood Lining

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ADNUSN1D5U0145117