



CONDITION REPORT



Report No:
2016960583
DATE
28/07/2025

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572



Assignment

Client	MFC Auction House	Inspection Location	MFC
Requested Date	28/07/2025		M57 Pretoria Road - 1619
Inspection Date	28/07/2025		Kempton Park - GT

Vehicle Data

Vehicle Type	LIGHT LOAD VEHICLE	Registered Owner	MFC
Manufacturer	NISSAN	Registration Number	BK47VKZN
Model	NP200 1.6 8V BASE +AC SAFETY PU [2011-ON]	Register Number	
VIN	ADNUSN1D5U0180163	Date Of First Licensing	
Engine Number		Last COR	
Doors	2	License Expiry Date	31/03/2025
Color	WHITE	Power / Displacement	
Year Model	2020	Paint Finish	TWO COAT UNI
Km Reading	86,538 KM	Fuel	PETROL
Cab / Body Type	SINGLE CAB	Transmission	MANUAL

Vehicle Options & Accessories

Items

VEHICLE INSPECTION

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za


VIN: ADNUSN1D5U0180163



CONDITION REPORT



Report No:
2016960583
DATE
28/07/2025



Damage

Repair Way

Seat Front Right Damaged	Repair
Side Mirror Right Paintwork • Scratched	Repair
Front Bumper Paintwork • Scratched	Repair
Bonnet Dented	Repair
Front Fender Left Dented	Repair
Front Fender Right Paintwork • Scratched	Repair
Rear Fender Left Damaged	Repair
Rear Fender Right Paintwork • Scratched	Repair
Door Front Left Paintwork • Scratched	Repair
Door Front Right Dented	Repair
Tailgate Damaged	Repair
Rear bumper Damaged	Repair
Load Body Dented	Repair
Tie Rod End right Damaged	Replace
Tyre Front Left Torn / Cut	Replace
Chassis Dented	Repair
Gearbox Oil Sweat	Repair
Jack Missing	Replace
Wheel Spanner Missing	Replace
Triangle Missing	Replace
Engine	Engine bay dirty.
Undercarriage	Vehicle undercarriage dirty
Undercarriage	Bottom of engine and gearbox covered
Body and Exterior	Dents and scratches on some body panels
Tyres and rims	Front and rear hubcaps scratched.
Tyres and rims	Spare wheel missing
Interior	Fuel flap release handle not opening

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s ²]
Front	2.69	2.66	-	
Rear	1.56	1.44	-	
Emergency / Parking	1.52	1.87	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	185/65 R15	88H	Voyager	Radial	V	0219	2 mm
Front Right	185/65 R15	88H	Encore	Reflex	V	2020	1 mm
Rear Left	185/65 R15	92T	Barum	Brillantis	V	4719	1 mm
Rear Right	185/65 R15	92T	Barum	Brillantis	V	4719	1 mm

* Tyre Legend: V=Virgin, R=Recap

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ADNUSN1D5U0180163



CONDITION REPORT



Report No:
2016960583
DATE
28/07/2025

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	AIR BAG	B1042	ECU SUPPLY VOLTAGE	

Inspection Conditions

No Test Drive

Battery Flat

Engine number – not possible to verify engine number (not visible without dismantling)

Inspection conditions for the vehicle inspection were sufficient

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Sibusiso Mokase

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ADNUSN1D5U0180163



CONDITION REPORT



Report No:
2016960583
DATE
28/07/2025

VEHICLE INFORMATION			
Client	Car	Customer name	SAUTERZ
Model	SAUTERZ	Registration	8473
Chassis no.	SAUTERZ	Manufacturer	SAUTERZ
Year built	2013	Model	SAUTERZ
Test result	130	VIN	ADNUSN1D5U0180163
STEERING			
Steering wheel	1.5 m/s	Steering axis	1.5 m/s
Steering wheel	1.5 m/s	Steering axis	1.5 m/s
SHOCK ABSORBER TEST			
Shock absorber test	0.02	Shock absorber test	0.02
Shock absorber test	0.02	Shock absorber test	0.02
BRAKE TEST			
Brake test	0.02	Brake test	0.02
Brake test	0.02	Brake test	0.02

Brake and shock absorber repor

VEHICLE INFORMATION			
Client	Car	Customer name	SAUTERZ
Model	SAUTERZ	Registration	8473
Chassis no.	SAUTERZ	Manufacturer	SAUTERZ
Year built	2013	Model	SAUTERZ
Test result	130	VIN	ADNUSN1D5U0180163
STEERING			
Steering wheel	1.5 m/s	Steering axis	1.5 m/s
Steering wheel	1.5 m/s	Steering axis	1.5 m/s
SHOCK ABSORBER TEST			
Shock absorber test	0.02	Shock absorber test	0.02
Shock absorber test	0.02	Shock absorber test	0.02
BRAKE TEST			
Brake test	0.02	Brake test	0.02
Brake test	0.02	Brake test	0.02

Diagnostic report



FRONT RIGHT CORNER



REAR LEFT CORNER



INTERIOR (FRONT DRIVER DOOR)



DASHBOARD (W/ ENGINE RUNNING)

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ADNUSN1D5U0180163



CONDITION REPORT



Report No:
2016960583
DATE
28/07/2025



ODOMETER



Manual Transmission



90 DEGREE FRONT



90 DEGREE RIGHT



90 DEGREE REAR



90 DEGREE LEFT

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ADNUSN1D5U0180163



CONDITION REPORT




Report No:
2016960583
DATE
28/07/2025



LF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD



RF TYRE TREAD



LICENSE DISC



VIN PLATE OR STICKER

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ADNUSN1D5U0180163



CONDITION REPORT



Report No:
2016960583
DATE
28/07/2025



ENGINE 1



Front chassis



Rear chassis



Oil cap and dipstick



Seat Front Right



Rear Fender Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ADNUSN1D5U0180163



CONDITION REPORT



Report No:
2016960583
DATE
28/07/2025



Door Front Left




Front Fender Left



Rear Fender Right



Door Front Right



Front Fender Right



Side Mirror Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ADNUSN1D5U0180163



CONDITION REPORT



Report No:
2016960583
DATE
28/07/2025



Front Bumper



Front Bumper



Bonnet



Rear bumper



Rear bumper



Tailgate

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ADNUSN1D5U0180163



CONDITION REPORT



Report No:
2016960583
DATE
28/07/2025



Tailgate



Load Body



Water level



Tyre Front Left



Tie Rod End right



Chassis

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ADNUSN1D5U0180163



CONDITION REPORT



Report No:
2016960583
DATE
28/07/2025



Gearbox

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ADNUSN1D5U0180163