

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572



Assignment

Client	MFC Auction House	Inspection Location	MFC
Requested Date	28/05/2025		M57 Pretoria Road - 1619
Inspection Date	28/05/2025		Kempton Park - GT

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	
Manufacturer	RENAULT	Registration Number	CX11VNGP
Model	SANDERO 1.6I STEPWAY 5-DR [2013-2015]	Register Number	
VIN	ADRB5RAFKUK410748	Date Of First Licensing	
Engine Number		Last COR	
Doors	5	License Expiry Date	31/01/2025
Color	WHITE	Power / Displacement	
Year Model	2013	Paint Finish	TWO COAT UNI
Km Reading	142,275 KM	Fuel	PETROL
Cab / Body Type	HATCHBACK	Transmission	MANUAL

Vehicle Options & Accessories

Items

VEHICLE INSPECTION

Damage	Repair Way
Fan Belt Defective	Replace
Radio/CD/USB Damaged	Replace
Windscreen Wiper Damaged	Replace
Windscreen Washer Damaged	Replace
Tail Light Left Cracked	Replace
Brake Light Centre Defective	Repair
Headlight Left Defective	Replace
Headlight Right Defective	Replace
Seat Front Left Damaged	Repair
Seat Front Right Damaged	Repair
Seat Rear Damaged	Repair
Door Lock Front Right Damaged	Replace
Parcel Tray Damaged	Repair
Side Mirror Left Paintwork • Scratched	Repair
Side Mirror Right Paintwork • Scratched	Repair
Front Bumper Damaged	Repair
Bonnet Paintwork • Scratched	Repair
C • Pillar Right Damaged	Repair
Front Fender Left Damaged	Repair
Front Fender Right Damaged	Repair

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ADRB5RAFKUK410748

Damage	Repair Way
Rear Fender Left Paintwork • Scratched	Repair
Rear Fender Right Damaged	Repair
Door Front Left Damaged	Repair
Door Front Right Damaged	Repair
Door Rear Left Damaged	Repair
Door Rear Right Damaged	Repair
Doorstopper Rear Left Defective	Repair
Boot Lid / Hatch door Damaged	Repair
Rear bumper Damaged	Repair
Inner Boot Floor Pan and Spare Wheel Well Damaged	Repair
Sill Panel Left Damaged	Repair
Roof Dented	Repair
Windscreen Cracked	Replace
Speed Sensor Damaged	Replace
Steering Rack Boot Right Damaged	Replace
Shock Absorber Front Left Damaged	Replace
Stabilizer Mounting Front Right Missing	Replace
Control Arm(s) Front Axle Right Welded	Replace
Tyre Front Left Worn	Replace
Tyre Front Right Worn	Replace
Tyre Rear Left Damaged	Replace
Tyre Rear Right Damaged	Replace
Spare Tyre Damaged	Replace
Rim Front Left Scratched	Repair
Rim Front Right Scratched	Repair
Rim Rear Left Scratched	Repair
Rim Spare Wheel Dented	Repair
Bolt(s) / Nut(s) Front Wheel Right Missing	Replace
Bolt(s) / Nut(s) Rear Wheel Left Missing	Replace
Bolt(s) / Nut(s) Rear Wheel Right Missing	Replace
Chassis Damaged	Repair
Silencer Damaged	Replace
Belly plates Damaged	Repair
Gearbox Oil Leak	Repair
CV Joint(s) Front Left (inner/outer) Defective	Replace
CV Joint(s) Front Right (inner/outer) Defective	Repair
CV Joint(s) Boot(s) Front Right (inner/outer) Damaged	Replace
Engine Noise Excessive	Repair
Clutch Operation Incorrect	Repair
Jack Missing	Replace
Warning lights illuminated on dashboard	Repair
Front left and right shock absorbers weak	Replace
Engine	Engine bay dirty.
Road test	Vehicle unsafe to drive
Undercarriage	Bottom of engine and gearbox covered
Interior	Vehicle interior dirty and some panels scratched
Body and Exterior	Dents and scratches on some body panels
Body and Exterior	Some body panels misaligned
Axle and suspension	Front suspension faulty
Tyres and rims	Front and rear tyre sizes different

Brakes

Brake Test Results

	Left	Right	Axle Weight [KG]	Deceleration [m/s ²]
	Braking Force [KN]	Braking Force [KN]		
Front	2.62	2.19	-	
Rear	1.67	1.65	-	
Emergency / Parking	1.17	1.06	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	205/60 R16	92V	Colo	Grenlader	V	4418	0 mm
Front Right	205/60 R16	92H	Continental	ComtiEco	V	2218	0 mm
Rear Left	205/55 R16	91V	Lanvigator	Comfort	V	0122	0 mm
Rear Right	205/55 R16	91V	Goodyear	Efficient	V	2618	0 mm
Spare	155R13LT	90P	Bridgestone	Duravis	V	1614	0 mm

* Tyre Legend: V=Virgin, R=Recap

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	INJECTION	DF124	DESTRUCTIVE MISFIRE	

Inspection Conditions

No Test Drive

Battery Flat

Engine number – not possible to verify engine number (not visible without dismantling)

Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.

Concluding Remarks






THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Sibusiso Mokase

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.





INTERIOR (FRONT DRIVER DOOR)



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



Manual Transmission



90 DEGREE FRONT



90 DEGREE RIGHT



90 DEGREE REAR



90 DEGREE LEFT



LF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD



RF TYRE TREAD



Spare wheel and Accessories



LICENSE DISC



VIN PLATE OR STICKER



ENGINE 1



Front chassis



Rear Chassis



Oil cap and dipstick



Seat Front Right



C • Pillar Right



Seat Rear



Rear Fender Right



Door Rear Right



Door Front Right



Front Fender Right



Side Mirror Right



Front Bumper



Front Bumper



Bonnet



Windscreen



Headlight Right



Headlight Left



Windscreen Wiper



Front Fender Left



Side Mirror Left



Door Front Left



Door Rear Left



Rear Fender Left



Side Mirror Left



Seat Front Left



Doorstopper Rear Left



Rear bumper




Rear bumper



Boot Lid / Hatch door



Roof



Windscreen Wiper



Spare Tyre



Inner Boot Floor Pan and Spare Wheel Well



Rim Spare Wheel



Parcel Tray



Brake Light Centre



Tail Light Left



Rim Front Right



Bolt(s) / Nut(s) Front Wheel Right



Bolt(s) / Nut(s) Rear Wheel Right



Tyre Rear Right



Rim Rear Left



Bolt(s) / Nut(s) Rear Wheel Left



Sill Panel Left



Rim Front Left



Belly plates



Tyre Front Right



Stabilizer Mounting Front Right



Gearbox



CV Joint(s) Boot(s) Front Right (inner/outer)



CV Joint(s) Boot(s) Front Right (inner/outer)



Control Arm(s) Front Axle Right



Steering Rack Boot Right



Tyre Front Left



Fan Belt



Speed Sensor



CV Joint(s) Front Right (inner/outer)



CV Joint(s) Front Left (inner/outer)



Chassis



Tyre Rear Right



Tyre Rear Left



Silencer



Water level



Windscreen Washer



Shock Absorber Front Left



Radio/CD/USB



Door Lock Front Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ADRBSRAFKUK410748