



## CONDITION REPORT



Report No:  
2017303138  
DATE  
25/09/2026

MFC Auction House  
M57 Pretoria Rd, Glenmarais, KEMPTON PARK  
Gauteng

DEKRA MFC  
M57 Pretoria Rd - 1619  
KEMPTON PARK - GT  
08610 33572



## Assignment

|                 |                   |                     |                          |
|-----------------|-------------------|---------------------|--------------------------|
| Client          | MFC Auction House | Inspection Location | MFC                      |
| Requested Date  | 25/09/2026        |                     | M57 Pretoria Road - 1619 |
| Inspection Date | 25/09/2026        |                     | Kempton Park - GT        |

## Vehicle Data

|                 |                                               |                         |                   |
|-----------------|-----------------------------------------------|-------------------------|-------------------|
| Vehicle Type    | LIGHT LOAD VEHICLE                            | Registered Owner        | MFC AUCTION HOUSE |
| Manufacturer    | FORD                                          | Registration Number     | DB32DMGP          |
| Model           | RANGER 3.2 XLT HR D-CAB DSL PU AT [2012-2016] | Register Number         |                   |
|                 |                                               | Date Of First Licensing |                   |
| VIN             | AFAPXXMJ2PES73511                             | Last COR                |                   |
| Engine Number   |                                               | License Expiry Date     |                   |
| Doors           | 4                                             | Power / Displacement    |                   |
| Color           | WHITE                                         | Paint Finish            | C - COMMON        |
| Year Model      | 2014                                          | Fuel                    | DIESEL            |
| Km Reading      | 302,557 KM                                    | Transmission            | AUTOMATIC         |
| Cab / Body Type | HATCHBACK                                     |                         |                   |

## Vehicle Options &amp; Accessories

## Items

## VEHICLE INSPECTION

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za

VIN: AFAPXXMJ2PES73511



## CONDITION REPORT



Report No:

2017303138

DATE

25/09/2026

## Damage

## Repair Way

|                                                     |                                               |
|-----------------------------------------------------|-----------------------------------------------|
| Engine Oil Leak                                     | Repair                                        |
| Switch Electrical Window Winder rear left Defective | Repair                                        |
| Indicator Light Front Left Damaged                  | Replace                                       |
| Seat Front Right Torn / Cut                         | Repair                                        |
| Side Mirror Right Damaged                           | Replace                                       |
| Front Bumper Dented                                 | Repair                                        |
| Bonnet Paintwork • Chipmarks                        | Repair                                        |
| Front Fender Left Paintwork • Scratched             | Repair                                        |
| Front Fender Right Paintwork • Scratched            | Repair                                        |
| Door Front Left Dented                              | Repair                                        |
| Door Front Right Paintwork • Scratched              | Repair                                        |
| Door Rear Left Dented                               | Repair                                        |
| Tailgate Paintwork • Scratched                      | Repair                                        |
| Sill Panel Left Dented                              | Repair                                        |
| Load Body Dented                                    | Repair                                        |
| Windscreen Cracked                                  | Replace                                       |
| Stabilizer Mounting Front Right Damaged             | Replace                                       |
| Ball Joint(s) Rear Axle Left Damaged                | Replace                                       |
| Gearbox Mountings Cracked                           | Replace                                       |
| Body exterior                                       | Signs of spray work done on body              |
| Body exterior                                       | Residual traces of poor repair on body panels |

## Brakes

## Brake Test Results

|                     | Left               | Right              |                  |                                  |
|---------------------|--------------------|--------------------|------------------|----------------------------------|
|                     | Braking Force [KN] | Braking Force [KN] | Axle Weight [KG] | Deceleration [m/s <sup>2</sup> ] |
| Front               | -                  | -                  | -                |                                  |
| Rear                | -                  | -                  | -                |                                  |
| Emergency / Parking | -                  | -                  | -                |                                  |

## Tyres and Rims

## Tyre Specification &amp; Measurement

|             | Size      | Load/Speed Index | Manufacture | Model    | Type* | Production Date | Tread Depth (mm) |
|-------------|-----------|------------------|-------------|----------|-------|-----------------|------------------|
| Front Left  | 265/65R17 | 112T             | Continental | Contact  | V     | 2118            | 2 mm             |
| Front Right | 265/65R17 | 112T             | Continental | Contact  | V     | 2118            | 2 mm             |
| Rear Left   | 265/65R17 | 112S             | Bridgestone | Dueler   | V     | 0923            | 3 mm             |
| Rear Right  | 265/65R17 | 112S             | Bridgestone | Dueler   | V     | 3024            | 4 mm             |
| Spare       | 255/65R17 | 110H             | Goodyear    | Wrangler | V     | //////          | 3 mm             |

\* Tyre Legend: V=Virgin, R=Recap

DEKRA Automotive (PTY) Ltd.  
 97 Willem Cruywagen Ave  
 Klerksoord, Pretoria, 0200  
 Phone: 012 542 4867  
[www.dekraauto.co.za](http://www.dekraauto.co.za)

VIN: AFAPXXMJ2PES73511



## CONDITION REPORT



Report No:

2017303138

DATE

25/09/2026

### Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

| No | System                    | Code        | Description                | Status |
|----|---------------------------|-------------|----------------------------|--------|
| 1  | POWERTRAIN CONTROL MODULE | P064C:00-28 | GLOW PLUG CONTROL MODULE 1 |        |

### Inspection Conditions

No Test Drive

Battery Flat

Engine number – not possible to verify engine number (not visible without dismantling)

Inspection conditions for the vehicle inspection were sufficient

### Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.

### Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

### Technician

Trevino Julius

This document was created electronically and is valid without signature.

General Remarks:

The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za

VIN: AFAPXXMJ2PES73511



## CONDITION REPORT



Report No:  
2017303138  
DATE  
25/09/2026



FRONT RIGHT CORNER



REAR LEFT CORNER



90 DEGREE FRONT



90 DEGREE REAR



90 DEGREE LEFT



90 DEGREE RIGHT

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
[www.dekraauto.co.za](http://www.dekraauto.co.za)

VIN: AFAPXXMJ2PES73511



## CONDITION REPORT



Report No:  
2017303138  
DATE  
25/09/2026



ODOMETER



DASHBOARD (W/ ENGINE RUNNING)



INTERIOR (FRONT DRIVER DOOR)



Automatic transmission



Warning lights illuminated



RR TYRE TREAD

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksord, Pretoria, 0200  
Phone: 012 542 4867  
[www.dekraauto.co.za](http://www.dekraauto.co.za)

VIN: AFAPXXMJ2PES73511



## CONDITION REPORT



Report No:  
2017303138  
DATE  
25/09/2026



RF TYRE TREAD



LF TYRE TREAD



LR TYRE TREAD



Sparewheel



Expansion bottle



Oil cap and dipstick

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksord, Pretoria, 0200  
Phone: 012 542 4867  
[www.dekraauto.co.za](http://www.dekraauto.co.za)

VIN: AFAPXXMJ2PES73511



## CONDITION REPORT




Report No:

2017303138

DATE

25/09/2026




REAR



ENGINE 1



ENGINE 2



CHASSIS



VIN PLATE OR STICKER



LICENSE DISC

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za

VIN: AFAPXXMJ2PES73511



## CONDITION REPORT



**Report No:**  
**2017303138**  
**DATE**  
**25/09/2026**

[illegible]

SHOCK AND BRAKE REPORT



**FORD**  
 1997

**NEW VEHICLE DIAGNOSTIC SERVICE**  
 Vehicle's On-board Diagnostic System (OBD) is designed to monitor engine and emission systems. When a problem is detected, the OBD will store a Diagnostic Trouble Code (DTC) in the Powertrain Control Module (PCM) and illuminate the Malfunction Indicator Lamp (MIL) on the instrument panel. The OBD will also store freeze frame data, which is a snapshot of the engine's operating conditions at the time the problem was detected. This information can be used to help diagnose the problem.

**Service Information**  
 For more information on the OBD system, see the Service Information section of the Owner's Manual.

**Powertrain Control Module (PCM)**  
 The PCM is the brain of the engine and emission systems. It monitors the engine's operating conditions and controls the fuel and air flow to the engine. The PCM also stores DTCs and freeze frame data.

**Malfunction Indicator Lamp (MIL)**  
 The MIL is a lamp on the instrument panel that illuminates when a problem is detected by the OBD system. The MIL is also known as the "check engine" light.

**Diagnostic Trouble Code (DTC)**  
 A DTC is a code that is stored in the PCM when a problem is detected. The DTC is used to identify the problem and to help diagnose the problem.

**Freeze Frame Data**  
 Freeze frame data is a snapshot of the engine's operating conditions at the time the problem was detected. This information can be used to help diagnose the problem.

**Service Information**  
 For more information on the OBD system, see the Service Information section of the Owner's Manual.

**Powertrain Control Module (PCM)**  
 The PCM is the brain of the engine and emission systems. It monitors the engine's operating conditions and controls the fuel and air flow to the engine. The PCM also stores DTCs and freeze frame data.

**Malfunction Indicator Lamp (MIL)**  
 The MIL is a lamp on the instrument panel that illuminates when a problem is detected by the OBD system. The MIL is also known as the "check engine" light.

**Diagnostic Trouble Code (DTC)**  
 A DTC is a code that is stored in the PCM when a problem is detected. The DTC is used to identify the problem and to help diagnose the problem.

**Freeze Frame Data**  
 Freeze frame data is a snapshot of the engine's operating conditions at the time the problem was detected. This information can be used to help diagnose the problem.

**Service Information**  
 For more information on the OBD system, see the Service Information section of the Owner's Manual.

DIAGNOSTIC REPORT PAGE 1

[illegible]

DIAGNOSTIC REPORT PAGE 2



Seat Front Right



Switch Electrical Window Winder rear left



Front Fender Right

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
[www.dekraauto.co.za](http://www.dekraauto.co.za)

VIN: AFAPXXMJ2PES73511



## CONDITION REPORT



Report No:  
2017303138  
DATE  
25/09/2026



Side Mirror Right



Windscreen



Windscreen



Door Front Right



Load Body



Load Body

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksord, Pretoria, 0200  
Phone: 012 542 4867  
[www.dekraauto.co.za](http://www.dekraauto.co.za)

VIN: AFAPXXMJ2PES73511



## CONDITION REPORT



Report No:  
2017303138  
DATE  
25/09/2026



Tailgate



Door Rear Left



Front Fender Left



Indicator Light Front Left



Door Front Left



Bonnet

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksord, Pretoria, 0200  
Phone: 012 542 4867  
[www.dekraauto.co.za](http://www.dekraauto.co.za)

VIN: AFAPXXMJ2PES73511




## CONDITION REPORT



Report No:  
2017303138  
DATE  
25/09/2026



Water level



Stabilizer Mounting Front Right



Ball Joint(s) Rear Axle Left



Front Bumper



Front Bumper



Front Bumper

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
[www.dekraauto.co.za](http://www.dekraauto.co.za)

VIN: AFAPXXMJ2PES73511



## CONDITION REPORT



Report No:  
2017303138  
DATE  
25/09/2026



Front Bumper



Sill Panel Left



Engine



Engine



Engine



Gearbox Mountings

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
[www.dekraauto.co.za](http://www.dekraauto.co.za)

VIN: AFAPXXMJ2PES73511