



## CONDITION REPORT

Report No: 2016338674

DATE  
12/04/2024

MFC Auction House  
M57 Pretoria Rd, Glenmarais, KEMPTON PARK  
Gauteng

DEKRA MFC  
M57 Pretoria Rd - 1619  
KEMPTON PARK - GT  
08610 33572

**Assignment**

Client	MFC Auction House	Inspection Location	MFC
Requested Date	12/04/2024		M57 Pretoria Road - 1619
Inspection Date	12/04/2024		Kempton Park - GT


**Vehicle Data**

Vehicle Type	LIGHT LOAD VEHICLE	Registered Owner	MFC AUCTION HOUSE
Manufacturer	FORD	Registration Number	KS48MXGP
Model	RANGER	Register Number	
VIN	AFAPXXMJ2PNJ14765	Date Of First Licensing	
Engine Number		Last COR	
Doors	4	License Expiry Date	31/08/2024
Color	WHITE	Power / Displacement	
Year Model		Paint Finish	TWO COAT UNI
Km Reading	34,597 KM	Fuel	DIESEL
Cab / Body Type	DOUBLE CAB	Transmission	AUTOMATIC

**Vehicle Options & Accessories****Items**

## VEHICLE INSPECTION

Damage	Repair Way
Front Bumper Damaged	Repair
Bonnet Damaged	Repair
Rear Fender Right Damaged	Repair
Rear bumper Damaged	Repair
Body and exterior	Minor dents and scratches and stone chips.
Body and exterior	Signs of repair work done to somebody panels.





## CONDITION REPORT

Report No: 2016338674

DATE  
12/04/2024

### Brakes

#### Brake Test Results

No Brake Test on a brake test machine has been performed.

	<b>Left</b>	<b>Right</b>		
	<b>Braking Force [KN]</b>	<b>Braking Force [KN]</b>	<b>Axle Weight [KG]</b>	<b>Deceleration [m/s<sup>2</sup>]</b>
Front	-	-	-	
Rear	-	-	-	
Emergency / Parking	-	-	-	

### Tyres and Rims

#### Tyre Specification & Measurement

	<b>Size</b>	<b>Load/Speed Index</b>	<b>Manufacture</b>	<b>Model</b>	<b>Type*</b>	<b>Production Date</b>	<b>Tread Depth (mm)</b>
Front Left	265/60R18	110T	Continental	Crosscontact	V	1422	4 mm
Front Right	265/60R18	110T	Continental	Crosscontact	V	1422	4 mm
Rear Left	265/60R18	110T	Continental	Crosscontact	V	1422	4 mm
Rear Right	265/60R18	110T	Continental	Crosscontact	V	1422	4 mm

\* Tyre Legend: V=Virgin, R=Recap

### Diagnostic

During the diagnostic no active error messages were detected. (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

### Inspection Conditions

No Test Drive

Battery Flat

Engine number – not possible to verify engine number (not visible without dismantling)

Inspection conditions for the vehicle inspection were sufficient

### Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.

### Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

### Technician

Werner Laubscher

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.




## CONDITION REPORT

VIN: AFAPK61201835674

2 / 7

DATE


12/04/2024




Shock test



Diagnostic report



Diagnostic report



Diagnostic report



FRONT RIGHT CORNER



REAR LEFT CORNER



## CONDITION REPORT

Report No: 2016338674

VIN: AFAPXXMJ2PNJ14765

DATE

12/04/2024

3/7

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
[www.dekraauto.co.za](http://www.dekraauto.co.za)



## CONDITION REPORT

Report No: 2016338674

DATE

VIN: AFAPXXM129042024

4 / 7



INTERIOR (FRONT DRIVER DOOR)



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



Automatic



90 DEGREE FRONT



90 DEGREE RIGHT



## CONDITION REPORT

Report No: 2016338674

DATE  
12/04/2024

VIN: AFAPXXMJ2PNJ14765

5 / 7

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
[www.dekraauto.co.za](http://www.dekraauto.co.za)



## CONDITION REPORT

Report No: 2016338674

DATE  
12/04/2024

VIN: AFAPXXMJ2PNJ14765

6 / 7



90 DEGREE REAR



90 DEGREE LEFT



LF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD



RF TYRE TREAD



## CONDITION REPORT

Report No: 2016338674

DATE  
12/04/2024

VIN: AFAPXXMJ2PNJ14765

7 / 7

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
[www.dekraauto.co.za](http://www.dekraauto.co.za)



## CONDITION REPORT

Report No: 2016338674

DATE  
12/04/2024

LICENSE DISC



VIN PLATE OR STICKER



ENGINE 1



Undercarriage rear.



Undercarriage front.



Oil cap and dipstick



## CONDITION REPORT

Report No: 2016338674

DATE  
12/04/2024

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
[www.dekraauto.co.za](http://www.dekraauto.co.za)



## CONDITION REPORT

Report No: 2016338674

DATE  
12/04/2024

Water level



Front Bumper



Front Bumper



Bonnet



Rear bumper



Rear Fender Right



## CONDITION REPORT

Report No: 2016338674

DATE  
12/04/2024

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
[www.dekraauto.co.za](http://www.dekraauto.co.za)