



CONDITION REPORT

Report No: 2016209963

DATE
22/12/2023

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572

**Assignment**

Client	MFC Auction House	Inspection Location	MFC
Requested Date	22/12/2023		M57 Pretoria Road - 1619
Inspection Date	22/12/2023		Kempton Park - GT

Vehicle Data

Vehicle Type	LIGHT LOAD VEHICLE	Registered Owner	MFC
Manufacturer	FORD	Registration Number	NONE
Model	RANGER	Register Number	
VIN	AFAPXXMJ2PPK15055	Date Of First Licensing	
Engine Number		Last COR	
Doors	4	License Expiry Date	22/12/2023
Color	RED	Power / Displacement	
Year Model		Paint Finish	TWO COAT METALLIC
Km Reading	17,800 KM	Fuel	DIESEL
Cab / Body Type	DOUBLE CAB	Transmission	AUTOMATIC

Vehicle Options & Accessories**Items**

VEHICLE INSPECTION



Damage	Repair Way
Side Mirror Left Paintwork • Scratched	Repair
Side Mirror Right Paintwork • Scratched	Repair
Front Bumper Paintwork • Scratched	Repair
Bonnet Dented	Repair
Rear Fender Right Paintwork • Scratched	Repair
Door Front Right Paintwork • Scratched	Repair
Door Rear Right Paintwork • Scratched	Smart Repair
Rear bumper Damaged	Repair
Windscreen Chipped	Repair





CONDITION REPORT

Report No: 2016209963

DATE
22/12/2023**Brakes****Brake Test Results**

	Left	Right	Axle Weight [KG]	Deceleration [m/s ²]
	Braking Force [kN]	Braking Force [kN]		
Front	4.19	4.68	-	
Rear	3.15	3.36	-	
Emergency / Parking	2.9	3.2	-	

Tyres and Rims**Tyre Specification & Measurement**

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	255/65 R18	111H	Goodyear	Wrangler	V	4722	6 mm
Front Right	255/65 R18	111H	Goodyear	Wrangler	V	4722	7 mm
Rear Left	255/65 R18	111H	Goodyear	Wrangler	V	4622	7 mm
Rear Right	255/65 R18	111H	Goodyear	Wrangler	V	4722	7 mm
Spare	255/65 R18	111H	Goodyear	Wrangler	V	0000	8 mm

* Tyre Legend: V=Virgin, R=Recap

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacturer).

No	System	Code	Description	Status
1	ABS(ANTI-LOCK BRAKE SYSTEM)	U0146:00-68	LOST COMMUNICATION WITH SERIAL DATA GATEWAY A	

Inspection Conditions

No Test Drive

Battery Flat

Engine number – not possible to verify engine number (not visible without dismantling)

Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: SHOCK ABSORBER TEST COULD NOT BE PERFORMED. VEHICLE HAS NO LICENSE DISC .FRONT AND REAR NUMBER PLATES MISSING.

Engine Compartment: Engine bay dirty. Brake fluid level ok.

Interior: Vehicle interior dirty and some interior panels scratched.

Body • Exterior: Right tail gate clip missing. Minor dents and scratches on some body panels. Spray work on some body panels. Some body panels misaligned.

Stone chips on some body panels.

Tyres and Rims: Some alloy rims scratched.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.

Technician

Sibusiso Mokase

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.



CONDITION REPORT

VIN: AFAPKYM12P15053
Report No: 2016209953

2 / 9

,
DATE

22/12/2023

Brake test report

Diagnostic report page 1

1
1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16
17
18
19
20
21
22
23
24
25
26
27
28
29
30
31
32
33
34
35
36
37
38
39
40
41
42
43
44
45
46
47
48
49
50
51
52
53
54
55
56
57
58
59
60
61
62
63
64
65
66
67
68
69
70
71
72
73
74
75
76
77
78
79
80
81
82
83
84
85
86
87
88
89
90
91
92
93
94
95
96
97
98
99
100

Diagnostic report page 2



FRONT RIGHT CORNER



REAR LEFT CORNER



INTERIOR (FRONT DRIVER DOOR)



CONDITION REPORT

Report No: 2016209963

VIN: AFAPXXMJ2PPK15055

DATE

22/12/2023

3/9

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016209963

DATE

VIN: AFAPXXM122112/2023

4 / 9



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



90 DEGREE FRONT



90 DEGREE RIGHT



90 DEGREE REAR



90 DEGREE LEFT



CONDITION REPORT

Report No: 2016209963

DATE
22/12/2023

VIN: AFAPXXMJ2PPK15055

5 / 9

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016209963

DATE
22/12/2023

VIN: AFAPXXMJ2PPK15055

6 / 9



LF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD



RF TYRE TREAD



Spare wheel



LICENSE DISC



CONDITION REPORT

Report No: 2016209963

DATE
22/12/2023

VIN: AFAPXXMJ2PPK15055

7 / 9



CONDITION REPORT

Report No: 2016209963

DATE
22/12/2023

VIN PLATE OR STICKER



VIN: AFAPXXMJ2PPK15055

8 / 9

ENGINE 1



Rear chassis



Front chassis



Spare wheel Accessories



Oil cap and dipstick



CONDITION REPORT

Report No: 2016209963

DATE
22/12/2023

VIN: AFAPXXMJ2PPK15055

9 / 9



CONDITION REPORT

Report No: 2016209963

DATE
22/12/2023

Automatic Transmission



Front Bumper



Front Bumper



Bonnet



Door Front Right



Door Rear Right



CONDITION REPORT

Report No: 2016209963

DATE
22/12/2023

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016209963

DATE
22/12/2023

Rear Fender Right



Rear bumper



Rear bumper



Side Mirror Left



Side Mirror Right



Water level



CONDITION REPORT

Report No: 2016209963

DATE
22/12/2023

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016209963

DATE
22/12/2023

Windscreen



CONDITION REPORT

Report No: 2016209963

DATE
22/12/2023

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za