



CONDITION REPORT



Report No:

2017305777

DATE _____

01/10/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572



Assignment

Client	MFC Auction House	Inspection Location	MFC
Requested Date	01/10/2026		M57 Pretoria Road - 1619
Inspection Date	01/10/2026		Kempton Park -

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	MFC
Manufacturer	TOYOTA	Registration Number	KD33CLGP
Model	COROLLA QUEST 1.8 PLUS [2021-2022]	Register Number	
VIN	AHTBF8JE401012813	Date Of First Licensing	
Engine Number		Last COR	
Doors	4	License Expiry Date	31/01/2027
Color	GREEN	Power / Displacement	
Year Model	2021	Paint Finish	TWO COAT METALLIC
Km Reading	248,769 KM	Fuel	PETROL
Cab / Body Type	SEDAN	Transmission	MANUAL

Vehicle Options & Accessories

.....
Items

VEHICLE INSPECTION

DEKRA Automotive (PTY) Ltd
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za


VIN: AHTBF8JE401012813



CONDITION REPORT



Report No:
2017305777
DATE
01/10/2026



Damage	Repair Way
Engine Oil Leak	Repair
Bonnet hinges Damaged	Replace
Center Console / Cubbyhole + Lid Missing	Replace
Indicator Light Front Left Cracked	Replace
Headlight Left Damaged	Replace
Headlight Right Damaged	Replace
Seat Front Left Dirty	Repair
Seat Front Right Damaged	Repair
Seat Rear Damaged	Repair
Hood Lining Excessive Wear & Tear	Repair
Door Sealing Rubber Front Right Damaged	Replace
Mirror Adjusters Malfunction	Replace
Steering Wheel Trim Excessive Wear & Tear	Repair
Front Bumper Damaged	Replace
Grill Damaged	Replace
Bonnet Damaged	Repair
Bonnet slam plate (Shock tower/ Inner tray) Damaged	Repair
Front Fender Left Damaged	Repair
Front Fender Right Damaged	Repair
Rear Fender Left Dented	Repair
Door Front Left Residual Traces of Repair	Repair
Door Front Right Damaged	Repair
Door Rear Left Paintwork • Scratched	Repair
Rear bumper Damaged	Repair
Inner Boot Floor Pan and Spare Wheel Well Damaged	Repair
Sill Panel Left Damaged	Repair
Sill Panel Right Dented	Repair
Roof Dented	Repair
Shock Absorber Rear Right Leak	Replace
Control Arm Bush(es) Front Axle Left Cracked	Replace
Control Arm Bush(es) Front Axle Right Cracked	Replace
Mounting Rubber(s) Rear Axle Left Cracked	Replace
Mounting Rubber(s) Rear Axle Right Cracked	Replace
Tyre Front Right Damaged	Replace
Tyre Rear Left Damaged	Replace
Spare Tyre Damaged	Replace
Rim Front Left Dented	Repair
Chassis Damaged	Repair
Cross Member Rear Left Damaged	Repair
Cross Member Rear Right Damaged	Repair
Silencer Damaged	Repair
Belly plates Damaged	Replace
Gearbox Oil Leak	Repair
Gear knob damaged	Replace
Engine oil sump damaged	Replace
Front right and rear left tyres regrooved	Replace
Front left and right tyre sizes different	Repair

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTBF8JE401012813



CONDITION REPORT



Report No:
2017305777
DATE
01/10/2026

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s ²]
Front	3.77	3.15	-	
Rear	2.25	2.02	-	
Emergency / Parking	1.11	0.94	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	195/65 R15	91H	Continental	Contipremuim	V	2327	2 mm
Front Right	185/65 R15	88H	Bridgestone	B250	V	0319	0 mm
Rear Left	195/65 R15	91H	Firestone	Touring	V	4917	0 mm
Rear Right	195/65 R15	91H	Continental	Contipremuim	V	2524	4 mm
Spare	195/65 R15	91H	Continental	Contipremuim	V	2324	0 mm

* Tyre Legend: V=Virgin, R=Recap

Diagnostic

During the diagnostic no active error messages were detected. (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

Inspection Conditions

No Test Drive

Battery Flat

Engine number – not possible to verify engine number (not visible without dismantling)

Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: Interior: Vehicle interior dirty and panels scratched.

Body • Exterior: Signs of hail damage on body panels. Poor residual traces of repair on body panels. Body panels misaligned. Stone chips and spray work on body panels. Dents and scratches on body panels. Signs of impact damage to front of vehicle.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Sibusiso Mokase

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTBF8JE401012813



CONDITION REPORT



Report No:
2017305777
DATE
01/10/2026

03/05/2023				97,864.41		MMA	
No				Lot			
Accessories				License plate		KX221417	
Brand				Make up		Nissan	
Age make				Painting		Nissan	
In warranty				Registration		Nissan	
First date				Year		2017	
Year				Model		Nissan	
Accessories				Engine		1.8L	
Accessories				Transmission		Automatic	
Accessories				Drive		Front	
Accessories				Fuel tank		45L	
Accessories				Fuel tank		45L	
Accessories				Fuel tank		45L	
Accessories				Fuel tank		45L	
Accessories				Fuel tank		45L	
Accessories				Fuel tank		45L	
Accessories				Fuel tank		45L	
Accessories				Fuel tank		45L	
Accessories				Fuel tank		45L	
Accessories				Fuel tank		45L	
Accessories				Fuel tank		45L	
Accessories				Fuel tank		45L	
Accessories				Fuel tank		45L	
Accessories				Fuel tank		45L	
Accessories				Fuel tank		45L	
Accessories				Fuel tank		45L	
Accessories				Fuel tank		45L	
Accessories				Fuel tank		45L	
Accessories				Fuel tank		45L	
Accessories				Fuel tank		45L	
Accessories				Fuel tank		45L	
Accessories				Fuel tank		45L	
Accessories				Fuel tank		45L	
Accessories				Fuel tank		45L	
Accessories				Fuel tank		45L	
Accessories				Fuel tank		45L	
Accessories				Fuel tank		45L	
Accessories				Fuel tank		45L	
Accessories				Fuel tank		45L	
Accessories				Fuel tank		45L	
Accessories				Fuel tank		45L	
Accessories				Fuel tank		45L	
Accessories				Fuel tank		45L	
Accessories				Fuel tank		45L	
Accessories				Fuel tank		45L	
Accessories				Fuel tank		45L	
Accessories				Fuel tank		45L	
Accessories				Fuel tank		45L	
Accessories				Fuel tank		45L	
Accessories				Fuel tank		45L	
Accessories				Fuel tank		45L	
Accessories				Fuel tank		45L	
Accessories				Fuel tank		45L	
Accessories				Fuel tank		45L	
Accessories				Fuel tank		45L	
Accessories				Fuel tank		45L	
Accessories				Fuel tank		45L	
Accessories				Fuel tank		45L	
Accessories				Fuel tank		45L	
Accessories				Fuel tank		45L	
Accessories				Fuel tank		45L	
Accessories				Fuel tank		45L	
Accessories				Fuel tank		45L	
Accessories				Fuel tank		45L	
Accessories				Fuel tank		45L	
Accessories				Fuel tank		45L	
Accessories				Fuel tank		45L	
Accessories				Fuel tank		45L	
Accessories				Fuel tank		45L	
Accessories				Fuel tank		45L	
Accessories				Fuel tank		45L	
Accessories				Fuel tank		45L	
Accessories				Fuel tank		45L	
Accessories				Fuel tank		45L	
Accessories				Fuel tank		45L	
Accessories				Fuel tank		45L	
Accessories				Fuel tank		45L	
Accessories				Fuel tank		45L	
Accessories				Fuel tank		45L	
Accessories				Fuel tank		45L	
Accessories				Fuel tank		45L	
Accessories				Fuel tank		45L	
Accessories				Fuel tank		45L	
Accessories				Fuel tank		45L	
Accessories				Fuel tank		45L	
Accessories				Fuel tank		45L	
Accessories				Fuel tank		45L	
Accessories				Fuel tank		45L	
Accessories				Fuel tank		45L	
Accessories				Fuel tank		45L	
Accessories				Fuel tank		45L	
Accessories				Fuel tank		45L	
Accessories				Fuel tank		45L	
Accessories				Fuel tank		45L	
Accessories				Fuel tank		45L	
Accessories				Fuel tank		45L	
Accessories				Fuel tank		45L	
Accessories				Fuel tank		45L	
Accessories				Fuel tank		45L	
Accessories				Fuel tank		45L	
Accessories				Fuel tank		45L	
Accessories				Fuel tank		45L	
Accessories				Fuel tank		45L	
Accessories				Fuel tank		45L	
Accessories				Fuel tank		45L	
Accessories				Fuel tank		45L	
Accessories				Fuel tank		45L	
Accessories				Fuel tank		45L	
Accessories				Fuel tank		45L	
Accessories				Fuel tank		45L	
Accessories				Fuel tank		45L	
Accessories				Fuel tank		45L	
Accessories				Fuel tank		45L	
Accessories				Fuel tank		45L	
Accessories				Fuel tank		45L	
Accessories				Fuel tank		45L	
Accessories				Fuel tank		45L	
Accessories				Fuel tank		45L	
Accessories				Fuel tank		45L	
Accessories				Fuel tank		45L	
Accessories				Fuel tank		45L	
Accessories				Fuel tank		45L	
Accessories				Fuel tank		45L	
Accessories				Fuel tank		45L	
Accessories				Fuel tank		45L	
Accessories				Fuel tank		45L	
Accessories				Fuel tank		45L	
Accessories				Fuel tank		45L	
Accessories				Fuel tank		45L	
Accessories				Fuel			

Brake and shock absorber report

Diagnostic Report	
Engine	Good
Transmission	Good
Brake	Good
Shock	Good
Steering	Good
Wheels	Good
Lighting	Good
Exterior	Good
Interior	Good
Engine	Good
Overall	Good

Diagnostic report



FRONT RIGHT CORNER



REAR LEFT CORNER



INTERIOR (FRONT DRIVER DOOR)



DASHBOARD (W/ ENGINE RUNNING)

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTBF8JE401012813



CONDITION REPORT



Report No:
2017305777
DATE
01/10/2026



ODOMETER



Manual Transmission



90 DEGREE FRONT



90 DEGREE RIGHT



90 DEGREE REAR



90 DEGREE LEFT

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTBF8JE401012813



CONDITION REPORT



Report No:
2017305777
DATE
01/10/2026



LF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD



RF TYRE TREAD



Spare wheel and Accessories



LICENSE DISC

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTBF8JE401012813



CONDITION REPORT



Report No:
2017305777
DATE
01/10/2026




VIN PLATE OR STICKER



ENGINE 1



Front chassis



Rear chassis



Engine oil sump



Oil cap and dipstick

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTBF8JE401012813



CONDITION REPORT



Report No:

Report No.
2017305777

DATE

01/10/2026



Hood Lining



Steering Wheel Trim



Seat Front Right



Door Sealing Rubber Front Right



Seat Rear



Seat Rear

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTBF8JE401012813



CONDITION REPORT



Report No:

Report No.
2017305777

DATE _____

01/10/2026



Center Console / Cubbyhole + Lid



Front Fender Right



Door Front Right



Rear bumper



Rear bumper



Rear bumper

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTBF8JE401012813



CONDITION REPORT



Report No:
2017305777
DATE
01/10/2026



Rear Fender Left



Door Rear Left



Door Rear Left



Seat Front Left



Door Front Left



Front Fender Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTBF8JE401012813



CONDITION REPORT



Report No:

Report No.
2017305777

DATE _____

01/10/2026



Bonnet



Grill



Roof



Mirror Adjusters



Spare Tyre



Bonnet slam plate (Shock tower/ Inner tray)

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTBF8JE401012813



CONDITION REPORT



Report No:


Report No.
2017305777

DATE _____

01/10/2026



Headlight Right



Headlight Left



Headlight Left



Water level



Bonnet hinges



Bonnet hinges

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTBF8JE401012813



CONDITION REPORT



Report No:
2017305777
DATE
01/10/2026



Control Arm Bush(es) Front Axle Right



Front Bumper



Front Bumper



Front Bumper



Control Arm Bush(es) Front Axle Left



Sill Panel Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTBF8JE401012813



CONDITION REPORT



Report No:

Report No.
2017305777

DATE

01/10/2026



Sill Panel Right



Belly plates



Gearbox



Engine



Tyre Front Right



Rim Front Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTBF8JE401012813



CONDITION REPORT



Report No:

Report No.
2017305777

DATE _____

01/10/2026



Chassis



Chassis



Cross Member Rear Left



Cross Member Rear Right



Chassis



Chassis

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTBF8JE401012813



CONDITION REPORT



Report No:
2017305777
DATE
01/10/2026



Mounting Rubber(s) Rear Axle Right



Mounting Rubber(s) Rear Axle Left



Tyre Rear Left



Shock Absorber Rear Right



Inner Boot Floor Pan and Spare Wheel Well



Silencer

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTBF8JE401012813



CONDITION REPORT



Report No:
2017305777
DATE
01/10/2026



Indicator Light Front Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTBF8JE401012813