



CONDITION REPORT



Report No:
2017303410
DATE
25/09/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572



Assignment

Client	MFC Auction House	Inspection Location	MFC
Requested Date	25/09/2026		M57 Pretoria Road - 1619
Inspection Date	25/09/2026		Kempton Park - GT

Vehicle Data

Vehicle Type	LIGHT LOAD VEHICLE	Registered Owner	
Manufacturer	TOYOTA	Registration Number	LV21VCGP
Model	HILUX 2.4 GD-6 RB RAIDER D-CAB DSL PU [2021-2023]	Register Number	
		Date Of First Licensing	
VIN	AHTJB3DD704528644	Last COR	
Engine Number		License Expiry Date	31/05/2027
Doors	4	Power / Displacement	
Color	SILVER	Paint Finish	TWO COAT UNI
Year Model	2022	Fuel	DIESEL
Km Reading	121,037 KM	Transmission	MANUAL
Cab / Body Type	DOUBLE CAB		

Vehicle Options & Accessories

Items

VEHICLE INSPECTION

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTJB3DD704528644



CONDITION REPORT



Report No:

2017303410

DATE

25/09/2026



Damage

Repair Way

Engine Wiring Defective	Repair
Tail Light Left Cracked	Replace
Hood Lining Dirty	Repair
Steering Wheel Trim Excessive Wear & Tear	Repair
Front Bumper Paintwork • Scratched	Repair
Bonnet Paintwork • Scratched	Repair
Rear Fender Left Damaged	Repair
Door Front Left Dented	Repair
Door Front Right Paintwork • Scratched	Repair
Door Rear Left Paintwork • Scratched	Repair
Tailgate Paintwork • Scratched	Repair
Rear bumper Damaged	Repair
Roof Paintwork • Chipmarks	Repair
Load Body Dented	Repair
Windscreen Chipped	Repair
Shock Absorber Front Right Sweat	Replace
Shock Absorber Mounting Rear Left Cracked	Replace
Belly plates Damaged	Repair
Triangle Missing	Replace
Front right and rear right shock absorbers weak	Replace

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s ²]
Front	4.48	4.34	-	
Rear	3.27	3.07	-	
Emergency / Parking	2.52	1.57	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	265/65 R17	112T	Goodyear	Wrangler	V	0225	7 mm
Front Right	265/65 R17	112T	Goodyear	Wrangler	V	4524	7 mm
Rear Left	265/65 R17	112T	Goodyear	Wrangler	V	2925	8 mm
Rear Right	265/65 R17	112T	Goodyear	Wrangler	V	1425	8 mm
Spare	265/65 R17	112S	Dunlop	Grandtrek	V	0000	9 mm

* Tyre Legend: V=Virgin, R=Recap

DEKRA Automotive (PTY) Ltd.
 97 Willem Cruywagen Ave
 Klerksoord, Pretoria, 0200
 Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTJB3DD704528644



CONDITION REPORT



Report No:
2017303410
DATE
25/09/2026

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	COMBINATION METER	B1504	LOST COMMUNICATION WITH HMI-LAN	

Inspection Conditions

No Test Drive

Battery Flat

Engine number – not possible to verify engine number (not visible without dismantling)

Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS. Interior: Vehicle interior dirty and panels scratched.

Body • Exterior: Left bumper grill missing. Dents and scratches on body panels

Undercarriage: Bottom of engine covered.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Sibusiso Mokase

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTJB3DD704528644



CONDITION REPORT



Report No:
2017303410
DATE
25/09/2026

Name: _____
Address: _____
Zip code, City: _____
Telephone: _____
Year made: 2004
Year made: 14-02
Test results: _____

EU
License reg. in: EU/SG
License: EU/SG
Max speed: 170 km/h
Max power: 110 kW
Weight: 607 kg
ANTRAFAT/04/2004

Lithke	Result
1.50-100 km/h	
From 0 to 1.50 km/h: _____ From 0 to 1.50 km/h: _____	0 - 1.50 km/h: _____ 0 - 1.50 km/h: _____
1.50-300 km/h	
From 0 to 1.50 km/h: _____ From 0 to 1.50 km/h: _____	0 - 1.50 km/h: _____ 0 - 1.50 km/h: _____
1.50-400 km/h	
From 0 to 1.50 km/h: _____ From 0 to 1.50 km/h: _____	0 - 1.50 km/h: _____ 0 - 1.50 km/h: _____
1.50-500 km/h	
From 0 to 1.50 km/h: _____ From 0 to 1.50 km/h: _____	0 - 1.50 km/h: _____ 0 - 1.50 km/h: _____
1.50-600 km/h	
From 0 to 1.50 km/h: _____ From 0 to 1.50 km/h: _____	0 - 1.50 km/h: _____ 0 - 1.50 km/h: _____
1.50-700 km/h	
From 0 to 1.50 km/h: _____ From 0 to 1.50 km/h: _____	0 - 1.50 km/h: _____ 0 - 1.50 km/h: _____
1.50-800 km/h	
From 0 to 1.50 km/h: _____ From 0 to 1.50 km/h: _____	0 - 1.50 km/h: _____ 0 - 1.50 km/h: _____
1.50-900 km/h	
From 0 to 1.50 km/h: _____ From 0 to 1.50 km/h: _____	0 - 1.50 km/h: _____ 0 - 1.50 km/h: _____
1.50-1000 km/h	
From 0 to 1.50 km/h: _____ From 0 to 1.50 km/h: _____	0 - 1.50 km/h: _____ 0 - 1.50 km/h: _____

Brake and shock absorber report

[illegible]

Diagnostic report page 1

Tipton/Heck		Test Time: 2024-09-26 14:50:19		Report ID: MUXMA20240926145019	
UDT55	Last communication with instrument panel cluster (IPC) control module			History	
Technician Notes 2017303438					
Customer name:					
Technician:					
Date:					
Note: Please save a copy of this report for your records.					

Diagnostic report page 2



FRONT RIGHT CORNER



REAR LEFT CORNER



INTERIOR (FRONT DRIVER DOOR)

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTJB3DD704528644



CONDITION REPORT



Report No:
2017303410
DATE
25/09/2026



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



Manual Transmission



90 DEGREE FRONT



90 DEGREE RIGHT



90 DEGREE REAR

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTJB3DD704528644



CONDITION REPORT




Report No:
2017303410
DATE
25/09/2026




90 DEGREE LEFT



LF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD



RF TYRE TREAD



Spare tyre

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTJB3DD704528644



CONDITION REPORT



Report No:

2017303410

DATE

25/09/2026



Spare Wheel Accessories



LICENSE DISC



VIN PLATE OR STICKER



ENGINE 1



Front chassis



Rear chassis

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTJB3DD704528644



CONDITION REPORT



Report No:
2017303410
DATE
25/09/2026



Oil cap and dipstick



Steering Wheel Trim



Hood Lining



Door Front Right



Door Front Right



Bonnet

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTJB3DD704528644



CONDITION REPORT



Report No:
2017303410
DATE
25/09/2026



Bonnet



Door Front Left



Windscreen



Roof



Door Rear Left



Door Rear Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTJB3DD704528644



CONDITION REPORT



Report No:

2017303410

DATE

25/09/2026



Rear Fender Left



Rear bumper



Tailgate



Load Body



Tail Light Left



Water level

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTJB3DD704528644



CONDITION REPORT



Report No:
2017303410
DATE
25/09/2026



Engine Wiring



Front Bumper



Front Bumper



Shock Absorber Mounting Rear Left



Belly plates



Shock Absorber Front Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTJB3DD704528644