



CONDITION REPORT

Report No: 201620776

DATE
20/12/2023

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572

**Assignment**

Client	MFC Auction House	Inspection Location	MFC
Requested Date	20/12/2023		M57 Pretoria Road - 1619
Inspection Date	20/12/2023		Kempton Park - GT


Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	MFC
Manufacturer	TOYOTA	Registration Number	KRS924NW
Model	COROLLA CROSS	Register Number	
VIN	AHTKFAAG400607708	Date Of First Licensing	
Engine Number		Last COR	
Doors	5	License Expiry Date	29/02/2024
Color	WHITE	Power / Displacement	
Year Model		Paint Finish	C - COMMON
Km Reading	40,323 KM	Fuel	PETROL
Cab / Body Type	STATION WAGON	Transmission	AUTOMATIC

Vehicle Options & Accessories**Items**

VEHICLE INSPECTION

Damage	Repair Way
--------	------------





CONDITION REPORT

Report No: 2016207767

DATE
20/12/2023**Brakes****Brake Test Results**

	Left	Right	Axle Weight [KG]	Deceleration [m/s ²]
	Braking Force [kN]	Braking Force [kN]		
Front	2.4	2.4	-	
Rear	1.5	1.6	-	
Emergency / Parking	1.3	2	-	

Tyres and Rims**Tyre Specification & Measurement**

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	215/60R17	96H	Bridgestone	Alenza	V	4121	3 mm
Front Right	215/60R17	96H	Bridgestone	Alenza	V	4421	5 mm
Rear Left	215/60R17	96H	Bridgestone	Alenza	V	4721	3 mm
Rear Right	215/60R17	96H	Bridgestone	Alenza	V	4212	5 mm
Spare	T155/70D17	110M	Dunlop	Temporary	V	//////	6 mm

* Tyre Legend: V=Virgin, R=Recap

Diagnostic

During the diagnostic no active error messages were detected. (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacturer).

Inspection Conditions

No Test Drive

Battery Flat

Engine number – not possible to verify engine number (not visible without dismantling)

Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE NORMAL WEAR AND TEAR MARKS ON BODY INTERIOR EXTERIOR AND MECHANICAL ENGINEERING PARTS.SHOCK TEST NOT PERFORMED,DUE NO MACHINE NOT WORKING.

Engine Compartment: Bottom of engine is fully covered.

Body • Exterior: Minor dents scratches and stone chips on some body panels. Signs of spray work done on some body panels.

Axe and Suspension: Shock test not performed.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Trevino Julius

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.



CONDITION REPORT

VIN: 20100207707 Report No: 20100207707


2 / 7

DATE


20/12/2023



Shock and brake



Diagnostic test



Diagnostic test



FRONT RIGHT CORNER



REAR LEFT CORNER



INTERIOR (FRONT DRIVER DOOR)

**CONDITION REPORT****Report No: 2016207767**

VIN: AHTKFAAG400607708

DATE

20/12/2023

3/7



CONDITION REPORT

Report No: 2016207767

DATE

VIN: AHTKFAAG209027028

20/09/2023

4 / 7



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



90 DEGREE FRONT



90 DEGREE RIGHT



90 DEGREE REAR



90 DEGREE LEFT



CONDITION REPORT

Report No: 2016207767

DATE
20/12/2023

VIN: AHTKFAAG400607708

5 / 7

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016207767

DATE
20/12/2023

VIN: AHTKFAAG400607708

6 / 7



LF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD



Sparewheel



RF TYRE TREAD



LICENSE DISC



CONDITION REPORT

Report No: 2016207767

DATE
20/12/2023


VIN: AHTKFAAG400607708

7 / 7



CONDITION REPORT

Report No: 2016207767

DATE
20/12/2023


VIN PLATE OR STICKER



ENGINE 1



ENGINE 2



CHASSIS



Rear end



Automatic



CONDITION REPORT

Report No: 2016207767

DATE
20/12/2023

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016207767

DATE
20/12/2023

Expansion bottle



Oil filler cap and dipstick



CONDITION REPORT

Report No: 2016207767

DATE
20/12/2023

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za