



CONDITION REPORT



Report No:
2017293105
DATE
02/09/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572



Assignment

Client	MFC Auction House	Inspection Location	MFC
Requested Date	02/09/2026		M57 Pretoria Road - 1619
Inspection Date	02/09/2026		Kempton Park -

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	MFC
Manufacturer	TOYOTA	Registration Number	CX21ZXGP
Model	COROLLA 1.3 PROFESSIONAL [2010-2014]	Register Number	
VIN	AHTLT58E106048687	Date Of First Licensing	
Engine Number		Last COR	
Doors	4	License Expiry Date	
Color	BLUE	Power / Displacement	
Year Model	2014	Paint Finish	M - METALLIC
Km Reading	376,537 KM	Fuel	PETROL
Cab / Body Type	SEDAN	Transmission	MANUAL

Vehicle Options & Accessories

Items

VEHICLE INSPECTION

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za


VIN: AHTLT58E106048687



CONDITION REPORT



Report No:
2017293105
DATE
02/09/2026



Damage	Repair Way
Fan Belt Excessive Wear & Tear	Replace
Center Console / Cubbyhole + Lid Damaged	Repair
Park Light Front Left Defective	Repair
Dim Light Left Defective	Repair
Seat Front Left Torn / Cut	Repair
Seat Front Right Torn / Cut	Repair
Seat Rear Damaged	Repair
Front Bumper Residual Traces of Repair	Repair
Bonnet Residual Traces of Repair	Repair
Bonnet slam plate (Shock tower/ Inner tray) Damaged	Repair
Front Fender Left Residual Traces of Repair	Repair
Front Fender Right Residual Traces of Repair	Repair
Rear Fender Left Paintwork • Scratched	Repair
Rear Fender Right Dented	Repair
Door Front Left Dented	Repair
Door Front Right Paintwork • Scratched	Repair
Door Rear Left Paintwork • Scratched	Repair
Door Rear Right Dented	Repair
Rear bumper Damaged	Repair
Fuel Flap Damaged	Repair
Sill Panel Left Paintwork • Scratched	Repair
Brake disc 2. Axle left Corrosion	Replace
Brake disc 2. Axle right Corrosion	Replace
Stabilizer Mounting Front Left Damaged	Replace
Stabilizer Mounting Front Right Damaged	Replace
Tyre Front Left Smooth	Replace
Tyre Rear Left Smooth	Replace
Rim Front Right Deformed	Repair
Gearbox Oil Leak	Repair
Radiator Cross Member Damaged	Repair
Engine Noise Excessive	Repair
Front tyre size differs	Replace
Warning lights illuminated	Repair
Body exterior	Signs of spray work done on body panels
Body exterior	Minor dents scratches stone chips on body panels

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s ²]
Front	3.3	3.1	-	
Rear	2.6	3.0	-	
Emergency / Parking	1.6	1.8	-	

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTLT58E106048687



CONDITION REPORT



Report No:
2017293105
DATE
02/09/2026

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	T125/70D17	98M	Bf Goodrich	Temporary	V	4306	0 mm
Front Right	195/65R15	91H	Bridgestone	B390	V	3605	2 mm
Rear Left	195/65R15	91H	llink	L comfort	V	1422	0 mm
Rear Right	195/65R15	91H	Goodride	Radial	V	3319	6 mm
Spare	195/65R15	91H	Goodride	Radial	V	//////	2 mm

* Tyre Legend: V=Virgin, R=Recap

Diagnostic

During the diagnostic no active error messages were detected. (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).
Diagnostic could not be performed due to no data available and or OBD interface malfunction.

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE: NORMAL WEAR AND TEAR MARKS ON THE BODY, INTERIOR, AND MECHANICAL.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Trevino Julius

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTLT58E106048687



CONDITION REPORT



Report No:
2017293105
DATE
02/09/2026

Report No: 2017293105			
Car: 2017293105			
VIN: AHTLT58E106048687			
Test results			
Shock and brake test			
Shock absorber test			
Brake test			

Shock and brake report



Sparewheel



Expansion bottle



Oil cap and dipstick



Manual transmission



ABS warning lights illuminated

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTLT58E106048687



CONDITION REPORT



Report No:
2017293105
DATE
02/09/2026



FRONT RIGHT CORNER



REAR LEFT CORNER



INTERIOR (FRONT DRIVER DOOR)



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



90 DEGREE FRONT

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTLT58E106048687



CONDITION REPORT



Report No:
2017293105
DATE
02/09/2026



90 DEGREE RIGHT




90 DEGREE REAR



90 DEGREE LEFT



LF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTLT58E106048687



CONDITION REPORT



Report No:
2017293105
DATE
02/09/2026



RF TYRE TREAD



LICENSE DISC



VIN PLATE OR STICKER



REAR



ENGINE 1



ENGINE 2

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTLT58E106048687



CONDITION REPORT



Report No:
2017293105
DATE
02/09/2026



CHASSIS



Park Light Front Left



Dim Light Left



Seat Front Left



Seat Rear



Seat Front Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTLT58E106048687



CONDITION REPORT



Report No:

2017293105

DATE

02/09/2026



Center Console / Cubbyhole + Lid



Front Fender Right



Door Front Right



Door Rear Right



Door Rear Right



Rear Fender Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTLT58E106048687



CONDITION REPORT



Report No:
2017293105
DATE
02/09/2026



Rear bumper



Rear bumper



Rear bumper



Fuel Flap



Rear Fender Left



Door Rear Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTLT58E106048687



CONDITION REPORT



Report No:
2017293105
DATE
02/09/2026



Door Front Left



Front Fender Left



Bonnet



Bonnet slam plate (Shock tower/ Inner tray)



Bonnet slam plate (Shock tower/ Inner tray)



Bonnet slam plate (Shock tower/ Inner tray)

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTLT58E106048687



CONDITION REPORT




Report No:
2017293105
DATE
02/09/2026



Fan Belt



Water level



Rim Front Right



Stabilizer Mounting Front Right



Front Bumper



Front Bumper

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTLT58E106048687



CONDITION REPORT



Report No:
2017293105
DATE
02/09/2026



Front Bumper



Front Bumper



Front Bumper



Front Bumper



Tyre Front Left



Stabilizer Mounting Front Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTLT58E106048687



CONDITION REPORT



Report No:
2017293105
DATE
02/09/2026



Sill Panel Left



Radiator Cross Member



Radiator Cross Member



Gearbox



Gearbox



Brake disc 2. Axle left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTLT58E106048687



CONDITION REPORT



Report No:
2017293105
DATE
02/09/2026



Tyre Rear Left



Brake disc 2. Axle right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTLT58E106048687