



CONDITION REPORT



Report No:  
2017306428  
DATE  
02/10/2026

MFC Auction House  
M57 Pretoria Rd, Glenmarais, KEMPTON PARK  
Gauteng

DEKRA MFC  
M57 Pretoria Rd - 1619  
KEMPTON PARK - GT  
08610 33572



Assignment

|                 |                   |                     |                          |
|-----------------|-------------------|---------------------|--------------------------|
| Client          | MFC Auction House | Inspection Location | MFC                      |
| Requested Date  | 02/10/2026        |                     | M57 Pretoria Road - 1619 |
| Inspection Date | 02/10/2026        |                     | Kempton Park -           |

Vehicle Data

|                 |                                                   |                         |                   |
|-----------------|---------------------------------------------------|-------------------------|-------------------|
| Vehicle Type    | PASSENGER VEHICLE                                 | Registered Owner        | MFC AUCTION HOUSE |
| Manufacturer    | TOYOTA                                            | Registration Number     | KF05YRGP          |
| Model           | HI-ACE 2.5 SESFIKILE 16-S DSL MINIBUS [2020-2022] | Register Number         |                   |
| VIN             | AHTSS22P107126788                                 | Date Of First Licensing |                   |
| Engine Number   |                                                   | Last COR                |                   |
| Doors           | 4                                                 | License Expiry Date     |                   |
| Color           | WHITE                                             | Power / Displacement    |                   |
| Year Model      | 2021                                              | Paint Finish            | C - COMMON        |
| Km Reading      | 675,765 KM                                        | Fuel                    | DIESEL            |
| Cab / Body Type | OTHERS                                            | Transmission            | MANUAL            |

Vehicle Options & Accessories

Items

VEHICLE INSPECTION

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za

VIN: AHTSS22P107126788



## CONDITION REPORT



Report No:

2017306428

DATE

02/10/2026

## Damage

## Repair Way

|                                                                      |                                         |
|----------------------------------------------------------------------|-----------------------------------------|
| Engine Oil Leak                                                      | Repair                                  |
| Engine Wiring Defective                                              | Repair                                  |
| Hoses Damaged                                                        | Repair                                  |
| Bonnet cable Damaged                                                 | Repair                                  |
| Bonnet stay and shocks Missing                                       | Replace                                 |
| Center Console / Cubbyhole + Lid Damaged                             | Replace                                 |
| Tail Light Left Cracked                                              | Replace                                 |
| Tail Light Right Cracked                                             | Replace                                 |
| Fuse box and fuses Damaged                                           | Replace                                 |
| Headlight Left Damaged                                               | Replace                                 |
| Seat Front Left Torn / Cut                                           | Repair                                  |
| Seat Front Right Torn / Cut                                          | Repair                                  |
| Seat Rear Torn / Cut                                                 | Repair                                  |
| Seat Rear ( 2. Row) Torn / Cut                                       | Repair                                  |
| Interior Mirror Missing                                              | Replace                                 |
| Door Hinges Front Right Damaged                                      | Repair                                  |
| Door Sealing Rubber Front Right Missing                              | Repair                                  |
| Boot Panel Left Missing                                              | Replace                                 |
| Front Bumper Damaged                                                 | Repair                                  |
| Bonnet Paintwork • Chipmarks                                         | Repair                                  |
| Front Fender Left Residual Traces of Repair                          | Replace                                 |
| Front Fender Right Damaged                                           | Repair                                  |
| Rear Fender Left Paintwork • Scratched                               | Repair                                  |
| Rear Fender Right Damaged                                            | Repair                                  |
| Front Fender Left / Inner Tray Damaged                               | Replace                                 |
| Door Front Left Paintwork • Scratched                                | Repair                                  |
| Door Front Right Dented                                              | Repair                                  |
| Boot Lid / Hatch door Dented                                         | Repair                                  |
| Rear bumper Damaged                                                  | Repair                                  |
| Sliding Door Paintwork • Scratched                                   | Repair                                  |
| Windscreen Cracked                                                   | Replace                                 |
| Brake Piping Leak                                                    | Replace                                 |
| Parking Brake Performance Left / Right Difference out of legal range | Repair                                  |
| Steering Rack Boot Right Leak                                        | Repair                                  |
| Hydraulics System Leak                                               | Repair                                  |
| Stabilizer Mounting Front Left Damaged                               | Replace                                 |
| Stabilizer Mounting Front Right Damaged                              | Replace                                 |
| Tyre Front Left Smooth                                               | Replace                                 |
| Tyre Front Right Smooth                                              | Replace                                 |
| Tyre Rear Left Smooth                                                | Replace                                 |
| Bolt(s) / Nut(s) Front Wheel Left Missing                            | Replace                                 |
| Gearbox Oil Leak                                                     | Repair                                  |
| Differential Oil Sweat                                               | Repair                                  |
| Fuel Tank Sweat                                                      | Repair                                  |
| Engine Smoke Excessive                                               | Repair                                  |
| Gear Selections Malfunction                                          | Repair                                  |
| Bonnet does not close                                                | Repair                                  |
| Warning lights illuminated                                           | Repair                                  |
| Vehicle idling while testing                                         | Battery                                 |
| R/R window is broken                                                 | Replace                                 |
| Body exterior                                                        | Signs of spray work done on body panels |

DEKRA Automotive (PTY) Ltd.  
 97 Willem Cruywagen Ave  
 Klerksoord, Pretoria, 0200  
 Phone: 012 542 4867  
[www.dekraauto.co.za](http://www.dekraauto.co.za)

VIN: AHTSS22P107126788



## CONDITION REPORT



Report No:

2017306428

DATE

02/10/2026

## Brakes

## Brake Test Results

|                     | Left               | Right              |                  |                                  |
|---------------------|--------------------|--------------------|------------------|----------------------------------|
|                     | Braking Force [KN] | Braking Force [KN] | Axle Weight [KG] | Deceleration [m/s <sup>2</sup> ] |
| Front               | 4.4                | 3.5                | -                |                                  |
| Rear                | 0.5                | 0.6                | -                |                                  |
| Emergency / Parking | 0.9                | 1.5                | -                |                                  |

## Tyres and Rims

## Tyre Specification &amp; Measurement

|             | Size   | Load/Speed Index | Manufacture | Model | Type* | Production Date | Tread Depth (mm) |
|-------------|--------|------------------|-------------|-------|-------|-----------------|------------------|
| Front Left  | 195R15 | 106/104R         | Annaite     | AC838 | V     | 0000            | 0 mm             |
| Front Right | 195R15 | 106/104R         | Annaite     | AN900 | V     | 0725            | 0 mm             |
| Rear Left   | 195R15 | 106/104R         | Annaite     | AN900 | V     | 0000            | 0 mm             |
| Rear Right  | 195R15 | 106/104R         | Annaite     | AN900 | V     | 0926            | 0 mm             |

\* Tyre Legend: V=Virgin, R=Recap

## Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

| No | System | Code  | Description                      | Status |
|----|--------|-------|----------------------------------|--------|
| 1  | ABS    | C1241 | LOW OR HIGH POWER SUPPLY VOLTAGE |        |

## Inspection Conditions

No Test Drive

Battery Flat

Engine number – not possible to verify engine number (not visible without dismantling)

Inspection conditions for the vehicle inspection were sufficient

## Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.

## Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

## Technician

Trevino Julius

This document was created electronically and is valid without signature.

## General Remarks:

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksord, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za

VIN: AHTSS22P107126788

**CONDITION REPORT**

**Report No:**  
2017306428  
**DATE**  
02/10/2026

The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
[www.dekraauto.co.za](http://www.dekraauto.co.za)

VIN: AHTSS22P107126788



## CONDITION REPORT



Report No:

2017306428

DATE

02/10/2026



FRONT RIGHT CORNER



REAR LEFT CORNER



90 DEGREE FRONT



90 DEGREE REAR



90 DEGREE RIGHT



90 DEGREE LEFT

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
[www.dekraauto.co.za](http://www.dekraauto.co.za)

VIN: AHTSS22P107126788



## CONDITION REPORT




Report No:  
2017306428  
DATE  
02/10/2026



ODOMETER



DASHBOARD (W/ ENGINE RUNNING)



INTERIOR (FRONT DRIVER DOOR)



Manual transmission



LF TYRE TREAD



Warning lights illuminated

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksord, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za

VIN: AHTSS22P107126788



## CONDITION REPORT



Report No:

2017306428

DATE

02/10/2026




Oil cap and dipstick



R/R window broken



Expansion bottle



No sparewheel



R/R window broken



LR TYRE TREAD

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
[www.dekraauto.co.za](http://www.dekraauto.co.za)


VIN: AHTSS22P107126788



## CONDITION REPORT



Report No:  
2017306428  
DATE  
02/10/2026



RR TYRE TREAD



RF TYRE TREAD



VIN PLATE OR STICKER



LICENSE DISC

| SHOCK AND BRAKE REPORT                                                                                                                                                                                        |  |  |  |
|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--|--|--|
| <p>Vehicle: Car<br/>           Model: 40460485907P NFI<br/>           Year: 2016<br/>           Year date: 12/17<br/>           Year make: 12/17</p>                                                          |  |  |  |
| <p>License plate: 40460485907P NFI<br/>           Make: 40460485907P NFI<br/>           Model: 40460485907P NFI<br/>           Year: 2016<br/>           Year date: 12/17<br/>           Year make: 12/17</p> |  |  |  |
| <p>Vehicle: Car<br/>           Model: 40460485907P NFI<br/>           Year: 2016<br/>           Year date: 12/17<br/>           Year make: 12/17</p>                                                          |  |  |  |
| <p>Vehicle: Car<br/>           Model: 40460485907P NFI<br/>           Year: 2016<br/>           Year date: 12/17<br/>           Year make: 12/17</p>                                                          |  |  |  |
| <p>Vehicle: Car<br/>           Model: 40460485907P NFI<br/>           Year: 2016<br/>           Year date: 12/17<br/>           Year make: 12/17</p>                                                          |  |  |  |
| <p>Vehicle: Car<br/>           Model: 40460485907P NFI<br/>           Year: 2016<br/>           Year date: 12/17<br/>           Year make: 12/17</p>                                                          |  |  |  |
| <p>Vehicle: Car<br/>           Model: 40460485907P NFI<br/>           Year: 2016<br/>           Year date: 12/17<br/>           Year make: 12/17</p>                                                          |  |  |  |
| <p>Vehicle: Car<br/>           Model: 40460485907P NFI<br/>           Year: 2016<br/>           Year date: 12/17<br/>           Year make: 12/17</p>                                                          |  |  |  |
| <p>Vehicle: Car<br/>           Model: 40460485907P NFI<br/>           Year: 2016<br/>           Year date: 12/17<br/>           Year make: 12/17</p>                                                          |  |  |  |

SHOCK AND BRAKE REPORT

| DIAGNOSTIC REPORT PAGE 1                                                                                                                             |  |
|------------------------------------------------------------------------------------------------------------------------------------------------------|--|
| <p>Vehicle: Car<br/>           Model: 40460485907P NFI<br/>           Year: 2016<br/>           Year date: 12/17<br/>           Year make: 12/17</p> |  |
| <p>Vehicle: Car<br/>           Model: 40460485907P NFI<br/>           Year: 2016<br/>           Year date: 12/17<br/>           Year make: 12/17</p> |  |
| <p>Vehicle: Car<br/>           Model: 40460485907P NFI<br/>           Year: 2016<br/>           Year date: 12/17<br/>           Year make: 12/17</p> |  |
| <p>Vehicle: Car<br/>           Model: 40460485907P NFI<br/>           Year: 2016<br/>           Year date: 12/17<br/>           Year make: 12/17</p> |  |
| <p>Vehicle: Car<br/>           Model: 40460485907P NFI<br/>           Year: 2016<br/>           Year date: 12/17<br/>           Year make: 12/17</p> |  |
| <p>Vehicle: Car<br/>           Model: 40460485907P NFI<br/>           Year: 2016<br/>           Year date: 12/17<br/>           Year make: 12/17</p> |  |
| <p>Vehicle: Car<br/>           Model: 40460485907P NFI<br/>           Year: 2016<br/>           Year date: 12/17<br/>           Year make: 12/17</p> |  |
| <p>Vehicle: Car<br/>           Model: 40460485907P NFI<br/>           Year: 2016<br/>           Year date: 12/17<br/>           Year make: 12/17</p> |  |
| <p>Vehicle: Car<br/>           Model: 40460485907P NFI<br/>           Year: 2016<br/>           Year date: 12/17<br/>           Year make: 12/17</p> |  |

DIAGNOSTIC REPORT PAGE 1

DEKRA Automotive (PTY) Ltd.  
 97 Willem Cruywagen Ave  
 Klerksoord, Pretoria, 0200  
 Phone: 012 542 4867  
 www.dekraauto.co.za

VIN: AHTSS22P107126788



## CONDITION REPORT




Report No:

2017306428

DATE

02/10/2026



DIAGNOSTIC REPORT PAGE 2



REAR



CHASSIS



ENGINE 2



ENGINE 1



Hoses

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
[www.dekraauto.co.za](http://www.dekraauto.co.za)

VIN: AHTSS22P107126788



## CONDITION REPORT



Report No:

2017306428

DATE

02/10/2026



Center Console / Cubbyhole + Lid



Fuse box and fuses



Seat Front Left



Seat Rear



Seat Rear



Seat Rear ( 2. Row)

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksord, Pretoria, 0200  
Phone: 012 542 4867  
[www.dekraauto.co.za](http://www.dekraauto.co.za)

VIN: AHTSS22P107126788



## CONDITION REPORT




Report No:

2017306428

DATE

02/10/2026



Seat Rear ( 2. Row)



Boot Panel Left



Windscreen



Windscreen



Windscreen



Headlight Left

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
[www.dekraauto.co.za](http://www.dekraauto.co.za)

VIN: AHTSS22P107126788



## CONDITION REPORT



Report No:

2017306428

DATE

02/10/2026



Headlight Left



Headlight Left



Engine Wiring



Bonnet stay and shocks



Front Fender Left



Front Fender Left

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksord, Pretoria, 0200  
Phone: 012 542 4867  
[www.dekraauto.co.za](http://www.dekraauto.co.za)

VIN: AHTSS22P107126788



## CONDITION REPORT



Report No:

2017306428

DATE

02/10/2026



Bonnet



Bonnet



Door Front Left



Sliding Door



Rear Fender Left



Rear Fender Left

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksord, Pretoria, 0200  
Phone: 012 542 4867  
[www.dekraauto.co.za](http://www.dekraauto.co.za)

VIN: AHTSS22P107126788



## CONDITION REPORT



Report No:

2017306428

DATE

02/10/2026




Rear Fender Left



Boot Lid / Hatch door



Tail Light Right



Tail Light Left



Rear Fender Right



Rear Fender Right

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
[www.dekraauto.co.za](http://www.dekraauto.co.za)

VIN: AHTSS22P107126788



## CONDITION REPORT



Report No:  
2017306428  
DATE  
02/10/2026



Rear Fender Right



Rear Fender Right



Front Fender Right



Door Front Right



Seat Front Right



Bonnet cable

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksord, Pretoria, 0200  
Phone: 012 542 4867  
[www.dekraauto.co.za](http://www.dekraauto.co.za)

VIN: AHTSS22P107126788



## CONDITION REPORT



Report No:  
2017306428  
DATE  
02/10/2026



Door Sealing Rubber Front Right



Door Sealing Rubber Front Right



Interior Mirror



Front Bumper



Front Bumper



Front Bumper

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
[www.dekraauto.co.za](http://www.dekraauto.co.za)

VIN: AHTSS22P107126788



## CONDITION REPORT



Report No:

2017306428

DATE

02/10/2026



Front Bumper



Bolt(s) / Nut(s) Front Wheel Left




Rear bumper



Rear bumper



Hydraulics System



Hydraulics System

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksord, Pretoria, 0200  
Phone: 012 542 4867  
[www.dekraauto.co.za](http://www.dekraauto.co.za)

VIN: AHTSS22P107126788



## CONDITION REPORT



Report No:

2017306428

DATE


02/10/2026



Steering Rack Boot Right



Tyre Front Right




Tyre Front Left



Engine



Engine



Engine

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
[www.dekraauto.co.za](http://www.dekraauto.co.za)

VIN: AHTSS22P107126788



## CONDITION REPORT




Report No:  
2017306428  
DATE  
02/10/2026



Stabilizer Mounting Front Left



Stabilizer Mounting Front Left



Front Fender Left / Inner Tray



Front Fender Left / Inner Tray



Front Fender Left / Inner Tray



Front Fender Left / Inner Tray

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
[www.dekraauto.co.za](http://www.dekraauto.co.za)

VIN: AHTSS22P107126788



## CONDITION REPORT



Report No:

2017306428

DATE

02/10/2026



Stabilizer Mounting Front Right




Engine




Engine



Gearbox



Gearbox



Gearbox

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksord, Pretoria, 0200  
Phone: 012 542 4867  
[www.dekraauto.co.za](http://www.dekraauto.co.za)

VIN: AHTSS22P107126788



## CONDITION REPORT



Report No:  
2017306428  
DATE  
02/10/2026



Gearbox



Fuel Tank



Fuel Tank



Tyre Rear Left



Brake Piping



Brake Piping

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
[www.dekraauto.co.za](http://www.dekraauto.co.za)

VIN: AHTSS22P107126788



CONDITION REPORT



Report No:  
2017306428  
DATE  
02/10/2026



Brake Piping



Differential



Differential



Differential



Door Hinges Front Right

|              |      |       |            |         |
|--------------|------|-------|------------|---------|
|              | left | right | Difference | Weight  |
| Front axle   | 0,22 | 0,08  | 64 %       | 1497 kg |
| Rear axle    | 0,17 | 0,19  | 11 %       | 1067 kg |
| Total weight |      |       |            | 2564 kg |

|                            |             |         |            |              |
|----------------------------|-------------|---------|------------|--------------|
| Brake test                 |             |         |            |              |
|                            | Brake force |         | Difference |              |
|                            | left        | right   |            |              |
| Front axle                 | 4,41 kN     | 3,57 kN | 19 %       |              |
| Parking brake              | 0,98 kN     | 1,58 kN | 38 %       |              |
| Rear axle                  | 0,54 kN     | 0,65 kN | 16 %       |              |
| Final evaluation static    |             |         |            |              |
| Deceleration service brake |             | 36 %    |            |              |
| Deceleration parking brake |             | 10 %    |            | Total weight |

Parking Brake Performance

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za

VIN: AHTSS22P107126788