



CONDITION REPORT



Report No:
2017305252
DATE
30/09/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572



Assignment

Client	MFC Auction House	Inspection Location	MFC
Requested Date	30/09/2026		M57 Pretoria Road - 1619
Inspection Date	30/09/2026		Kempton Park - GT

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	MFC
Manufacturer	TOYOTA	Registration Number	LD21KFGP
Model	HI-ACE 2.5 SESFIKILE 16-S DSL MINIBUS [2021-2024]	Register Number	
VIN	AHTSS22P307146668	Date Of First Licensing	
Engine Number		Last COR	
Doors	4	License Expiry Date	30/06/2026
Color	YELLOW	Power / Displacement	
Year Model	2023	Paint Finish	C - COMMON
Km Reading	314,417 KM	Fuel	DIESEL
Cab / Body Type	OTHERS	Transmission	MANUAL

Vehicle Options & Accessories

Items

VEHICLE INSPECTION

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTSS22P307146668



CONDITION REPORT



Report No:

2017305252

DATE

30/09/2026

Damage

Repair Way

Tail Light Right Cracked	Replace
Seat Front Left Damaged	Repair
Seat Front Right Damaged	Repair
Seat Rear Damaged	Repair
Seat Rear (2. Row) Damaged	Repair
Front Bumper Damaged	Repair
Grill Damaged	Repair
Bonnet Dented	Repair
B • Pillar Left Paintwork • Scratched	Repair
Front Fender Left Paintwork • Scratched	Repair
Front Fender Right Dented	Repair
Rear Fender Left Dented	Repair
Door Front Left Paintwork • Chipmarks	Repair
Rear bumper Paintwork • Scratched	Repair
Sliding Door Poor Alignment	Repair
Windscreen Cracked	Replace
Bolt(s) / Nut(s) Front Wheel Right Missing	Replace
All four hup caps missing	Repair
Warning light illuminated	Repair

Brakes

Brake Test Results

	Left	Right	Axle Weight [KG]	Deceleration [m/s ²]
	Braking Force [KN]	Braking Force [KN]		
Front	5.4	3.9	-	
Rear	1.9	2.1	-	
Emergency / Parking	2.4	2.6	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	195R15	106/104S	Toyo	Ho7	V	0325	2 mm
Front Right	195R15	106/104S	Toyo	Ho7	V	1124	1 mm
Rear Left	195R15	106/104S	Toyo	Ho7	V	0925	3 mm
Rear Right	195R15	106/104S	Toyo	Ho7	V	2025	2 mm

* Tyre Legend: V=Virgin, R=Recap

DEKRA Automotive (PTY) Ltd.
 97 Willem Cruywagen Ave
 Klerksoord, Pretoria, 0200
 Phone: 012 542 4867
 www.dekraauto.co.za

VIN: AHTSS22P307146668



CONDITION REPORT



Report No:
2017305252
DATE
30/09/2026

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	CURRENT	B1801	DRIVING SIDE SQUIB CIRCUIT OPEN	

Inspection Conditions

No Test Drive

Battery Flat

Engine number – not possible to verify engine number (not visible without dismantling)

Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS. Body • Exterior: Spray work done on some body panels.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Andrick Wymers

This document was created electronically and is valid without signature.

General Remarks:

The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTSS22P307146668



CONDITION REPORT



Report No:
2017305252
DATE
30/09/2026

Vehicle Information			
Make/Model	Year	Engine	Transmission
Toyota Hilux	2015	2.5L Diesel	5-Speed Manual
Registration	Color	Condition	Inspection Date
LD 23 XG-57	Yellow	Good	30/09/2026
Inspection Results			
System	Test	Result	Remarks
Engine	Oil Level	OK	
Engine	Water Level	OK	
Engine	Belts & Hoses	OK	
Engine	Exhaust	OK	
Engine	Idle Speed	OK	
Engine	Throttle Response	OK	
Engine	Acceleration	OK	
Engine	Brake Pedal	OK	
Engine	Clutch Pedal	OK	
Engine	Gear Shift	OK	
Engine	Steering	OK	
Engine	Suspension	OK	
Engine	Tires	OK	
Engine	Washers	OK	
Engine	Lights	OK	
Engine	Horn	OK	
Engine	Security	OK	
Engine	Interior	OK	
Engine	Exterior	OK	
Engine	Overall	OK	

Shock and brake report

Vehicle Diagnostic Report			
Make/Model	Year	Engine	Transmission
Toyota Hilux	2015	2.5L Diesel	5-Speed Manual
Registration	Color	Condition	Inspection Date
LD 23 XG-57	Yellow	Good	30/09/2026
Diagnostic Results			
System	Test	Result	Remarks
Engine	Oil Level	OK	
Engine	Water Level	OK	
Engine	Belts & Hoses	OK	
Engine	Exhaust	OK	
Engine	Idle Speed	OK	
Engine	Throttle Response	OK	
Engine	Acceleration	OK	
Engine	Brake Pedal	OK	
Engine	Clutch Pedal	OK	
Engine	Gear Shift	OK	
Engine	Steering	OK	
Engine	Suspension	OK	
Engine	Tires	OK	
Engine	Washers	OK	
Engine	Lights	OK	
Engine	Horn	OK	
Engine	Security	OK	
Engine	Interior	OK	
Engine	Exterior	OK	
Engine	Overall	OK	

Diagnostic report



FRONT RIGHT CORNER



REAR LEFT CORNER



INTERIOR (FRONT DRIVER DOOR)



DASHBOARD (W/ ENGINE RUNNING)

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTSS22P307146668



CONDITION REPORT



Report No:
2017305252
DATE
30/09/2026



ODOMETER



Manual



90 DEGREE FRONT



90 DEGREE RIGHT



90 DEGREE REAR



90 DEGREE LEFT

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTSS22P307146668



CONDITION REPORT



Report No:
2017305252
DATE
30/09/2026



LF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD



RF TYRE TREAD



No spare wheel



LICENSE DISC

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTSS22P307146668



CONDITION REPORT



Report No:
2017305252
DATE
30/09/2026



VIN PLATE OR STICKER




ENGINE 1



ENGINE 2



CHASSIS



Oil cap and dipstick



Coolant bottle

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTSS22P307146668




CONDITION REPORT



Report No:
2017305252
DATE
30/09/2026



Water level



Bonnet



Seat Front Left



Seat Front Right



Seat Rear



Seat Rear (2. Row)

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTSS22P307146668



CONDITION REPORT



Report No:
2017305252
DATE
30/09/2026



Windscreen




Front Bumper



Grill



Front Fender Right



Front Fender Left



Door Front Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTSS22P307146668




CONDITION REPORT



Report No:
2017305252
DATE
30/09/2026



B • Pillar Left



Sliding Door



Rear Fender Left



Rear bumper



Rear bumper



Tail Light Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTSS22P307146668



CONDITION REPORT



Report No:
2017305252
DATE
30/09/2026



Bolt(s) / Nut(s) Front Wheel Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTSS22P307146668