



CONDITION REPORT



Report No:
2017305374
DATE
30/09/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572



Assignment

Client	MFC Auction House	Inspection Location	MFC
Requested Date	30/09/2026		M57 Pretoria Road - 1619
Inspection Date	30/09/2026		Kempton Park -

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	MFC
Manufacturer	TOYOTA	Registration Number	KXW151MP
Model	HI-ACE 2.5 SESFIKILE 16-S DSL MINIBUS [2021-2024]	Register Number	
		Date Of First Licensing	
VIN	AHTSS22P307153989	Last COR	
Engine Number		License Expiry Date	30/04/2027
Doors	4	Power / Displacement	
Color	WHITE	Paint Finish	TWO COAT UNI
Year Model	2023	Fuel	DIESEL
Km Reading	203,754 KM	Transmission	MANUAL
Cab / Body Type	STATION WAGON		

Vehicle Options & Accessories

Items

VEHICLE INSPECTION

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTSS22P307153989



CONDITION REPORT



Report No:
2017305374
DATE
30/09/2026



Damage	Repair Way
Bonnet stay and shocks Defective	Repair
Tail Light Left Cracked	Replace
Tail Light Right Defective	Repair
Headlight Left Scratched	Replace
Seat Front Left Damaged	Repair
Seat Front Right Damaged	Repair
Seat Rear Damaged	Repair
Seat Rear (2. Row) Torn / Cut	Repair
Door Panel Front Left Dirty	Repair
Door Panel Front Right Dirty	Repair
Door Sealing Rubber Rear Left Damaged	Replace
Carpet Rear Damaged	Repair
Steering Wheel Trim Excessive Wear & Tear	Repair
Front Bumper Damaged	Repair
Grill Paintwork • Scratched	Repair
Bonnet Damaged	Repair
B • Pillar Left Residual Traces of Repair	Repair
Rear Fender Left Residual Traces of Repair	Repair
Rear Fender Right Damaged	Repair
Front Fender Left / Inner Tray Damaged	Repair
Front Fender Right / Inner Tray Damaged	Repair
Rear Fender Left / Inner Tray Damaged	Repair
Rear Fender Right / Inner Tray Paintwork • Scratched	Repair
Door Front Left Damaged	Repair
Door Rear Left Residual Traces of Repair	Repair
Boot Lid / Hatch door Damaged	Repair
Rear bumper Paintwork • Scratched	Repair
Sill Panel Left Damaged	Repair
Sill Panel Right Damaged	Repair
Windscreen Cracked	Replace
Caliper 1. Axle left Damaged	Replace
Caliper 1. Axle right Leak	Repair
Service Brake Performance Front Axle Left / Right	Repair
Difference out of legal range	
Service Brake Performance Rear Axle Left / Right	Repair
Difference out of legal range	
Parking Brake Performance Insufficient	Repair
Steering Rack Defective	Replace
Mounting Rubber(s) Rear Axle Left Damaged	Replace
Mounting Rubber(s) Rear Axle Right Damaged	Replace
Tyre Front Left Damaged	Replace
Tyre Front Right Worn	Replace
Rim Front Left Dented	Repair
Bolt(s) / Nut(s) Front Wheel Right Missing	Replace
Chassis Damaged	Repair
Sub Frame Damaged	Repair
Silencer Damaged	Replace
Catalytic converter Missing	Replace
Gearbox Mountings Damaged	Replace
Gearbox Oil Sweat	Repair
Fuel Tank Damaged	Replace
Radiator Cradle Damaged	Replace
Gear Selections Malfunction	Repair
Wheel Spanner Missing	Replace
Triangle Missing	Replace
Warning lights illuminated on dashboard	Repair

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTSS22P307153989



CONDITION REPORT



Report No:
2017305374
DATE
30/09/2026

Damage	Repair Way
Front left and right shock absorbers weak	Replace
Deceleration service brake defective	Repair
Spare wheel missing	Replace
Engine oil sump damaged	Replace
Rear left door step box missing	Replace
Left side mirror glass missing	Replace

Brakes

Brake Test Results

	Left Braking Force [KN]	Right Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s ²]
Front	5.42	3.34	-	
Rear	0.58	3.61	-	
Emergency / Parking	0	0	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	195R15C	106R	Autogrip	Vanmax	V	2925	0 mm
Front Right	195R15C	106R	Autogrip	Vanmax	V	2925	0 mm
Rear Left	195R15C	106R	Autogrip	Vanmax	V	2925	3 mm
Rear Right	195R15C	106R	Autogrip	Vanmax	V	2925	3 mm

* Tyre Legend: V=Virgin, R=Recap

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	ENGINE AND ECT	P0335	CRANKSHAFT POSITION(CKP) SENSOR A CIRCUIT	

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS. Interior: Rear left window net loose. Vehicle interior dirty and panels scratched.
Body • Exterior: Tow bar damaged. Poor residual traces of repair on body panels. Body panels misaligned. Stone chips and spray work on body panels. Dents and scratches on body panels. Signs of impact damage to front of vehicle.
Steering: Steering rack leak.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTSS22P307153989

**CONDITION REPORT**

Report No:
2017305374
DATE
30/09/2026

Axle and Suspension: Front suspension faulty
Road Test: Excessive engine vibration. Gearbox faulty. Vehicle unsafe to drive

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Sibusiso Mokase

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTSS22P307153989



CONDITION REPORT



Report No:

2017305374

DATE _____

30/09/2026

[illegible]

Brake and shock absorber report

AUTOS		1997 Model Year		MSRP		1997 EPA est. city/hwy/mix							
AUTOS		Model		Price		City/hwy/mix							
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCKS													
TRUCK													

Diagnostic report page 1

Device Name/Model	Part # or P/N or MFR # or ETC	Part # or P/N or MFR # or ETC
216940	ABS motor relay control unit	History
216939	ABS motor initialization with ECM/PCM-IV™	History
169174	Lost communication with lambda sensor/air sensor module	History
169176	Loss of normal location with steering angle sensor (SAS) module	History
ERR clearing (3 STROs)		
DTC	description	Status
RT391	Driving side squib circuit open	Current
RT392	Driving side squib circuit open	History
RT393	Pass. side squib open	History

Technician Notes
2013/09/04

Customer name _____
 Technician _____
 Date _____

© 2007 Pearson Education, Inc. All Rights Reserved

Diagnostic report page 2



FRONT RIGHT CORNER



REAR LEFT CORNER



INTERIOR (FRONT DRIVER DOOR)

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTSS22P307153989



CONDITION REPORT



Report No:
2017305374
DATE
30/09/2026



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



Manual Transmission



90 DEGREE FRONT



90 DEGREE RIGHT



90 DEGREE REAR

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTSS22P307153989



CONDITION REPORT



Report No:
2017305374
DATE
30/09/2026



90 DEGREE LEFT



LF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD



RF TYRE TREAD



LICENSE DISC

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTSS22P307153989



CONDITION REPORT



Report No:
2017305374
DATE
30/09/2026




VIN PLATE OR STICKER



ENGINE 1



Front chassis



Rear chassis



Engine oil sump



Oil cap and dipstick

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTSS22P307153989



CONDITION REPORT



Report No:

2017305374

DATE

30/09/2026



ADDITIONAL 7



Seat Front Right



Front Fender Right / Inner Tray



Steering Wheel Trim



Door Panel Front Right



Rear Fender Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTSS22P307153989



CONDITION REPORT



Report No:
2017305374
DATE
30/09/2026



Bonnet



Front Bumper



Front Bumper



Front Bumper



Door Front Left



B • Pillar Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTSS22P307153989



CONDITION REPORT



Report No:
2017305374
DATE
30/09/2026



Door Rear Left



Rear Fender Left



Seat Front Left



Door Panel Front Left



Tail Light Left



Tail Light Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTSS22P307153989



CONDITION REPORT



Report No:
2017305374
DATE
30/09/2026




Boot Lid / Hatch door




Front Bumper




Windscreen



Parking Brake Performance



Service Brake Performance Rear Axle



Service Brake Performance Front Axle

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTSS22P307153989



CONDITION REPORT



Report No:
2017305374
DATE
30/09/2026



Headlight Left



Water level



Bolt(s) / Nut(s) Front Wheel Right



Grill



Rim Front Left



Sill Panel Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTSS22P307153989



CONDITION REPORT



Report No:

2017305374

DATE

30/09/2026



Rear bumper



Rear bumper



Rear bumper



Sill Panel Right



Sill Panel Right



Steering Rack

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTSS22P307153989



CONDITION REPORT



Report No:

2017305374

DATE

30/09/2026



Radiator Cradle



Caliper 1. Axle right



Tyre Front Right



Tyre Front Left



Chassis



Gearbox

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTSS22P307153989



CONDITION REPORT



Report No:
2017305374
DATE
30/09/2026



Fuel Tank



Gearbox Mountings



Catalytic converter



Mounting Rubber(s) Rear Axle Left



Mounting Rubber(s) Rear Axle Right



Silencer

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTSS22P307153989



CONDITION REPORT



Report No:

2017305374

DATE

30/09/2026



Caliper 1. Axle left



Front Fender Left / Inner Tray



Front Fender Right / Inner Tray



Sub Frame



Sub Frame



Radiator Cradle

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za


VIN: AHTSS22P307153989



CONDITION REPORT




Report No:
2017305374
DATE
30/09/2026



Water level



Bonnet stay and shocks




Carpet Rear



Seat Rear



Seat Rear



Seat Rear (2. Row)

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTSS22P307153989



CONDITION REPORT



Report No:
2017305374
DATE
30/09/2026



Rear Fender Left / Inner Tray



Rear Fender Right / Inner Tray



Door Sealing Rubber Rear Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTSS22P307153989