



CONDITION REPORT

Report No: 2016850329

DATE
22/04/2025

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572



Assignment

Client	MFC Auction House	Inspection Location	MFC
Requested Date	22/04/2025		M57 Pretoria Road - 1619
Inspection Date	22/04/2025		Kempton Park - GT

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	
Manufacturer	TOYOTA	Registration Number	HDN122L
Model	HI-ACE 2.5 SESFIKILE 16-S DSL MINIBUS [2021-2024]	Register Number	
VIN	AHTSS22P807159142	Date Of First Licensing	
Engine Number		Last COR	
Doors	5	License Expiry Date	28/02/2026
Color	WHITE	Power / Displacement	
Year Model	2024	Paint Finish	TWO COAT UNI
Km Reading	60,162 KM	Fuel	DIESEL
Cab / Body Type	STATION WAGON	Transmission	MANUAL

Vehicle Options & Accessories

Items

VEHICLE INSPECTION

Damage	Repair Way
Engine Oil Leak	Repair
Radio/CD/USB Damaged	Repair
Engine Management Lights Set	Repair
Seat Front Right Damaged	Repair
Door Panel Rear Left Damaged	Repair
Front Bumper Damaged	Repair
Bonnet Damaged	Repair
Rear Fender Right Damaged	Repair
Boot Lid / Hatch door Damaged	Repair
Windscreen Damaged	Replace
Caliper 1. Axle left Leak	Repair
Caliper 1. Axle right Leak	Repair
Wheel Cylinder / Caliper 2. Axle left Damaged	Replace
Wheel Cylinder / Caliper 2. Axle right Damaged	Repair
Brake disc 1. Axle left Worn	Replace
Brake disc 1. Axle right Worn	Replace
Brake Drum 2. Axle left Defective	Replace
Brake Drum 2. Axle right Defective	Repair
Brake Piping Damaged	Repair

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTSS22P807159142



CONDITION REPORT

Report No: 2016850329

DATE
22/04/2025

Damage	Repair Way
Steering box Leak	Repair
Tyre Front Left Worn	Replace
Tyre Front Right Damaged	Replace
Tyre Rear Left Worn	Replace
Tyre Rear Right Worn	Replace
Gearbox Oil Leak	Repair
Differential Oil Leak	Repair
Steering Noisy	Repair
Brakes Insufficient	Repair

Brakes

Brake Test Results

	Left Braking Force [KN]	Right Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s²]
Front	4.48	3.57	-	
Rear	0.64	0.83	-	
Emergency / Parking	0	0	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	205/75R14	107S	Yokohama	Radial	V	4722	0 mm
Front Right	205/75R14	107S	Yokohama	Radial	V	2223	2 mm
Rear Left	205/75R14	107S	Yokohama	Radial	V	4820	0 mm
Rear Right	205/75R14	107S	Yokohama	Radial	V	4822	0 mm

* Tyre Legend: V=Virgin, R=Recap

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	ENGINE AND ECT	P0500	VEHICLE SPEED SENSOR	

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: 15 DTC'S AT TIME OF TESTING SEE DTC REPORT.Engine Compartment: vehicle is leaking diesel on engine. starter bolts loose.
Body • Exterior: Minor dents and scratches to some body panels. Signs of stone chips to some body panels. Signs of repair work done to somebody panels. Poor alignment to somebody panels.
Brakes: handbrake does not work.
Road Test: Vehicle is unsafe to drive.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTSS22P807159142



CONDITION REPORT

Report No: 2016850329

DATE
22/04/2025

Werner Laubscher

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTSS22P807159142




CONDITION REPORT


Report No: 2016850329

DATE
22/04/2025

Brake test



Diagnostics



Diagnostics



FRONT RIGHT CORNER



REAR LEFT CORNER



INTERIOR (FRONT DRIVER DOOR)

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTSS22P807159142



CONDITION REPORT

Report No: 2016850329

DATE
22/04/2025

DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



Manual.



90 DEGREE FRONT



90 DEGREE RIGHT



90 DEGREE REAR

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTSS22P807159142



CONDITION REPORT


Report No: 2016850329

DATE
22/04/2025

90 DEGREE LEFT



LF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD



RF TYRE TREAD



LICENSE DISC

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTSS22P807159142



CONDITION REPORT

Report No: 2016850329

DATE
22/04/2025

VIN PLATE OR STICKER



ENGINE 1



Undercarriage front.



Undercarriage rear.



Oil cap and dipstick.



Water level

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTSS22P807159142



CONDITION REPORT

Report No: 2016850329

DATE
22/04/2025

Front Bumper



Front Bumper



Bonnet



Boot Lid / Hatch door



Rear Fender Right



Windscreen

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTSS22P807159142



CONDITION REPORT

Report No: 2016850329

DATE
22/04/2025

Seat Front Right



Door Panel Rear Left



Radio/CD/USB



Engine Management Lights



Wheel Cylinder / Caliper 2. Axle left



Wheel Cylinder / Caliper 2. Axle right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTSS22P807159142



CONDITION REPORT

Report No: 2016850329

DATE
22/04/2025

Brake Piping



Differential



Brake Drum 2. Axle left



Brake Drum 2. Axle right



Engine



Gearbox

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTSS22P807159142



CONDITION REPORT

Report No: 2016850329

DATE
22/04/2025

Caliper 1. Axle left



Caliper 1. Axle right



Brake disc 1. Axle right



Brake disc 1. Axle left



Steering box



Tyre Front Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTSS22P807159142



CONDITION REPORT

Report No: 2016850329

DATE
22/04/2025

Tyre Rear Left



Tyre Front Left



Tyre Rear Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTSS22P807159142