



Shop Name: Dekra MFC Auction House  
Tel: --  
Email: --  
Address: MFC AUCTION HOUSE  
M57 PRETORIA ROAD  
KEMPTON PARK

Report ID: MAXIA20250422115724  
Test Time: 2025-04-22 11:57:24  
Technician: Travino

# Volkswagen VEHICLE DIAGNOSTIC REPORT

## Vehicle Information

--/Volkswagen/6RS - Polo Vivo 2018 >/--  
VIN: AAVZZZ6RZKU003178  
Odometer Reading: 168869  
License Plate: JRC363MP

## Customer Information

Name: Dekra MFC AUCTION HOUSE  
Tel: 0861033572

## Device information

Scanner: MaxiSys MS906 BT  
Version: V22.00  
Serial Number: VB8GJCC01514  
Repair Order Number: --

## System Scanned( 9 )

| System                           | Status/DTC  |
|----------------------------------|---|
| 01 - Engine Control Module 1     |  0   |
| 03 - Brakes 1                    |  1   |
| 09 - Electronic central electric |  3  |
| 15 - Airbag                      |  1 |
| 17 - Instrument cluster          |  1 |
| 19 - Gateway                     |  1 |
| 25 - Anti-Theft Immobilizer      |  0 |
| 44 - Power Steering              |  3 |
| 56 - Radio                       |  1 |

## DTC ( 11 )

### 03 - Brakes 1 ( 1 DTC )

| DTC     | Description                     | Status           |
|---------|---------------------------------|------------------|
| U010000 | Lost Communication with ECM/PCM | Passive/Sporadic |

### 09 - Electronic central electric ( 3 DTCs )

| DTC       | Description   | Status           |
|-----------|---|------------------|
| 00532:002 | Supply voltage - Lower limit not reached                                  | Passive/Sporadic |
| 00446:002 | Function limitation due to insufficient voltage - Lower limit not reached | Passive/Sporadic |
| 01598:000 | Drive battery voltage   | Passive/Sporadic |

### 15 - Airbag ( 1 DTC )

| DTC | Description | Status |
|-----|-------------|--------|
|-----|-------------|--------|



|         |                                   |                  |
|---------|-----------------------------------|------------------|
| U101100 | Supply voltage<br>Voltage too low | Passive/Sporadic |
|---------|-----------------------------------|------------------|

17 - Instrument cluster ( 1 DTC )

| DTC     | Description                       | Status           |
|---------|-----------------------------------|------------------|
| U101100 | Supply voltage<br>Voltage too low | Passive/Sporadic |

19 - Gateway ( 1 DTC )

| DTC       | Description                                   | Status           |
|-----------|---|------------------|
| 01314:004 | Engine control unit - No signal/communication | Passive/Sporadic |

44 - Power Steering ( 3 DTCs )

| DTC     | Description                                    | Status           |
|---------|--|------------------|
| U111100 | Function restriction caused by missing message | Passive/Sporadic |
| U140A00 | Terminal 30<br>Open circuit                    | Passive/Sporadic |
| U101100 | Supply voltage<br>Voltage too low              | Passive/Sporadic |

56 - Radio ( 1 DTC )

| DTC       | Description                      | Status        |
|-----------|----------------------------------|---------------|
| 01044:000 | Control module incorrectly coded | Active/static |

Technician Notes  
2016850234

Customer name: \_\_\_\_\_

Technician: \_\_\_\_\_

Date: \_\_\_\_\_

Note:Please save a copy of this report for your records.