AUTEL

Shop: DEKRA MFC

Tel: --Email: --

Address: MFC Auction House

Kempton Park

Report ID: MAXIA20240109144136 Test Time: 2024-01-09 14:41:36

Technician: Sbu

Page 1

# Volkswagen VEHICLE DIAGNOSTIC REPORT

**Vehicle Information** 

--/Volkswagen/Polo TSI/--VIN: AAVZZZAWZMU056005

**Customer Information** 

Name: DEKRA AUTOMATIC MFC MFC AUCTION HOUSE

**Device information** 

Scanner: MaxiSys MS906 BT

Version: V19.00

Odometer Reading: 62675km License Plate: LH00VTGP

Tel: 0861033572

Serial Number: VB8GJCC01482

Repair Order Number: --

### 🔁 System Scanned( 10 )

System	Status/DTC
01 - Engine Control Module 1	<b>Q</b> 9
02 - Transmission electronics	<b>②</b> 0
03 - Brakes 1	<b>Q</b> 2
08 - Air Conditioning	<b>②</b> 0
09 - Electronic central electric	<b>②</b> 0
15 - Airbag	<b>Q</b> 1
17 - Instrument cluster	<b>Q</b> 3
19 - Gateway	<b>Q</b> 1
44 - Power Steering	<b>Q</b> 2
5F - Information electronics 1	<b>Q</b> 1

# **DTC (19)**

#### 01 - Engine Control Module 1 (9 DTCs)

DTC	Description	Status
P06E900	Engine Starter Performance	Passive/Sporadic
U041600	Invalid data received from vehicle dynamics control module	Passive/Sporadic
P013A00	O2 Sensor Bank 1 Sensor 2 Slow Response - Rich to Lean	Passive/Sporadic
P036600	Camshaft Position (CMP) sensor circuit Range/performance	Passive/Sporadic
P008700	Fuel rail/system pressure - too low	Passive/Sporadic

AUTEL www.autel.com

MaxiSys MS906 BT

/Volkswagen/Pol	o TSI Test Time: 2024-01-09 14:41:3	Report ID: MAXIA20240109144136
P030000	Random/multiple cylinder Misfire detected	Passive/Sporadic
P030300	Cylinder 3 Misfire detected	Passive/Sporadic
P014800	Fuel Delivery Error	Passive/Sporadic
P125000	Fuel level too low	Passive/Sporadic
03 - Brakes 1 (	2 DTCs)	
DTC	Description	Status
C101C07	Left rear Wheel Speed Sensor (WSS) Mechanical fault	Active/static
C101D07	Right rear Wheel Speed Sensor (WSS) - mechanical	fault Active/static
15 - Airbag ( 1	DTC)	
DTC	Description	Status
B13BCF2	Multiple collision brake No function	Passive/Sporadic
17 - Instrumer	t cluster ( 3 DTCs )	
DTC	Description	Status
U111000	Function restriction caused by communication inter	ruption Passive/Sporadic
B104B31	Key No signal	Passive/Sporadic
B104C29	Key Range/performance	Passive/Sporadic
19 - Gateway (	1 DTC)	
DTC	Description	Status
B1802F1	NV-Energy management Alarm triggered	Passive/Sporadic
44 - Power Ste	eering ( 2 DTCs )	
DTC	Description	Status
U112300	Databus error value received	Passive/Sporadic
B200FF0	Internal malfunction	Passive/Sporadic
5F - Informatio	on electronics 1 (1 DTC)	
DTC	Description	Status
B2008F0	Function restriction Caused by overtemperature protection	Passive/Sporadic



0.4 11 (5.1 70)		
/Volkswagen/Polo TSI	Test Time: 2024-01-09 14:41:36	Report ID: MAXIA20240109144136

## **Technician Notes**

2016222756

Customer name: _	
Technician: _	
Date: _	

Note:Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.



MaxiSys MS906 BT Page 3