



Shop Name: --
Tel: --
Email: --
Address: --

Report ID: MAXIA20250714100814
Test Time: 2025-07-14 10:08:14
Technician: Travino

Toyota VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Toyota/Hilux/--
VIN: AHTCW8CB501963545

Odometer Reading: 76328km
License Plate: FTM730L

Customer Information

Name: MFC Dekra Nedbank Auction House







Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT
Version: V11.30

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned(5)

System	Status/DTC
Engine and ECT	 0
ABS/VSC/TRC	 1
SRS airbag	 2
Combination meter	 0
Cruise control	  0

DTC (3)

ABS/VSC/TRC (1 DTC)

DTC	Description	Status
C1241	Low or high power supply voltage	Current

SRS airbag (2 DTCs)

DTC	Description	Status
B1803	Driver squib circuit short to battery (+)	Current
B1803	Driver squib circuit short to battery (+)	History

Technician Notes

2016945342

Customer name: _____

Technician: _____

Date: _____

Note:Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.

