

Toyota VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Toyota/Fortuner/--
VIN: AHTJA3GS100238095

Odometer Reading: 116426km
License Plate: KHF539MP

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V11.80

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (13)

System	Status/DTC
Engine and ECT	 1
ABS/VSC/TRC	 1
SRS airbag	 0
Combination meter	 1
Back door	 2
Air conditioner	 0
Headlamp auto leveling	  0
Entry&Start	 0
Power source control	 1
Starting control	 0
Navigation system	 3
4WD	 1
Radar cruise 1	  0

DTC (10)

Engine and ECT (1 DTC)

DTC	Description	Status
P1605	Rough idling	History

ABS/VSC/TRC (1 DTC)

DTC	Description	Status
C1241	Low or high power supply voltage	History

Combination meter (1 DTC)

DTC	Description	Status
-----	-------------	--------

B150A	Lost communication with HMI-LAN	History
-------	---------------------------------	---------

Back door (2 DTCs)

DTC	Description	Status
B2226	Power back door(PBD) unit pulse sensor (left) circuit	History
B2228	Power back door(PBD) unit motor (left) circuit	History

Power source control (1 DTC)

DTC	Description	Status
B2285	Steering lock position signal (cable-information does not match to LIN information)	History

Navigation system (3 DTCs)

DTC	Description	Status
B1324	Lost communication with meter	History
C1622	Rear camera disconnected	History
U0073	Sending fault (navigation to APGS)	History

4WD (1 DTC)

DTC	Description	Status
P17CC	Rear differential lock control switch stuck in on position	History

Technician Notes
2017304902

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.