



Shop Name: Dekra MFC Auction House
Tel: --
Email: --
Address: MFC AUCTION HOUSE
M57 PRETORIA ROAD
KEMPTON PARK

Report ID: MAXIA20250423093841
Test Time: 2025-04-23 09:38:41
Technician: Travino

Toyota VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Toyota/Hilux/--
VIN: AHTKB8CBX02852202

Odometer Reading: 411372km
License Plate: JZ46MFGP

Customer Information

Name: Dekra MFC AUCTION HOUSE







Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT
Version: V11.20

Serial Number: VB8GJCC01514
Repair Order Number: --

System Scanned(6)

System	Status/DTC
Engine and ECT	 4
ABS/VSC/TRC	 1
SRS airbag	 0
Combination meter	 1
4WD	 9
Immobilizer	 0

DTC (15)

Engine and ECT (4 DTCs)

DTC	Description	Status
P1605	Rough idling	Current
P1608	Engine lack of power	Current
P1605	Rough idling	History
P1608	Engine lack of power	History

ABS/VSC/TRC (1 DTC)

DTC	Description	Status
C1404	Fault in rear speed sensor left circuit	Current

Combination meter (1 DTC)

DTC	Description	Status
U0129	Lost communication with brake system control module	History

4WD (9 DTCs)

DTC	Description	Status
-----	-------------	--------



P17A4	Automatic disconnecting differential motor limit switch circuit	History
P17A8	Transfer shift motor control circuit open	History
P17A9	Transfer shift motor control circuit low	History
P17AA	Transfer shift motor control circuit high	History
P17AC	Transfer shift motor limit switch circuit	History
P17C8	Front differential oil temperature sensor circuit high	History
P17CC	Rear differential lock control switch stuck in on position	History
P279E	4WD range signal circuit range/performance	History
U0416	Invalid data received from vehicle dynamic control (VDC) module	History

Technician Notes
2016851296

Customer name: _____

Technician: _____

Date: _____

Note:Please save a copy of this report for your records.