

Toyota VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Toyota/Hiace/Ventury/--
VIN: AHTSS22P307153989

Odometer Reading: 203753
License Plate: KXW151MP

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V11.80

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (5)

System	Status/DTC
Engine and ECT	 5
ABS/VSC/TRC	 10
SRS airbag	 3
Combination meter	 0
Immobilizer	 0

DTC (18)

Engine and ECT (5 DTCs)

DTC	Description	Status
P0335	Crankshaft position (CKP) sensor A circuit	Current
P0340	Camshaft position (CMP) sensor circuit	Current
P0335	Crankshaft position (CKP) sensor A circuit	History
P0340	Camshaft position (CMP) sensor circuit	History
P2138	Throttle/pedal position sensor/switch D/E voltage correlation	History

ABS/VSC/TRC (10 DTCs)

DTC	Description	Status
C1201	Engine/EV control system malfunction	History
C1241	Low or high power supply voltage	History
C1290	Zero point of wheel speed sensor (WSS) abnormal	Current
U0126	Lost communication with steering angle sensor (SAS) module	Current
C1290	Zero point of wheel speed sensor (WSS) abnormal	History
C1425	Stop switch circuit open	History

C146D	ABS motor relay circuit short	History
U0100	Lost communication with ECM/PCM/EV "A"	History
U0124	Lost communication with lateral acceleration sensor module	History
U0126	Lost communication with steering angle sensor (SAS) module	History

SRS airbag (3 DTCs)

DTC	Description	Status
B1801	Driving side squib circuit open	Current
B1801	Driving side squib circuit open	History
B1806	P squib circuit open	History

Technician Notes
2017305374

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.