

Toyota VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Toyota/Hiace/Ventury/--
VIN: AHTSS22P407146534

Odometer Reading: 253641km
License Plate: NONE plate

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V11.80

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (5)

System	Status/DTC
Engine and ECT	 0
ABS/VSC/TRC	 10
SRS airbag	 2
Combination meter	 3
Immobilizer	 0

DTC (15)

ABS/VSC/TRC (10 DTCs)

DTC	Description	Status
C1241	Low or high power supply voltage	History
C1404	Fault in rear speed sensor left circuit	History
C1416	Left rear speed sensor circuit output	History
C146D	ABS motor relay circuit short	Current
U0073	Control module communication bus off	Current
U0126	Lost communication with steering angle sensor (SAS) module	Current
C146D	ABS motor relay circuit short	History
U0073	Control module communication bus off	History
U0124	Lost communication with lateral acceleration sensor module	History
U0126	Lost communication with steering angle sensor (SAS) module	History

SRS airbag (2 DTCs)

DTC	Description	Status
B1801	Driving side squib circuit open	History

B1806	P squib circuit open	History
-------	----------------------	---------

Combination meter (3 DTCs)

DTC	Description	Status
U0100	Lost communication with ECM/PCM/EV "A"	History
U0129	Lost communication with brake system control module	History
U0151	Lost communication with restraints control module	History

Technician Notes
2017305354

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.