

# Toyota VEHICLE DIAGNOSTIC REPORT

## Vehicle Information

--/Toyota/Hiace/Ventury/--  
VIN: AHTSS22P407148347

Odometer Reading: 85913km  
License Plate: LF26MDGP

## Customer Information

Name: MFC Dekra Nedbank Auction House






Tel: 0861033572

## Device information

Scanner: MaxiSys MS906 BT  
Version: V9.21

Serial Number: VB8GJCC01509  
Repair Order Number: --

## System Scanned( 5 )

System	Status/DTC
Engine and ECT	 1
ABS/VSC/TRC	 3
SRS airbag	 2
Combination meter	 1
Immobilizer	 0

## DTC ( 7 )

### Engine and ECT ( 1 DTC )

DTC	Description	Status
P2138	Throttle/pedal position sensor/switch D/E voltage correlation	History

### ABS/VSC/TRC ( 3 DTCs )

DTC	Description	Status
C1201	Engine/EV control system malfunction	History
C1407	Right rear speed sensor circuit open or short	History
C1425	Stop switch circuit open	History

### SRS airbag ( 2 DTCs )

DTC	Description	Status
B1801	Driving side squib circuit open	History
B1806	P squib circuit open	History

### Combination meter ( 1 DTC )

DTC	Description	Status
U0129	Lost communication with brake system control module	History

## Technician Notes

2016292187

Customer name: \_\_\_\_\_

Technician: \_\_\_\_\_

Date: \_\_\_\_\_

Note: Please save a copy of this report for your records.