

Toyota VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Toyota/Hiace/Ventury/--
 VIN: AHTSS22P407153001

Odometer Reading: 32463km
 License Plate: LK16WGGP

Customer Information

Name: MFC Dekra Nedbank Auction House






Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT
 Version: V9.21

Serial Number: VB8GJCC01509
 Repair Order Number: --

System Scanned(5)

System	Status/DTC
Engine and ECT	 2
ABS/VSC/TRC	 1
SRS airbag	 2
Combination meter	 2
Immobilizer	 0

DTC (7)

Engine and ECT (2 DTCs)

DTC	Description	Status
P2138	Throttle/pedal position sensor/switch D/E voltage correlation	Current
P2138	Throttle/pedal position sensor/switch D/E voltage correlation	History

ABS/VSC/TRC (1 DTC)

DTC	Description	Status
C1201	Engine/EV control system malfunction	History

SRS airbag (2 DTCs)

DTC	Description	Status
B1801	Driving side squib circuit open	History
B1806	P squib circuit open	History

Combination meter (2 DTCs)

DTC	Description	Status
U0129	Lost communication with brake system control module	History

B1508 Turn signal/hazard flasher circuit short

History

Technician Notes

2016293658

Customer name: _____

Technician: _____

Date: _____

Note:Please save a copy of this report for your records.