

Toyota VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Toyota/Hiace/Ventury/--
VIN: AHTSS22P807125380

Odometer Reading: 512760km
License Plate: KF03HPGP

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V11.80

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (5)

System	Status/DTC
Engine and ECT	 0
ABS/VSC/TRC	 7
SRS airbag	 3
Combination meter	 1
Immobilizer	 0

DTC (11)

ABS/VSC/TRC (7 DTCs)

DTC	Description	Status
C0200	Right front speed sensor circuit	Current
C0205	Left front speed sensor circuit	Current
C0278	ABS solenoid relay circuit open	Current
C1235	Foreign object attached on tip of right front speed sensor	Current
C1236	Foreign object attached on tip of left front speed sensor	Current
C1241	Low or high power supply voltage	Current
C1249	Stop lamp switch circuit open	Current

SRS airbag (3 DTCs)

DTC	Description	Status
B1801	Driving side squib circuit open	Current
B1801	Driving side squib circuit open	History
B1806	P squib circuit open	History

Combination meter (1 DTC)

DTC	Description	Status
U0129	Lost communication with brake system control module	History

Technician Notes
2017305272

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.