



Shop Name: Dekra MFC Auction House
Tel: --
Email: --
Address: MFC AUCTION HOUSE
M57 PRETORIA ROAD
KEMPTON PARK

Report ID: MAXIA20250422122342
Test Time: 2025-04-22 12:23:42
Technician: Werner

Toyota VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Toyota/Hiace/Ventury/--
VIN: AHTSS22P807159142

Odometer Reading: 60162km
License Plate: N O N E r eg

Customer Information

Name: Dekra MFC AUCTION HOUSE

Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT
Version: V11.20

Serial Number: VB8GJCC01514
Repair Order Number: --

System Scanned(5)

System	Status/DTC
Engine and ECT	 3
ABS/VSC/TRC	 7
SRS airbag	 5
Combination meter	 0
Immobilizer	 0

DTC (15)

Engine and ECT (3 DTCs)

DTC	Description	Status
P0500	Vehicle speed sensor (VSS)	Current
P0500	Vehicle speed sensor (VSS)	History
P2138	Throttle/pedal position sensor/switch D/E voltage correlation	History

ABS/VSC/TRC (7 DTCs)

DTC	Description	Status
C1201	Engine/EV control system malfunction	History
C1407	Right rear speed sensor circuit open or short	Current
C1408	Left rear speed sensor circuit open or short	Current
C1433	Steering angle sensor (SAS) internal circuit	Current
C1407	Right rear speed sensor circuit open or short	History
C1408	Left rear speed sensor circuit open or short	History
C1433	Steering angle sensor (SAS) internal circuit	History

SRS airbag (5 DTCs)



DTC	Description	Status
B1801	Driving side squib circuit open	Current
B1900	Right pretensioner squib circuit short	Current
B1801	Driving side squib circuit open	History
B1806	P squib circuit open	History
B1900	Right pretensioner squib circuit short	History

Technician Notes

2016850329

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.