

# Hyundai VEHICLE DIAGNOSTIC REPORT

## Vehicle Information

--/Hyundai/Accent(RB)/--  
 VIN: KMHCT41DLJU404664

Odometer Reading: 376606  
 License Plate: HJ83HZGP

## Customer Information

Name: DEKRA AUTOMATIC MFC MFC AUCTION HOUSE








Tel: 0861033572

## Device information

Scanner: MaxiSys MS906 BT  
 Version: V13.50

Serial Number: VB8GJCC01482  
 Repair Order Number: --

## System Scanned( 7 )

| System   | Status/DTC  |
|--|---|
| ENG (Engine)   |  4   |
| ABS/ESP (Anti Lock Brake/Electronic Stability Program) |  0   |
| AB (Airbag)  |  2  |
| IMMO (Immobilizer)                                     |  0 |
| CODE (Transmitter Code Saving)                         |  0 |
| EPS (Motor Driven Power Steering)                      |  0 |
| BCM (Body Control)                                     |  0 |

## DTC ( 6 )

### ENG (Engine) ( 4 DTCs )

| DTC   | Description  | Status  |
|-------|--|---------|
| P0011 | Intake camshaft position (CMP) A timing over-Advanced or system performance (Bank 1) | Pending |
| P0134 | Oxygen sensor circuit no activity detected (Bank 1 sensor 1)                         | Pending |
| P0616 | Starter relay circuit low  | History |
| P2188 | System too rich at idle (Bank 1)   | History |

### AB (Airbag) ( 2 DTCs )

| DTC   | Description   | Status  |
|-------|---|---------|
| B1102 | Battery voltage low                                 | History |
| B1346 | Driver airbag (DAB) resistance too high (1st Stage) | Active  |

## Technician Notes

2016244506

Customer name: \_\_\_\_\_

Technician: \_\_\_\_\_

Date: \_\_\_\_\_

Note: Please save a copy of this report for your records.