

GreatWall VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/GreatWall/Poer/P-Series/Cannon/Ute/Poer Ruman and
Sukan/2019-2022/--

VIN: LGWCBF198NJ631076

Odometer Reading: 113033

License Plate: HKT162L

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT

Version: V11.00

Serial Number: VB8GJCC01509

Repair Order Number: --



System Scanned (16)

System	Status/DTC
ECM (Engine Control Module)-ECM (Engine Control Module) - 4D20M	✓ 0
A/T (Automatic Transmission)	✗ 1
ESP (Electronic Stability Program)	✗ 1
SRS (Supplemental Restraint System)	✓ 0
BCM (Body Control Module)	✓ 0
ICM/IP (Instrument Cluster Module/Instrument Panel)-Yazaki instrument (3.5)	✗ 3
TPMS (Tire Pressure Monitoring System)	✗ 8
A/C (Air Conditioning)	✓ 0
CSA (Combination Switch Assembly) - with Steering Angle Sensor Calibration Function	✗ 2
PEPS (Passive Start System)	✗ 3
SBWM (Shift-By-Wire Module)	✓ 0
HUT (Multimedia Player Assembly)	ADAS ✗ 2
GW (Gateway)	✗ 1
EPS (Electric Power Steering)	✓ 0
ESCL (Electronic Steering Column Lock)	✗ 1
IMMO (Immobilizer)	✗ 3



DTC (25)

A/T (Automatic Transmission) (1 DTC)

DTC	Description	Status
U016487	Lost communication with A/C	History DTC

ESP (Electronic Stability Program) (1 DTC)

DTC	Description	Status
U016487	A/C signal timeout	History DTC

ICM/IP (Instrument Cluster Module/Instrument Pannel)-Yazaki instrument (3.5) (3 DTCs)

DTC	Description	Status
U110116	Corresponding voltage is too low	History DTC
U014087	Lost communication with BCM	History DTC
U012787	Lost communication with TPMS	History DTC

TPMS (Tire Pressure Monitoring System) (8 DTCs)

DTC	Description	Status
C008351	Left front sensor ID not configured	History DTC
C008352	Right front sensor ID not configured	History DTC
C008353	Right rear sensor ID not configured	History DTC
C008354	Left rear sensor ID not configured	History DTC
C008302	Right front sensor lost	History DTC
C007701	Left front tire low pressure warning	History DTC
C007702	Right front tire low pressure warning	History DTC
C007704	Left rear tire low pressure warning	History DTC

CSA (Combination Switch Assembly) - with Steering Angle Sensor Calibration Function (2 DTCs)

DTC	Description	Status
U168287	BCM missing message	History DTC
U100287	Passive Entry Passive Start (PEPS) node lost	History DTC

PEPS (Passive Start System) (3 DTCs)

DTC	Description	Status
U014087	Lost communication with BCM unit	History DTC
U025487	Lost communication with ESCL	History DTC
B182700	Immobilizer system authentication failed	History DTC

HUT (Multimedia Player Assembly) (2 DTCs)

DTC	Description	Status
U015587	Lost communication with instrument panel	History DTC
U014587	CSA Lost Communication	History DTC

GW (Gateway) (1 DTC)

DTC	Description	Status
-----	-------------	--------

U016487	Lost communication with AC (AC-FCP)	History DTC
---------	-------------------------------------	-------------

ESCL (Electronic Steering Column Lock) (1 DTC)

DTC	Description	Status
U100287	Lost communication with Passive Entry Passive Start (PEPS)	History DTC

IMMO (Immobilizer) (3 DTCs)

DTC	Description	Status
U014087	Lost communication with BCM unit	History DTC
U025487	Lost communication with electronic steering column lock	History DTC
B182700	Immobilizer system authentication failed	History DTC

Technician Notes
2017301933

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.