

GreatWall VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/GreatWall/Poer/P-Series/Cannon/Ute/Poer Ruman and
Sucan/2019-2022/--
VIN: LGWDCF194NJ633229

Odometer Reading: 40777

License Plate: LBH295MP

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V11.00

Serial Number: VB8GJCC01509
Repair Order Number: --

 System Scanned (17)

System	Status/DTC
ECM (Engine Control Module)-ECM (Engine Control Module) - 4D20M	 1
A/T (Automatic Transmission)	 1
ESP (Electronic Stability Program)	 2
SRS (Supplemental Restraint System)	 1
BCM (Body Control Module)	 1
ICM/IP (Instrument Cluster Module/Instrument Pannel)-Yazaki instrument (3.5)	 2
TPMS (Tire Pressure Monitoring System)	 7
A/C (Air Conditioning)	 0
CSA (Combination Switch Assembly) - with Steering Angle Sensor Calibration Function	 2
PEPS (Passive Start System)	 5
SBWM (Shift-By-Wire Module)	 1
HUT (Multimedia Player Assembly)	  2
TOD (Toque On Demand) - 4WD	 3
GW (Gateway)	 3
EPS (Electric Power Steering)	 0
ESCL (Electronic Steering Column Lock)	 1
IMMO (Immobilizer)	 5

 DTC (37)

ECM (Engine Control Module)-ECM (Engine Control Module) - 4D20M (1 DTC)

DTC	Description	Status
P26E100	External voltage fault	History DTC

A/T (Automatic Transmission) (1 DTC)

DTC	Description	Status
U016487	Lost communication with A/C	History DTC

ESP (Electronic Stability Program) (2 DTCs)

DTC	Description	Status
C010896	Abnormal power-off detected by PBC	History DTC
U016487	A/C signal timeout	History DTC

SRS (Supplemental Restraint System) (1 DTC)

DTC	Description	Status
U110116	Diagnostic voltage too low	History DTC

BCM (Body Control Module) (1 DTC)

DTC	Description	Status
U110116	Supply voltage below the diagnostic required voltage 9V	History DTC

ICM/IP (Instrument Cluster Module/Instrument Pannel)-Yazaki instrument (3.5) (2 DTCs)

DTC	Description	Status
U110116	Corresponding voltage is too low	History DTC
U014087	Lost communication with BCM	History DTC

TPMS (Tire Pressure Monitoring System) (7 DTCs)

DTC	Description	Status
U016487	Lost communication with AC (AC-FCP)	History DTC
C008352	Right front sensor ID not configured	History DTC
C008354	Left rear sensor ID not configured	History DTC
C007701	Left front tire low pressure warning	History DTC
C007702	Right front tire low pressure warning	History DTC
C007703	Right rear tire low pressure warning	History DTC
C007704	Left rear tire low pressure warning	History DTC

CSA (Combination Switch Assembly) - with Steering Angle Sensor Calibration Function (2 DTCs)

DTC	Description	Status
U168287	BCM missing message	History DTC
U100287	Passive Entry Passive Start (PEPS) node lost	History DTC

PEPS (Passive Start System) (5 DTCs)

DTC	Description	Status
U110116	System voltage too low	History DTC

U014087	Lost communication with BCM unit	History DTC
U025487	Lost communication with ESCL	History DTC
B182400	Immobilizer system initialization error	History DTC
B182700	Immobilizer system authentication failed	History DTC

SBWM (Shift-By-Wire Module) (1 DTC)

DTC	Description	Status
U110116	Corresponding voltage is too low	History DTC

HUT (Multimedia Player Assembly) (2 DTCs)

DTC	Description	Status
U015587	Lost communication with instrument panel	History DTC
U014587	CSA Lost Communication	History DTC

TOD (Toque On Demand) - 4WD (3 DTCs)

DTC	Description	Status
U012281	Electronic stability program-ABS signal invalid	History DTC
U016487	Lost communication with A/C	History DTC
U010181	TCU/DCT signal invalid	History DTC

GW (Gateway) (3 DTCs)

DTC	Description	Status
U110116	Communication voltage too low	History DTC
U014087	Lost communication with BCM	History DTC
U016487	Lost communication with AC (AC-FCP)	History DTC

ESCL (Electronic Steering Column Lock) (1 DTC)

DTC	Description	Status
U100287	Lost communication with Passive Entry Passive Start (PEPS)	History DTC

IMMO (Immobilizer) (5 DTCs)

DTC	Description	Status
U110116	Corresponding voltage is too low	History DTC
U014087	Lost communication with BCM unit	History DTC
U025487	Lost communication with electronic steering column lock	History DTC
B182400	Immobilizer system initialization error	History DTC
B182700	Immobilizer system authentication failed	History DTC

Technician Notes

2017298331

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.