Nedbonk MFC **Auction House**A division of **SINEDBANK**

Shop Name: Dekra MFC Auction House

Tel: --Email: --

Email: --

Address: MFC AUCTION HOUSE

M57 PRETORIA ROAD KEMPTON PARK Report ID: MAXIA20250415120007 Test Time: 2025-04-15 12:00:07

Technician: Werner

GreatWall VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/GreatWall/Haval H2/2019 (China 6)/-- Odometer Reading: 99744 VIN: LGWEE4A40KH914356 License Plate: JYF050MP

Customer Information

Name: Dekra MFC AUCTION HOUSE Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT Serial Number: VB8GJCC01514

Version: V11.00 Repair Order Number: --

🔁 System Scanned(11)

System	Status/DTC
ECM (Engine Control Module)	② 0
ESP (Electronic Stability Program)	② 0
SRS (Supplemental Restraint System)	Q 4
BCM (Body Control Module)	Q 4
ICM/IP (Instrument Cluster Module/Instrument Pannel)	② 0
A/C (Air Conditioning) - A/C (Air Conditioning) - Red Logo	② 0
PEPS (Passive Start System)	Q 1
GW (Gateway)-Gateway - Continental	② 0
ESCL (Electronic Steering Column Lock)	Q 8
EPS (Electric Power Steering)-EPS (Electric Power Steering)	Q 3
CMS (CAN Signal Conversion System)	② 0

DTC (20)

SRS (Supplemental Restraint System) (4 DTCs)

` ''		
DTC	Description	Status
B103414	Crash Output of Controller Short to GND or Open	History DTC
U110116	Power supply voltage too low	History DTC
U012287	ABS/ESP communication lost	History DTC
U014687	GW communication lost	History DTC

v.autel.com MaxiSys MS906 BT

B14DA96 B14DB96 B14DC96 B14DD96			Status Current DTC
B14DA96 B14DB96 B14DC96 B14DD96	Left front wheel transmitter los Right front wheel transmitter lost Left rear wheel transmitter lost		Current DTC
B14DB96 B14DC96 B14DD96	Right front wheel transmitter lost		
B14DC96 B14DD96	Left rear wheel transmitter lost	ost	
B14DD96			Current DTC
		Left rear wheel transmitter lost	
DEDO (Deseive O	Right rear wheel transmitter lost		Current DTC
PEPS (Passive S	tart System) (1 DTC)		
DTC	Description		Status
U011100	Lost communication with base station LIN		History DTC
ESCL (Electronic	Steering Column Lock) (8 DTCs)		
DTC	Description		Status
U110016	Voltage too low		History DTC
U000188	CAN bus off		History DTC
U100587	NMLimphome		History DTC
U100287	PEPS lost		History DTC
U150287	Front wheel speed information lost		History DTC
U150387	Rear wheel speed information lost		History DTC
U150187	Engine speed information timeout		History DTC
U014087	Communication with BCM lost		History DTC
EPS (Electric Pov	wer Steering)-EPS (Electric Power S	Steering) (3 DTCs)	
DTC	Description		Status
C100200	Supply voltage below alert valu	ie	History DTC
C100400	Supply voltage below hazard value		History DTC
U010087	ECM lost		History DTC
Technician Not 2016843958	es		
		Customer name:	
		Technician:	
		Date:	

Note:Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.



autel.com MaxiSys MS906 BT Page 2