

Shop Name: Dekra MFC Auction House Tel: --Email: --Address: MFC AUCTION HOUSE M57 PRETORIA ROAD KEMPTON PARK Report ID: MAXIA20250506091851 Test Time: 2025-05-06 09:18:51 Technician: Sbu

GreatWall VEHICLE DIAGNOSTIC REPORT

| Vehicle Information | | |
|---|---|------------|
| /GreatWall/Haval H6/ | Odometer Reading: 82294 | |
| VIN: LGWEF6A52LH908559 | License Plate: FKN173L | |
| Customer Information | | |
| Name: Dekra MFC AUCTION HOUSE | Tel: 0861033572 | |
| Device information | | |
| Scanner: MaxiSys MS906 BT Version: V11.00 | Serial Number: VB8GJCC01514 Repair Order Number: | |
| 🔁 System Scanned(9) | | |
| System | | Status/DTC |
| ECM (Engine Control Module) | | 3 2 |
| A/T (Automatic Transmission)-TCU (Transmission | | |
| Control Unit) - 7DCT-300S & 400S - UAES Electronic | | O |
| Control | | |
| ESP (Electronic Stability Program) | | 3 2 |
| A/C (Air Conditioning) -A/C (Air Conditioning) - MIND | | Q 1 |
| CSA (Combination Switch Assembly) - with Steering | | |
| Angle Sensor Calibration Function | | O |
| EPS (Electric Power Steering)-EPS (Electric Power | | |
| Steering) - Nexteer | | 🕙 1 |
| GW (Gateway)-GW (Gateway) - UAES | | 3 |
| Give (Galeway) - Give (Galeway) - GALS | | V 0 |
| IDCS (Video Domain Controller System) | | S 3 |
| RPAS (Rear Parking Assist System) | ADAS | 8 🔇 |

🔼 DTC (20)

ECM (Engine Control Module) (2 DTCs)

| Description Electronic parking signal data damaged | Status History DTC | | | |
|---|---|--|--|--|
| Description | Status | | | |
| | | | | |
| ESP (Electronic Stability Program) (2 DTCs) | | | | |
| IMM_No Response | History DTC | | | |
| CAN module input voltage too low | History DTC | | | |
| Description | Status | | | |
| | CAN module input voltage too low IMM_No Response | | | |

| /GreatWall/Hava | H6 | Test Time: 2025-05-06 09:18:51 | Report ID: MAXIA20250506091851 | |
|---|--------------------------------------|--------------------------------|--------------------------------|--|
| A/C (Air Condi | tioning) -A/C (Air Conditioning) - I | MIND (1 DTC) | | |
| DTC | Description | | Status | |
| U110116 | Voltage too low | | History DTC | |
| EPS (Electric Power Steering)-EPS (Electric Power Steering) - Nexteer (1 DTC) | | | | |
| DTC | Description | | Status | |
| C100B00 | Please refer to vehicle servi | ce manual. | History DTC | |
| GW (Gateway) | -GW (Gateway) - UAES (3 DTCs) | | | |
| DTC | Description | | Status | |
| U018187 | Please refer to vehicle servi | ce manual. | History DTC | |
| U012687 | Lost communication with st | eering angle sensor | History DTC | |
| U110116 | Corresponding voltage is to | o low | History DTC | |
| IDCS (Video Do | omain Controller System) (3 DTC: | 3) | | |
| DTC | Description | | Status | |
| B211104 | Please refer to vehicle servi | ce manual. | History DTC | |
| U110116 | Voltage too low | | History DTC | |
| B217301 | Please refer to vehicle servi | ce manual. | History DTC | |
| RPAS (Rear Pa | rking Assist System) (8 DTCs) | | | |
| DTC | Description | | Status | |
| U012286 | Electronic stability program | checksum error | History DTC | |
| U014686 | Gateway node invalid/impla | usible | History DTC | |
| B121B14 | Please refer to vehicle servi | ce manual. | History DTC | |
| B121C14 | Please refer to vehicle servi | ce manual. | History DTC | |
| B121A14 | Please refer to vehicle servi | ce manual. | History DTC | |
| B121E14 | Please refer to vehicle servi | ce manual. | History DTC | |
| B121D14 | Please refer to vehicle servi | ce manual. | History DTC | |
| B121F14 | Please refer to vehicle servi | ce manual. | History DTC | |

Technician Notes 2016866029

Customer name:

Technician:

Date:

Note:Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.