

Chery VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Chery/Tiggo series/Tiggo 7 Plus/Tiggo 7 Pro/Tiggo 7 Pro
Max/Ebro S700/DR 6.0 T-GDI/Xcite X-Cross 7/--
VIN: LVVDB21B2RD767285

Odometer Reading: 34272
License Plate: LCJ399NW

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V14.60

Serial Number: VB8GJCC01509
Repair Order Number: --

 System Scanned (22)

System		Status/DTC
ECM (Engine system)-Engine Management System (EMS) - China VI - 1.5 T		✓ 0
AT (Automatic Transmission System)-CVT18/25 (transmission control system (continuously variable transmission))		✓ 0
ABS (Anti-Lock brake system)		✓ 0
IC (Instrument Cluster)		✓ 0
Tire Pressure Monitoring System (TPMS)		✗ 13
BCM (Body control system)-BCM		✗ 13
AC (Automatic air conditioning system)		✓ 0
PEPS (Keyless start system)		✗ 1
EPS (Electronic Power Steering System)		✓ 0
IMMO (Immobilizer)		✗ 1
SAS (Steering Angle System)		✓ 0
RADAR (radar system)	ADAS	✓ 0
AVM (Panorama Control System)-AVM (Panorama Control System)	ADAS	✗ 1
FCM (Front Camera Module)	ADAS	✗ 1
FRM (Front Radar Module)	ADAS	✗ 1
CGW (Central Gateway)		✓ 0
EGS (Electronic Gear Shifter)		✓ 0

AIPM/CCP(Automotive Integrated Power Module)	✓ 0
PLG (Power Lift Gate)	✗ 1
CWC (wireless charging module)	✓ 0
IHU (Infotainment Head Unit)	✗ 1
BSD (Blind Spot Detection)	 ✗ 7

DTC (40)

Tire Pressure Monitoring System (TPMS) (13 DTCs)

DTC	Description	Status
U010187	CAN Communication Error - Lost Communication with Transmission Control Unit	History/Message missing
C140629	Right rear tire pressure sensor signal failure	History/Signal failure
B100016	Please refer to vehicle service manual.	History/Circuit voltage below lower limit
B100113	Please refer to vehicle service manual.	History
B100213	Please refer to vehicle service manual.	History
B103513	Please refer to vehicle service manual.	History
B102116	Please refer to vehicle service manual.	History/Circuit voltage below lower limit
B102371	Please refer to vehicle service manual.	History
B102671	Please refer to vehicle service manual.	History
B103471	Please refer to vehicle service manual.	History
B102871	Please refer to vehicle service manual.	History
B102F86	FR window motor position signal error	History
B103186	Right rear window motor position signal error	History

BCM (Body control system)-BCM (13 DTCs)

DTC	Description	Status
U010187	Lost communication with transmission controller	Information lost/History
C140629	Right rear tire pressure sensor (signal failure)	History
B100016	Battery voltage circuit voltage too low	Circuit voltage below lower limit/History
B100113	Left turn lamp control circuit external load open	Circuit open/History
B100213	Right turn lamp control circuit external load open	Circuit open/History
B103513	Brake lamp control circuit external load circuit open	Circuit open/History

B102116	Anti-pinch module battery voltage too low	Circuit voltage below lower limit/History
B102371	Right front window button sticking	Relay burnout/History
B102671	Right front window button sticking	Relay burnout/History
B103471	Left rear window button sticking	Relay burnout/History
B102871	Right rear window button sticking	Relay burnout/History
B102F86	Right front window motor position signal error	Signal Invalid/History
B103186	Right rear window motor position signal error	Signal Invalid/History

PEPS (Keyless start system) (1 DTC)

DTC	Description	Status
B152F16	Battery voltage low	History

IMMO (Immobilizer) (1 DTC)

DTC	Description	Status
B152F16	Battery voltage too low	History

AVM (Panorama Control System)-AVM (Panorama Control System) (1 DTC)

DTC	Description	Status
B181400	Radio antenna abnormal	History

FCM (Front Camera Module) (1 DTC)

DTC	Description	Status
C190749	Electrical error: temporary electronic permanent fault	History

FRM (Front Radar Module) (1 DTC)

DTC	Description	Status
C194004	Radar function unavailable	History

PLG (Power Lift Gate) (1 DTC)

DTC	Description	Status
B1A9A1C	Left bar motor output fault	Historic Fault Code

IHU (Infotainment Head Unit) (1 DTC)

DTC	Description	Status
B181400	Radio antenna abnormal	History

BSD (Blind Spot Detection) (7 DTCs)

DTC	Description	Status
U010187	Lost communication with Transmission Control Module (TCM)	History
B1A4015	Right LED circuit open or short to power	History
B1A4115	Left LED circuit open or short to power	History

B1A4915	Right Door Opening Warning (DOW) circuit open or short to power	History
B1A4A15	Left Door Opening Warning (DOW) circuit open or short to power	History
B1A4416	Circuit power voltage too low	History
B1A4787	Lost communication with auxiliary radar	History

Technician Notes
2017302439

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.