

Shop Name: --Tel: --Email: --Address: -- Report ID: MAXIA20250721153319 Test Time: 2025-07-21 15:33:19

Technician: Andrick

## Mahindra VEHICLE DIAGNOSTIC REPORT

#### **Vehicle Information**

--/Mahindra/Tuv3oo/--VIN: MA1NA2WEXL6080562

Odometer Reading: 103276 License Plate: KW92SHGP

**Customer Information** 

Name: MFC Dekra Nedbank Auction House

Tel: 0861033572

**Device information** 

Scanner: MaxiSys MS906 BT

Serial Number: VB8GJCC01509

Version: V2.71 Repair Order Number: --

### System Scanned(8)

System	Status/DTC
Engine management system	<b>Q</b> 8
Anti-Lock braking system	<b>Q</b> 1
Supplementary restraint system	<b>Q</b> 1
Instrument cluster	<b>Q</b> 9
Mahindra body function module	<b>Q</b> 3
Reverse park assist system	<b>Q</b> 2
Infotainment system	<b>Q</b> 1
Immobiliser	<b>Q</b> 1

## **DTC (26)**

#### Engine management system (8 DTCs)

DTC	Description	Status
U170100	LIN error	Current
P056200	Signal range check for battery sensor signal below minimum limit	Healed
U041600	Plausibility error for increasing torque request (ESC)	Healed
P010000	Battery voltage error of HFM sensor	Healed
P1AE400	Start- stop lamp switch open load error	Healed
P183200	Immobilizer authentication error	Healed
P183F00	Immobilizer not present in vehicle	Healed
P068A00	Main relay early opening error	Healed

AUTEL www.autel.com

DTC

Anti-Lock braking system (1 DTC)

Description

MaxiSys MS906 BT

**Status** 

/Mahindra/Tuv3oo	Test Time: 2025-07-21 15:33:19	Report ID: MAXIA20250721153319
U300616	Under voltage error	Other
Supplementary	restraint system (1 DTC)	
DTC	Description	Status
B142A16	Battery voltage low	Other
Instrument clus	eter ( 9 DTCs )	
DTC	Description	Status
U170100	LIN error	Current
P056200	Signal range check for battery sensor signal below minimum limit	Healed
U041600	Plausibility error for increasing torque request (ESC)	Healed
P170F00	Starter relay open load	
P010000	Battery voltage error of HFM sensor	Healed
P1AE400	Please refer to vehicle service manual.	Healed
P183200	Please refer to vehicle service manual.	Healed
P183F00	Please refer to vehicle service manual.	Healed
P068A00	Main relay early opening error	Healed
Mahindra body	function module (3 DTCs)	
DTC	Description	Status
U250000	Low voltage CAN TX Stopped	Others
B110016	Power(Battery) under voltage	Others
B110816	RKE low battery	Current
Reverse park as	ssist system ( 2 DTCs )	
DTC	Description	Status
B100116	RPAS ECU supply voltage lower limit exceeded	Healed
B100216	RPAS sensor supply lower limit exceeded	Healed
Infotainment sy	rstem (1 DTC)	
DTC	Description	Status
B100516	IS undervoltage(Below 8V)	Healed
Immobiliser ( 1	DTC)	
DTC	Description	Status

Other

Page 2

# **Technician Notes** 2016953417

MBFM node absent

U110400

AUTEL www.autel.com MaxiSys MS906 BT

/Mahindra/Tuv3oo Test Time: 2025-07-21 15:33:19 Report ID: MAXIA20250721153319

Customer name:	
Technician: _	
Date:	

Note:Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.



MaxiSys MS906 BT Page 3