

Mahindra VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Mahindra/Kuv100/--

VIN: MA1VC2RBCK6A84046

Odometer Reading: 212568

License Plate: KLZ590NW

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT

Serial Number: VB8GJCC01509

Version: V3.10

Repair Order Number: --



System Scanned (8)

System	Status/DTC
Engine management system	11
Anti-Lock braking system	5
Supplementary restraint system	4
Instrument cluster	4
Electronic power steering	0
Mahindra body function module	7
Infotainment system	3
Immobiliser	8



DTC (42)

Engine management system (11 DTCs)

DTC	Description	Status
P056217	Signal range check for battery sensor signal below minimum limit	Healed
P056216	Signal range check for ignition key input below minimum limit	Healed
P33A000	Primary EMS-ICU1 authentication: Immobilized condition/Immobilizer authentication failed	Healed
P33A600	Primary EMS-ICU1 authentication: signature1 using page_1 failed	Other
P33AB00	Primary EMS-ICU1 authentication: signature 1 mismatch	Healed
P164100	EMS Software reset error	Healed
P33AD00	Primary EMS-ICU1 authentication: IMMTRG timeout	Healed
P33AE00	Primary EMS-ICU1 authentication: invalid trigger error	Healed

P030300	Cylinder 3 misfire detected	Other
U201600	ABS request torque increment signal content error	Current
U203400	ESC WHL_FR_SPD wheel speed signal content failure	Current

Anti-Lock braking system (5 DTCs)

DTC	Description	Status
C003412	Front right wheel speed sensor - short to battery	Current
C00341C	Front right wheel speed sensor short to another WSS	Other
U300616	Under voltage error	Other
U130300	VIN mismatch error	Other
C110F09	WSS generic failure	Other

Supplementary restraint system (4 DTCs)

DTC	Description	Status
U110187	Lost comm with EMS	Other
U110587	Lost comm with IC	Other
B142A16	Battery voltage low	Other
B101349	Autoliv ECU internal error	Other

Instrument cluster (4 DTCs)

DTC	Description	Status
U120500	IC bus off	Other
U110300	ABS/ESC node absent	Other
U200400	EMS engine speed signal content error	Healed
B2F3816	IC undervoltage	Healed

Mahindra body function module (7 DTCs)

DTC	Description	Status
B110016	Power(Battery) under voltage	Others
B110001	Battery 3(CDL + frnt wiper)Fault	Others
B110D11	Roof lamp+foot lamp output short to ground	Healed
U110100	EMS node absent	Others
U110300	ABS/ESC node absent	Others
U110800	Infotainment node absent	Others
U200400	EMS engine speed signal content fail	Others

Infotainment system (3 DTCs)

DTC	Description	Status
U110600	SRS node absent	Healed
U200400	EMS engine speed signal content error	Other

B100516	IS undervoltage(Below 8V)	Healed
---------	---------------------------	--------

Immobiliser (8 DTCs)

DTC	Description	Status
B2F4000	Missing transponder/ no response	Other
B2F4200	Wrong TXP	Other
B2F4500	Authentication failed/time out	Other
B2F4400	No ECM challenge	Other
U110400	MBFM node absent	Other
U110500	IC node absent	Other
U100400	MBFM message time out error	Other
U121700	IMMO bus off error	Other

Technician Notes
2017303943

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.