

Hyundai VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Hyundai/Grand i10/Xcent (BA)/--
VIN: MALA851CLHM546367

Odometer Reading: 226294
License Plate: FCZ629L

Customer Information

Name: MFC Dekra Nedbank Auction House










Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT
Version: V13.50

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned(9)

System	Status/DTC
ENG (Engine)	 0
ABS/ESP (Anti Lock Brake/Electronic Stability Program)	 2
AB (Airbag)	 2
CLU (Cluster Module)	 0
IMMO (Immobilizer)	 0
CODE (Transmitter Code Saving)	 0
EPS (Motor Driven Power Steering)	 0
BCM (Body Control)	 0
SJB (Smart Junction Block)	 6

DTC (10)

ABS/ESP (Anti Lock Brake/Electronic Stability Program) (2 DTCs)

DTC	Description	Status
C1102	Battery voltage low	Active
C1203	Right front vehicle speed sensor (VSS) circuit open or short	Active

AB (Airbag) (2 DTCs)

DTC	Description	Status
B1102:00	Battery voltage low	History
B1361:00	Front driver pretensioner resistance too high	Active

SJB (Smart Junction Block) (6 DTCs)

DTC	Description	Status
B2514:00	Right external tail lamp circuit short to ground	History
B2518:00	Left cornering lamp circuit short to ground	History
B2519:00	Right cornering lamp circuit short to ground	History
B2520:00	Right front turn signal lamp circuit open	History
B2521:00	Right rear turn signal lamp circuit open	History
B2524:00	Right front turn signal lamp circuit short to ground	History

Technician Notes

2016294850

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.