

Hyundai VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Hyundai/i20(BI3)/--
VIN: MALBG512LNM139533

Odometer Reading: 85489KM
License Plate: MH60SSGP

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V14.10

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (13)

System	Status/DTC
ENG (Engine)	 4
ABS/ESP (Anti Lock Brake/Electronic Stability Program)	 0
AB (Airbag)	 0
CLU (Cluster Module)	 0
IBU-TPMS (Integrated Body Control Unit-Tire Pressure Monitoring System)	 0
CODE (Transmitter Code Saving)	 0
EPS (Motor Driven Power Steering)	 0
AVN (Audio Video Navigation)	  0
IBU-BCM (Integrated Body Control Unit-Body Control Module)	 0
IBU-SMK (Integrated Body Control Unit-Smart Key Unit)	 0
IBU-IMMO (Integrated Body Control Unit-Immobilizer)	 0
ICU (Integrated Central Control Unit)	 0
RVM (Rear View Monitor)	  0

DTC (4)

ENG (Engine) (4 DTCs)

DTC	Description	Status
P0132:00	Oxygen sensor circuit voltage high (Bank 1 sensor 1)	History
P0402:00	EGR A Flow Excessive Detected	History

P2237:00	Oxygen sensor pumping current circuit/Open (Bank 1 sensor 1)	History
P2251:00	Oxygen sensor reference ground circuit/Open (Bank 1 sensor 1)	Active

Technician Notes
2017302500

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.