

Suzuki VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Suzuki/Swift/--
VIN: MBHZCDESR00180651

Odometer Reading: 59535
License Plate: MC59ZVGP

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V4.91

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (7)

System	Status/DTC
ECM/PCM(Engine/powertrain)	 0
ABS/ESP(Anti-lock Braking System / Electronic Stability Program)	 4
SRS(Airbag)	 1
IPC/MA(Instrument Panel Cluster (IPC)/meter/M&A)	 0
CGW(Central gateway control module)	 0
EPS(Power steering)	 0
BCM(Body Control Module)	 0

DTC (5)

ABS/ESP(Anti-lock Braking System / Electronic Stability Program) (4 DTCs)

DTC	Description	Status
U0100-87	Lost communication with ECM	History
C114A-29	Clutch Pedal Position (CPP) 2 switch system fault	History
C1157-1C	Power supply voltage abnormal	History
C1161-07	Pump motor circuit	History

SRS(Airbag) (1 DTC)

DTC	Description	Status
B1004-18	Power source voltage too low	History

Technician Notes
2017296016

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.